## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

May 16, 2017

Responsible Party 1: Resonponsible Pa		esonponsible Party 2:
Gervais Steve	Alexandra Rapaport	
44 Park Ave	478 Central Park West #7A	
South Portland, ME 04106	New York, NY 10025	
Location	CBL	Inspection Date
61 WILSON ST	003 M008001	4/18/2017
61 WILSON ST Inspector	003 M008001 Inspection Type	4/18/2017 <b>Status</b>

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 6/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 80- ANNEX D.4 1-HOUR FIRE DOORS ASSEMBLIES REQ; Listings are provided for floor fire door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have been tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 square feet of floor or ceiling.  Fire doors are required for each basement door and both doors to the second floor apartments.	8/01/2017
NFPA 10- 7.1.1 FIRE EXTINGUISHERS NEED ANNUAL SERVICE; The owner or designated agent or occupant of a property in which fire extinguishers are located shall be responsible for inspection, maintenance, and recharging.  There are 2 extinguishers in the basement. They are required to be inspected and serviced annually	
NFPA 101- 9.6.10.1.1 SMOKE DETECTOR REQUIRED; Where required by another section of this code, single-station and multiple-station smoke alarms shall be inaccordance with NFPA 72, National Fire Alarm Code, shall be provided in all occupiable areas in environments that are suitable for proper smoke detector operation.  There are detectors in the stairwells to the second floor on the middle landing attached to the baseboard trim. They need to be relocated to a proper height for proper installation/operation.	7/01/2017

Violation		Proposed Date of Completion
	OR NEEDS REPAIR; Any vertical opening shall be required	
in accordance with section 8.6.	the subflooring that exposes the 1st floor bathroom shower	
	sed with approved fire rated materials	
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU R	E-INSPECTION OF COMPLETED VIOLATION(S)	//
	to reject or modify any proposed plan of action, and may all capacity to complete the proposed plan. Please contact ION	-
•	as listed within the timeframes provided. If I require addit the Fire Prevention Bureau <u>prior to the deadline</u> to requ discretion to grant or deny.	- ·
•	my responsibility to schedule a reinspection of my proper My failure to schedule a reinspection shall be deemed an died.	•
	reement, I understand that I am liable for penalties pursue $\S\S$ 1-15 and 10-25, and 30-A M.R.S. $\S$ 4452 and may be s	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	