

Bill Betzner

MS-9200

Addressable Fire Alarm Control Panel

PRELIMINARY CATALOG SHEET

GENERAL

The MS-9200 is a compact, cost effective, addressable fire alarm control panel with a capacity of 198 Fire-Lite Series 300 devices. A single SLC loop supports up to 99 smoke or heat detectors and 99 control or monitor modules. The panel uses the latest in surface-mount technology, and is designed for ease of installation and programming. It features the latest in fire protection technology, including: maintenance alert and automatic detector test.

FEATURES

- 198 addressable device capacity (99 detectors and 99 monitor or control modules), Style 4, 6, or 7.
- 2 programmable Internal Notification Appliance (bell, signal) Circuits, Code Y or Z (Class B or A).
- Alarm, trouble and supervisory relays, standard.
- Maintenance alert warns when smoke detector dust accumulation is excessive.
- Optional plug-in Digital Alarm Communicator.
- Remote serial annunciators operate over high speed EIA-485 port.
- Optional printer interface.
- 3.0 A Notification Appliance (bell, signal) power, expandable to 6.0 A.
- 40 character LCD display with back-lighting.
- Custom English labels per point may be manually entered or selected from an internal library file.
- Real time clock/calendar.
- History file with 500 event capacity.
- Waterflow or supervisory selection per monitor point.
- System alarm verification, smoke only.
- Walk Test reports 2 devices set to same address.
- Presignal delay option per NFPA 72.
- Silence Inhibit and Auto Silence timer options.
- March Time/Temporal/California code for non-silenceable bell circuit.
- Field-programmable on panel, with user-defined passwords, plus an Autoprogram feature.
- Battery charger for up to 60 hours of standby power.
- Remote Acknowledge/Silence/Reset/Drill via M300 modules.
- Optional monitor module supports two-wire smoke detectors.



The MS-9200
15.0" H x 14.5" W x 3.0" D

- Rapid poll algorithm for manual stations. Responds in less than 2 seconds.
- Operates with untwisted, unshielded wire (up to 1,000 feet) for retrofit applications (U. S. Patent 5,210,523).
- New 300 Series addressable devices feature decimal address selection. Address of each device can be easily set in the field by use of a screwdriver. Smoke detectors also feature a plug-in wiring connector.




12 Clintonville Road
Northford, CT 06472
Phone: (203) 484-7161
FAX: (203) 484-7118

ISO-9001
Engineering and Manufacturing
Quality System Certified to
International Standard ISO-9001



DF-51275
Page 1 of 4
August 12, 1993

SYSTEM PERIPHERALS



ADDRESSABLE DEVICES

- SD300** Addressable photoelectric smoke detector. Includes mounting plate and plug-in wiring terminal block.
- SD300T** Same as SD300, plus a 135° F. thermostat heat detector.
- CP300** Addressable ionization smoke detector.
- BG-10LX** Addressable manual station based on the popular Fire-Lite BG-10 dual-action station. Made of LEXAN®.
- M300** Addressable monitor module for one zone of dry contact initiating devices. Mounts in standard 4-inch box. Includes plastic cover plate and end-of-line resistor. Features polling/ alarm LED and decimal address switches. May be configured for either Style B (Class B) or Style D (Class A).
- M301** Miniature version of M300. Excludes LED and Style D option. Connects with wire pigtailed.
- M302** Similar to M300, but may monitor up to 20 conventional 2-wire detectors. Requires external 24 V power. (Consult factory for compatible smoke detectors & availability).
- C300** Addressable control module for one Style Y zone of supervised polarized Notification Appliances, or may be configured as a dry contact (Form C) relay. Mounts in standard 4-inch box. Features polling LED and decimal address switches. Notification Appliance Circuit option requires external 24 VDC power. (Consult factory for compatible Notification Appliances).
- I300** This module isolates the SLC loop from short circuit conditions.

AFM ANNUNCIATORS

AFM-16ATX/AEM-16ATF

Serial remote annunciator modules may be located up to 6,000 feet from the panel. The AFM-16ATX displays alarm and trouble for 16 points or zones. Expandable to 64 points using up to three AEM-16ATF's. May also perform remote silence and reset. The first four switches from one annunciator may be used to remotely acknowledge, silence, reset, or to perform a drill.

AFM-32AX/AEM-32AF

Alarm-only indication by zone, with 32 alarm LEDs per module. AFM-32AX may support one AEM-32AF for a maximum of 64 zones.

AFM-16AF

Alarm indication only. 16 alarm LEDs, common trouble LED. Mounts to standard 4 gang box.

ABS-1F & ABS-2F


Surface mount annunciator boxes accept one or two annunciator modules.

ABF-1F, ABF-2F, & ABF-4F

Flush mount boxes accept 1, 2, or 4 modules.

AKS-1F

Annunciator key switch kit for use with AFM-16AT when used with ABF boxes.



Keypad and 40 Character LCD Display (with back lighting feature)

MAINTENANCE ALERT

The MS-9200 continually monitors each smoke detector and responds to a reading of 80% of the detectors alarm threshold. If the detector continually reports an 80% threshold reading (8/10 of what is required to be an alarm) for 24 hours a trouble condition is created. This reduces the risk of false alarms due to dust and dirt by creating a trouble condition and not an alarm.

AUTOMATIC TEST OPERATION

The MS-9200 performs an automatic test of each detector every 2 hours. Failure to meet the test limits causes an **AUTO TEST FAIL** trouble type. System Reset clears this trouble.

FIELD PROGRAMMING FEATURES

Off-Line Programming	Create entire program in your office using a DOS based PC computer (order programming kit PK-9200 separately). Upload/Download system programming to the MS-9200 in less than one minute.
Auto-Programming	Command the MS-9200 to program itself (takes less than 30 seconds). In the Auto-Program mode, the MS-9200 scans for all possible devices at all addresses, stores the device types, and addresses found, and then loads default values for all options (General Alarm). It also checks for two or more devices set to the same address.
On-Line Edit	While still providing fire protection, the MS-9200 may be programmed from the front panel. Simple menu trees displayed on the LCD allow the trained user to perform all functions without referring back to the programming manual.
English Label Library	Quickly select labels from a standard library "FLR 3 HALLWAY", or enter them in letter-by-letter. Use recall function to repeat previously used label.
Program Check	Automatically catch common errors, such as relays not linked to any zone or point.

SPECIFICATIONS

- Primary input power: 120 VAC, 50/60 Hz, 2.3 Amps.
- Total output 24 V power: 3.6 A (expandable to 6.0).
- Standard Notification Circuits: 2 (Style Y or Z).
- Expansion Notification Circuits: up to 99 (using C300 module)
- Notification Appliance Power: 3.0 A (expandable to 6.0 A with XRM-24).
- Four-wire detector power: 300 mA.
- Non-resettable regulated power: 300 mA.
- Non-regulated power: 2.5 Amps Maximum
- Battery charger range: 7 AH - 17 AH (BB-17F battery cabinet for 12 - 17 AH batteries).
- Remote charger (panel charger disabled): 25-55 AH (use R45-24).
- Charge float rate: 27.6 V.
- Charger current limited to 0.8 A.
- Control panel Alarm, Trouble, Supervisory Relay contact rating: 2.0 A @ 30 VDC.

SYSTEM CAPACITY:

- Total programmable input/output points 198
- Addressable Detectors 99
- Addressable monitor or control modules 99
- Programmable NAC (bell) circuits in panel 2*
- Programmable software zones 56
- AFM annunciators per system 4

NOTE: * NAC circuits are expandable using C300 control module.

CONTROLS AND INDICATORS

LED INDICATORS

1. AC POWER (green).
2. FIRE ALARM (red).
3. SUPERVISORY (yellow).
4. ALARM SILENCE (yellow).
5. SYSTEM TROUBLE (yellow).

MEMBRANE SWITCH CONTROLS

1. ACKNOWLEDGE/STEP
2. ALARM SILENCE
3. DRILL
4. SYSTEM RESET (lamp test)
- 5 - 16. 12 key pad with full alphabet
- 17 - 20. 4 cursor keys
21. ENTER

LCD DISPLAY

40 characters (2 X 20) with long-life LCD display, back-lit.

COMPATIBLE ADDRESSABLE DEVICES

MODEL	DESCRIPTION
CP300	Ionization Smoke Detector.
SD300	Photoelectric Smoke Detector.
SD300T	Photoelectric with 135° F. thermal element.
M300	Monitor Module.
M301	Miniature Monitor Module.
M302	2-Wire Detector Monitor Module.
C300	Control Module.
BG-10LX	Manual Fire Alarm Station, Addressable.

I300

Isolator Module

EIA-232 PORT

MODEL	DESCRIPTION
PIM-24	Printer/PC Interface Module.

COMPATIBLE DEVICES, EIA-485 PORT

MODEL	DESCRIPTION
AFM-16ATX	Annunciator Fixed Module, 16 Alarm LEDs, 16 Trouble LEDs, and 16 Switches. Accepts up to 3 AEM-16ATF expanders.
AEM-16ATF	Annunciator Expander Module, 16 Alarm LEDs, 16 Trouble LEDs.
AFM-32AX	Annunciator Fixed Module, 32 Alarm LEDs, Common Trouble LED.
AEM-32AF	Annunciator Expander Module, 32 Alarm LEDs.
AFM-16AF	Annunciator Fixed Module, 16 Alarm LEDs, Common Trouble LEDs. Mounts to four gang box.

PRODUCT LINE INFORMATION

MODEL	DESCRIPTION
MS-9200	Addressable Fire Panel. Includes display, single printed circuit board, and cabinet.
ZDM-16F	16 Zone LED Annunciator Option Module.
RTM-8F	Plug-in Relay Transmitter Option Module. Provides 8 Form-C relays, plus municipal box & remote station connections.
DP-9200	Full length internal dead front panel (required for Canadian applications).
UDACT-485	Digital Alarm Communicator/Transmitter (Availability to be announced).
XRM-24	120 VAC, 100 VA Transformer. Expands systems power supply. Expands Notification Appliance power from 2.0 amps to 5.0 amps.
PIM-24	Printer and PC Interface Module required for PC programming or to connect a printer.
PK-9200	Programming Kit for DOS based PC computer.
PS-1270	Battery, 12 volt, 7.0 AH, (two required).
PS-12120	Battery, 12 volt, 12.0 AH, (two required).
PS-12170	Battery, 12 volt, 17.0 AH, (two required).
BB-17F	Battery box, required to mount PS-12120 or PS-12170.
R45-24	Remote charger and battery cabinet. Allows charging 25 to 55 AH batteries.
PS-12250	Battery, 12 volt, 25 AH, (two required).
PS-12550	Battery, 12 volt, 55 AH, (two required).

Note: The following modules are in various stages of design and UL-Listing. Please contact Fire-Lite for availability information.

- SD300T
- M302
- I300
- UDACT-485


We try to keep our product information up-to-date and accurate. We cannot cover specific applications or anticipate all requirements. All specifications are subject to change without notice. For more information, contact FIRE-LITE®

DF-51276

VOICE EVACUATION ALARM

SERIES AU-360

MODULAR
TONE AND PAGING AMPLIFIER
SYSTEM



PATENTS ISSUED AND PENDING



AUDIOSONE INC.

HIGH TECHNOLOGY SIGNALING DEVICES

335 Benton Street
STRATFORD, CT 06497
(203) 377-4475
FAX: (203) 377-3374

OPERATION

SUPERVISED VOICE EVACUATION ALARM INTERFACE,
PROVIDES ALARM SIGNAL AND VOICE OVERRIDE
WHEN CONNECTED TO A CONVENTIONAL 24VDC FIRE
ALARM PANEL.
SPEAKER LINE, SIGNAL GENERATOR, AND AMPLIFIER
ARE CONTINUOUSLY SUPERVISED WITH TROUBLE
CONDITIONS AUTOMATICALLY INDICATED BY THE FIRE
ALARM PANEL.

FEATURES

- PENETRATING SLOW-WHOOP ALARM SIGNAL—
MORE EFFECTIVE THAN BELLS OR HORNS.
- CRYSTAL-CLEAR, HIGH-INTELLIGIBILITY VOICE
OVERRIDE. MICROPHONE CAN BE USED WITH
OR WITHOUT ALARM CONDITION.
- USE WITH CONVENTIONAL 24V FIRE ALARM
CONTROL PANELS. SIMPLE 6-WIRE HOOKUP.
- FULLY SUPERVISED AND UL LISTED.
- BATTERY BACKUP FROM FIRE ALARM PANEL.
- BATTERY SAVER CIRCUIT REDUCES CURRENT
TO 0.006 AMPS STANDBY ON BATTERIES.
- USES LOW-COST AU-350 SERIES SPEAKERS—
NO EXPENSIVE SPEAKER/AMPS NECESSARY.
- LOW-VOLTAGE SPEAKER LINE, RUN UP TO 3000
FT. WITH #18 TWISTED PAIR.
- UP TO 40 SPEAKERS PER 20 WATT MODULE.
- ATTRACTIVE BEIGE CABINET, SURFACE OR
SEMI-FLUSH MOUNTING, 16 GAUGE STEEL.
- OPTIONAL REMOTE MICROPHONE STATIONS—
AUTOMATICALLY DISABLED ON ALARM.
- RUGGED AND RELIABLE—CURRENT LIMITING
PROTECTS AMPLIFIER EVEN WHEN SHORTED.
- UPDATES FIRE ALARM SYSTEMS TO
COMPLY WITH LATEST LIFE SAFETY CODES.


- COMPLEX MULTI-ZONE, MULTI-SIGNAL
SYSTEMS CAN BE EASILY CONFIGURED.

- FOR NEW INSTALLATIONS, OR RETROFIT TO
EXISTING FIRE ALARM SYSTEMS, USING SAME
WIRING AND BACKBOXES.

SPECIFICATIONS:


- Power Output: 20 Watts RMS
- Audible Signaling Voltage: 25 VRMS (70 VRMS
optional).
- Microphone: Low impedance dynamic with push-to-
talk switch.
- Supervision: Amplifier, tone generator, power supply,
output transformer, and speaker lines continuously
supervised.
- Power Input: 24-40 VDC, Unfiltered, full wave
rectified from fire alarm panel.
- Current Drain: 1.2 Amp alarm condition, 0.006 Amp
stand-by on battery.
- Alarm Activation: Alarm will sound when bell circuit
activates. Auxiliary terminals supplied for manual or
zone activation.
- Frequency Response: 400—4000 Hz.
- Alarm Tone: Slow Whoop (Optional Horn, Hi-Lo,
March Time, Wail, Yelp, Beep).
- Protection: Overload, Polarity Reverse, Open/Short
Circuit. Automatic current limiting.
- Dimensions: Cabinet—20" x 14" x 4"
Amplifier Module—5" x 9" x 3"

TECHNICAL DATA



- FIRE ALARM PANEL CONNECTIONS:**
- 1. 120 VAC 60 Hz @ 0.03 amp for Battery saver. Connect to same Branch circuit as Fire Alarm Control Panel. Supervised.
 - 2. 24 VDC Power @ 1.2 Amp Max. (0.004 A stand-by on Battery) Supervised.
 - 3. Bell Circuit 0.025 Amp. (Alarm Polarity Shown) Supervised.
 - 4. Speaker Output 20 Watt RMS (see Dia. at right) Supervised.
 - 5. Class "K" Speaker Output: Supervised.

SUPERVISED CLASS A OPERATION




End of Line Resistor: Use ELR supplied by Control Unit Manufacturer for Bell Circuit

AUXILIARY MICROPHONE CONNECTIONS:

- 1. Black
- 2. White
- 3. Red
- 4. Green
- 5. Signal Active
- 6. Non-polarized + 24V
- 7. Audio-in Female
- 8. Negative
- 9. Push-to-Talk
- 10. Interrupted + 24V
- 11. Mic. Preamp Output

SUPERVISED CLASS B OPERATION



High efficiency amplifier with special circuitry permits high intelligibility voice messages with only 1/2 Watt power input to speaker. Equal performance would normally require several times the amplifier power with conventional designs.


ORDERING INFORMATION:

WHEN ORDERING PLEASE SPECIFY FIRE ALARM PANEL TYPE AND END OF LINE RESISTOR VALUE.

ILLUSTRATION	CAT. NO.	TOTAL SPEAKER WATTAGE	DESCRIPTION
	AU-360-M1	20 Watts	One 20 Watt Interface Module and Microphone with Enclosure. Includes microphone, signal generator, amplifier and interface module in a keylock enclosure, and operates from regulated or unregulated, unfiltered 24 to 40 Volts DC. One AU-360-M1 module will drive 40 1/2 Watt speakers (Up to 88 dB at 10 Feet)
	AU-360-M1 -DMR	20 Watts	One 20 Watt Interface Tone and Paging module with Digital Message Repeater, Mike and Enclosure.
	AU-360-M2	40 Watts	Two 20 Watt Interface Modules and Microphone with Enclosure.
	AU-360-1	20 Watts	One 20 W Interface Module with Enclosure.
	AU-360-2	40 Watts	Two 20 Watt Interface Modules with Enclosure.
	AU-360-3	60 Watts	Three 20 Watt Interface Modules with Enclosure.
	AU-360-E	20 Watts	One 20 Watt Module Extender Only.

Optional: for 70 VRMS applications, use Cat. No. AU-367.

TYPICAL INSTALLATION WITH AUXILIARY MICROPHONE




AU-360 SERIES ARCHITECTS/ENGINEERS SPECIFICATIONS

The required system shall provide an Evacuation Alarm Signal and Voice Transmission over the system speakers. All Equipment shall be UL Listed. The System shall be Audiosone Series AU-360 Voice Evacuation Alarm Integrated with a 24 VDC Fire Alarm Panel. Speaker Lines shall be 25 V RMS, and supervised for open or short circuit. Speakers shall be Audiosone Series AU-550 UL Listed Fire Protective Signaling Speakers.

1. Amplifier, Signal Generator, Power Supply, Output Transformer, and Speaker Lines shall be continuously supervised for normal operation, open or short circuit.
2. Amplifier shall be capable of withstanding a continuous output short circuit with alarm tone sounding without failure, fusing, or shutdown.
3. System shall be operable Non-Emergency Public Address announcements without an alarm condition.
4. The system shall have provision for connection of AU-562-2 UL Listed Remote Microphone Stations, which shall be automatically disconnected from system upon alarm activation.
5. A Battery Saver Circuit shall reduce standby current on the Amplifier Module to 0.005 Ampere or less during 120 VAC power failure.
6. Speaker Line Output shall include provision for Class A or Class B supervised speaker wiring.
7. Amplifier shall be specifically designed for High-Intelligibility Speech Reproduction and Fire Evacuation Signaling.
8. I/C Current Consumption shall be a maximum of 1.2 Amperes with a 20 Watt RMS Load with Alarm Sounding.
9. Protection Circuitry shall be included to prevent failure due to overloading, overheating, speaker line short circuit, over-voltage, and polarity reversal. Automatic current limiting shall keep circuitry within safe operating limits, without shutdown.

AU-562-2 AUDIO CONTROL



- Operates as a Remote Paging Microphone with AU-360 Series Voice Evacuation Alarm. Can be used for day-to-day paging, and automatically disabled during alarm condition.
- Attractive stainless-steel microphone station with gain control, key access switch, plug-in microphone and hanger bracket. Dual on-board amplifiers provide high output signal to eliminate hum and noise even when miles of wire are used.
- Unique design permits the use of an almost unlimited number of microphones, connected in parallel with 4-conductor shielded cable. (#20AWG)


AU-360-M1-DMR VOICE EVACUATION ALARM WITH PRE-RECORDED MESSAGE



The AU-360-M1-DMR forms a complete voice evacuation system that provides voice paging, a "slow whoop" alarm signal and pre-recorded message playback.

Upon activation, the DMR will pause 10 seconds to allow the "slow whoop" signal to be heard, then play back the pre-recorded message twice and return to the "slow whoop" signal. Timing and repetitions may be field programmed.

AU-510 VCS SERIES HIGH-POWER SPEAKER/AMPLIFIER



The AU-510-VCS Series was specifically designed for high-intelligibility voice and signal reproduction in supervised industrial evacuation systems. The audio input is taken directly from the AU-360 supervised speaker line, but without line-loading.

Rugged cast aluminum housing and aluminum re-entrant speaker, weather-proof for indoor or outdoor use.

State-of-the-art amplifier circuitry is high-efficiency and protected against overvoltage, overheating, overload, and polarity reversal. Requires no maintenance. 110 dB output, crystal-clear reproduction of voice and alarm signals. Volume control permits adjustment of output to suit local requirements.




Model	Voltage	Current	Audio Input Voltage	Audio Line Loading
AU-511-VCS	24 VDC	1.0A	25 VHMS	1/100 Watt
AU-512-VCS	120 VAC/24 VDC	0.4A/1.0A	(70.7V Optional)	1/100 Watt
AU-513-VCS	240 VAC/24 VDC	0.2A/1.0A		1/100 Watt

- Frequency Response: 400-4000 Hz. Tailored to optimize voice intelligibility and signal clarity.

- Power Output: 15 Watts RMS

- Input Impedance: 100 K Ohms. Load on speaker line less than 1/100 W

- Sound Level: 110 dBA @ 10 Feet



GENTEX

SPK SPEAKER

4" Square / 8" Round Speaker Series

1/4-2W SERIES

Applications

The Gentex SPK (1/4-2W) Series of speakers and strobe speakers are designed to meet code requirements for audio, visual and voice communications.

The SPK series are quality speaker products that offer you both dependable evacuation signaling and visual alarms or a combination of both.

The SPK series provide you a 25 or 70.7 VRMs speaker with field selectable power taps of 1/4W, 1/2W, 1W or 2W.

The SPK devices are UL 1480 listed for use with fire protective signaling system and are warranted for 2 years from the date of purchase.

Standard Features

- Strobe rating one flash per second
- High dB output
- Frequency Range 400-6000Hz
- Screw Terminals, separate in/out wiring to include 12Awg
- Flush wall or ceiling mounting to a standard 4" square x 2-1/8" backbox with a 1-1/2" extension ring.
- Both round and square speakers mount to all electrical boxes with extender ring.
- Optional 24VDC strobe models featuring 100cd strobe (H) or 17cd strobe (L). "Fire" printed in wall or ceiling mount versions, also available plain.
- Field selectable power taps: 1/4W, 1/2W, 1W, 2W
- Speaker voltage 25 or 70.7 VRMs standard, field selectable
- Sealed speaker back for optimum output and cone protection
- Attractive fire alarm red or beige textured painted finish. Only beige finish on 8" round faceplate.
- UL listed for fire protective services per UL 1480, strobe is listed UL 1638.

Available Models

Model Number	Speaker dB at 10 ft.			Strobe Rating			Color
	Input Watts	Typical dB	Peak dB	Input Voltage*	Light Intensity in Candels	Strobe Mount W.P.C	
SPK4R	1/4	81	87	15-30VDC	—	—	Red
SPK4-24VLR				15-30VDC	17	W	Red
SPK4-24VCR				15-30VDC	100	W	Red
SPK4-24VCR				15-30VDC	17	C	Red
SPK4-24VCR				15-30VDC	100	C	Red
SPK4-24VCR	1/2	84	90	15-30VDC	—	—	Red
SPK4-24VCR				15-30VDC	100	P	Red
SPK4-24VCR				15-30VDC	17	W	Beige
SPK4-24VCR				15-30VDC	100	W	Beige
SPK4-24VCR				15-30VDC	17	C	Beige
SPK4-24VCR	1	87	93	15-30VDC	100	W	Beige
SPK4-24VCR				15-30VDC	17	C	Beige
SPK4-24VCR				15-30VDC	100	C	Beige
SPK4-24VCR				15-30VDC	17	C	Beige
SPK4-24VCR				15-30VDC	100	C	Beige
SPK8-24VCR	2	90	96	15-30VDC	17	P	Beige
SPK8-24VCR				15-30VDC	100	P	Beige
SPK8-24VCR				15-30VDC	17	C	Beige
SPK8-24VCR				15-30VDC	100	C	Beige
SPK8-24VCR				15-30VDC	17	C	Beige



SPK4R



SPK8B



SPK824HCB



SPK424HWR

Approvals



- Americans with Disabilities Act (ADA)
- BS & A/MEA*
- CSFM*
- UL 1480/1638
- BIFP*
- NFPA 72

*Submitted and pending

How to Order: Example			
SPK4	24H	W	R
4 inch square	24VDC	Wall Mount	Red Faceplate
	100cd Strobe		
SPK8	24L	C	B
8 inch round	24VDC	Ceiling Mount	Beige Faceplate
	17cd Strobe		

SPK4-24VCR 100cd 17




GENTEX

SPK SPEAKER


1/4-2W SERIES

Mounting Diagrams

Minimal dimension for SBB backbox 3.5" approx.



Wiring Diagrams



NOTE: DO NOT USE LOOPEWIRE UNDER TERMINALS. BREAK WIRE RUN TO PROVIDE SUPERVISION OF CONNECTION.

NOTE: POWER IS SUPPLIED TO DEVICES WHEN CONTROL PANEL IS LATCHED
 *MAX. WIRE DISTANCE (IN FEET) = $\frac{\text{PANEL VOLTAGE} \times \text{WIRE CONDUCTIVITY}}{\text{TOTAL CURRENT DRAW}}$

*includes wire to and from device. Assumes use of copper wire. If aluminum wire is used, multiply wire conductivity by 0.61. CAUTION: APPLIES ONLY TO REGULATED SUPPLY.

NOTE: Peak operating current of "H" strobe - 200 ma rms.

Architect & Engineer Specifications

The fire alarm speaker shall be Gentex SPK _____ or equivalent. The speaker shall be capable of producing alarm tones or voice on all 25 or 70V RMS audio systems. The speaker shall provide incremental tap settings of 1/4, 1/2, 1 or 2 watts. Minimum dB ratings at 1/4 watt shall be _____ and at 2 watts _____ dB. Tap settings shall be adjustable with field selectable jumper pins. The speaker shall also have an optional visual signal capability. The strobe shall be a minimum of 100cd for compliance with the Americans with Disabilities Act and/or a minimum of 17cd for low intensity output requirements. All field wiring connections shall be made via terminal connections. All speakers shall be UL, CSM, BS&A, and BFP listed and comply with all local and state codes to include the Americans with Disabilities Act.

GENTEX

CORPORATION

Fire Protection Products: 10985 Chicago Dr.
 Box 310, Zeeland, MI 49464
 616/392-7195, FAX: 616/392-4219

Printed on recycled paper.

GX031792-2

Beam Smoke Detector



DS 240

Long Range Beam Smoke Detector



Featuring...

- ☐ Easy Bore Sight Alignment
- ☐ 30' to 350' Coverage
- ☐ 6 Sensitivity Levels
- ☐ 180° Horizontal Pointability
- ☐ Automatic Signal Synchronization
- ☐ Easy Maintenance
- ☐ High RFI Immunity
- ☐ Automatic Environmental Compensation
- ☐ Self-Adjusting Circuitry
- ☐ UL Listed, ULC Listed, CSFM Approved, BS & A Approved

Detection Systems, Inc. 130 Perinton Parkway, Fairport, New York 14450
Fairport, NY: 800/289-0096; 716/223-4060; FAX 716/223-9180
Hixson, TN: 800/727-3002; 615/877-3020

DS240 Specifications

Power Requirements

Operating Voltage: 18 to 32 VDC with a maximum allowable ripple of 4 Vp-p.
Standby Current: @ 24 VDC, receiver draws 40 mADC, transmitter draws 35 mADC.

Alarm Loop Configuration

Conventional 4-wire system.

Range

30 to 350 ft. (10m to 110m) range. Up to $\pm 90^\circ$ horizontal and $\pm 10^\circ$ vertical aiming capability.

Alarm Contacts

Form "A" (C, NO) contacts rated 1 amp, 60 VDC maximum for DC resistive loads.

Trouble Contacts

Form "B" (C, NO) contacts rated 1 amp, 60 VDC maximum for DC resistive loads.

Auxiliary Alarm Contacts

Form "C" (C, NO, NC) contacts rated 1 amp, 60 VDC maximum for DC resistive loads.

Storage and Operating Temperature

+32°F to +130°F (0°C to +54°C).

Mounting

Separate mounting base. The units are designed to be surface mounted, or mounted to 4" square, octagonal, single or double gang electrical boxes (not supplied).

Tamper Protection

Access door tamper switch in series with trouble contacts.

Sensitivity

Field selectable for 20, 30, 40, 50, 60, or 70% beam obscuration.

Signal Delay

Fire = 30 \pm 2 seconds; Trouble = 20 \pm 2 seconds.

Self-Compensating Circuitry

Receiver automatically adjusts for signal loss due to dust/dirt build-up on covers. Signals a trouble condition upon a 50% decrease or 20% increase in signal.

Automatic Signal Synchronization

Receiver automatically tunes to signal from Transmitter during setup mode. No need for sync wiring between Transmitter and Receiver.

Reference Signal Optimization

Receiver employs Automatic Gain Control (AGC) which automatically adjusts the signal level during setup or after a reset condition. This allows the system to optimize the signal regardless of the distance between the Transmitter and Receiver.

Optical Design

Vernier-Adjustable optics with bore sight alignment allows for easy setup.

Radio Frequency Immunity

No alarm or setup on critical frequencies in the range from 25 to 950 Megahertz using a 50 Watt transmitter.

Ordering Information

To order, specify DS240J and optional accessories shown below.

For ULC Installations, specify the DS240CAN and optional accessories shown below.

Listings and Approvals:

Listing Number:

Underwriter's Laboratories, Inc.

S3019

Underwriter's Laboratories of Canada


CS692

California State Fire Marshal

7257-1062:102

New York City Board of Standards and Appeals

Calendar # 723-87-SA





State Alarm/Electric Co., Inc.



1260 Lisbon Street

Lewiston, Maine 04240

(207) 782-2885

AGREEMENT

FOR

STATE THEATER

- ☐ PURCHASE / INSTALL
- ☐ LEASE / INSTALL
- ☐ SERVICE AGREEMENT
- ☐ MONITORING
- ☐ REPAIR ORDER
- ☐ ELECTRICAL

SPECIFICATIONS

PROPOSAL FOR FIRE/LITE SAFETY EQUIPMENT

- 1...Knox Box vault
 - 1...Fire Lite MS-9200 advanced fire control panel
 - 1...Remote 8 zone relay card
 - 1...XRM Power supply card
 - 2...12 volts 7AH Gell battery
 - 2...System sensor beam smoke detectors
 - 1...AU-360-M-1 Audio EVAC Panel
 - 1...DMR-Digital message repeater
 - 15...Gent & horn/speaker/strobe units
 - 11...BG-10LX Addressable pull stations
 - 5...135' Rate/rise heat detectors
 - 5...M300 Remote contact device modules
 - 10...Addressable smoke detectors
 - 2...Zone place of refuge systems
 - 1...2 circuit city box
1. All equipment 50% down 50% on delivery
 2. All staging and ladders over 8' by owner
 3. All cutting, patching, drilling where necessary by owner
 4. All AC wiring by others
 5. All labor to install above by State Alarm Company
 6. All external cost by city of Portland assumed by owner
 7. Work will be done by October 31, 1993

FOR THE CONTRACT PRICE OF\$
TAX\$
TOTAL\$
LESS DEPOSIT\$
BALANCE\$

ACCEPTANCE OF ABOVE AGREEMENT AS OUTLINED ABOVE AND
UNDER CONDITIONS ON REVERSE SIDE * PAYMENT OF BALANCE
WILL BE MADE AT COMPLETION OF INSTALLATION OR REPAIR ORDER
UNLESS NOTED ABOVE.

MONITORING \$ X per mo.

SERVICE/LEASE
AGREEMENT \$ X per mo.

PURCHASER

STATE ALARM/ELECTRIC CO., INC.

David Anderson
Authorized Representative

DATE 9/30/93



APPLICATION FOR PERMIT
DEPARTMENT OF BUILDING INSPECTIONS SERVICES
ELECTRICAL INSTALLATIONS

Date 19 July 1994, 19
Receipt and Permit number 3168

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 609 Congress St State Theatre
OWNER'S NAME: Congress Property Management ADDRESS: _____

	FEES
OUTLETS:	
Receptacle: <u>30</u> Switches <u>10</u> Plugmold _____ ft. TOTAL _____	8.00
FIXTURES: (number of)	
Incandescent <u>20</u> Fluorescent _____ (not strip) TOTAL _____	2.00
Strip Fluorescent _____ ft. _____	
SERVICES:	
Overhead _____ Underground _____ Temporary _____ TOTAL amperes _____	
METERS: (number of) _____	
MOTORS: (number of)	
Fractional _____	
1 HP or over _____	
RESIDENTIAL HEATING:	
Oil or Gas (number of units) _____	
Electric (number of rooms) _____	
COMMERCIAL OR INDUSTRIAL HEATING:	
Oil or Gas (by a main boiler) _____	
Oil or Gas (by separate units) _____	
Electric Under 20 kws _____ Over 20 kws _____	
APPLIANCES: (number of)	
Ranges _____	Water Heaters _____
Cook Tops _____	Disposals _____
Wall Ovens _____	Dishwashers _____
Dryers _____	Compactors _____
Fans _____	Others (denote) _____
TOTAL _____	
MISCELLANEOUS: (number of)	
Branch Panels _____	
Transformers _____	
Air Conditioners Central Unit _____	
Separate Units (windows) _____	
Signs 20 sq. ft. and under _____	
Over 20 sq. ft. _____	
Swimming Pools Above Ground _____	
In Ground _____	
Fire/Burglar Alarms Residential _____	
Commercial _____	
Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under _____	
over 30 amps _____	
Circus, Fairs, etc. _____	
Alterations to wires _____	
Repairs after fire _____	
Emergency Lights, battery <u>4</u> _____	4.00
Emergency Generators _____	
INSTALLATION FEE DUE: _____	
FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT DOUBLE FEE DUE: _____	
FOR REMOVAL OF A "STOP ORDER" (304-16.b) _____	
TOTAL AMOUNT DUE: _____	15.00

INSPECTION:

Will be ready on _____, 19____; or Will Call XXX
CONTRACTOR'S NAME: Thomas Electric Cliff Thomas
ADDRESS: RR 1 Box 305 W. Buxton
TEL.: 727-3257
MASTER LICENSE NO.: 3168 SIGNATURE OF CONTRACTOR: [Signature]
LIMITED LICENSE NO.: _____

INSPECTOR'S COPY — WHITE
OFFICE COPY — CANARY
CONTRACTOR'S COPY — GREEN

ELECTRICAL INSTALLATIONS —

Permit Number 5160

Location 607 Long Road

Owner Sybil J. Davis

Date of Permit 1-17-24Final Inspection 1-5-75

By Inspector — 2000

Permit Application Register Page No. Camp 12

INSPECTIONS: Service _____ by _____

Service called in _____

Closing-in 7-26-99 by SB

PROGRESS INSPECTIONS: _____ / _____ / _____

DATE OF BIRTH: _____ / _____ / _____

4. *Journal of the American Statistical Association*, 1990, 85, 1039-1042.

[illegible][illegible]
$$\frac{1}{\rho} \frac{d\rho}{dt} = \frac{1}{\rho} \frac{d\rho}{d\tau} \frac{d\tau}{dt} = \frac{1}{\rho} \frac{d\rho}{d\tau} \frac{1}{\gamma} = \frac{1}{\gamma} \frac{1}{\rho} \frac{d\rho}{d\tau}$$

_____ / _____ / _____

DATE:

REMARKS:

[illegible]

PRODUCER		INSURED		COVERAGE	
PRODUCER Kelly-Murray Insurance Agency P.O. Box 199 11626 York Road Hunt Valley MD 21030-0199 410-527-3434		INSURED MBNA Corp. and Subsidiaries Attn: Kristin Birch 400 Christians Road Sparks DE 19713		COVERAGE THIS CERTIFICATE IS ISSUED AS A MATTER OF INFORMATION ONLY AND CONFERS NO RIGHTS UPON THE CERTIFICATE HOLDER. THIS CERTIFICATE DOES NOT AMEND, EXTEND OR ALTER THE COVERAGE AFFORDED BY THE POLICIES BELOW.	
COMPANIES AFFORDING COVERAGE					
COMPANY LETTER A Federal Insurance Company		COMPANY LETTER B			
COMPANY LETTER C		COMPANY LETTER D			
COMPANY LETTER E		COMPANY LETTER F			
COVERAGE THIS IS TO CERTIFY THAT THE POLICIES OF INSURANCE LISTED BELOW HAVE BEEN ISSUED TO THE INSURED NAMED ABOVE FOR THE POLICY PERIOD INDICATED. NOTWITHSTANDING ANY REQUIREMENT, TERM OR CONDITION OF ANY CONTRACT OR OTHER DOCUMENT WITH RESPECT TO WHICH THIS CERTIFICATE MAY BE ISSUED OR MAY PERTAIN, THE INSURANCE AFFORDED BY THE POLICIES DESCRIBED HEREIN IS SUBJECT TO ALL THE TERMS, EXCLUSIONS AND CONDITIONS OF SUCH POLICIES. LIMITS SHOWN MAY HAVE BEEN REDUCED BY PAID CLAIMS.					
CO UTA	TYPE OF INSURANCE	POLICY NUMBER	POLICY EFFECTIVE DATE (MM/DD/YY)	POLICY EXPIRATION DATE (MM/DD/YY)	LIMITS
A	GENERAL LIABILITY COMMERCIAL GENERAL LIABILITY CLAIMS MADE OWNER'S & CONTRACTOR'S PROT.	35306328	03/01/94	03/01/95	GENERAL AGGREGATE \$3,000,000 PRODUCTS-COMP/OP AGG. \$3,000,000 PERSONAL & ADV. DUTY \$1,000,000 BODILY INJURY \$1,000,000 PROPERTY DAMAGE (Any one form) \$1,000,000 MED. EXPENSE (Any one person) \$10,000
	AUTOMOBILE LIABILITY ANY AUTO ALL OWNED AUTOS SCHEDULED AUTOS HIREN AUTOS NON-OWNED AUTOS DAMAGE LIABILITY				COMBINED SINGLE LIMIT BODILY INJURY PROPERTY DAMAGE
	UMBRELLA FORM OTHER THAN UMBRELLA FORM				EACH OCCURRENCE AGGREGATE
	WORKER'S COMPENSATION AND EMPLOYERS' LIABILITY				STATUTORY LIMITS EACH ACCIDENT DISEASE-POLICY LIMIT DISEASE-EACH EMPLOYEE
OTHER					
DESCRIPTION OF OPERATIONS/LOCATIONS/VEHICLES/SPECIAL ITEMS Re: Space leased at 901 Washington Avenue, Portland, ME 04101					
CERTIFICATE NOTICER J.B. Brown 682 Congress Street P.O. Box 207 Portland ME 04112-0207					
CANCELLATION SHOULD ANY OF THE ABOVE DESCRIBED POLICIES BE CANCELLED BEFORE THE EXPIRATION DATE THEREOF, THE ISSUING COMPANY WILL ENDEAVOR TO MAIL 10 DAYS WRITTEN NOTICE TO THE CERTIFICATE HOLDER NAMED TO THE LEFT. BUT FAILURE TO MAIL SUCH NOTICE SHALL IMPOSE NO OBLIGATION OR LIABILITY OF ANY KIND UPON THE COMPANY, ITS AGENTS OR REPRESENTATIVES.					
AUTHORIZED REPRESENTATIVE <i>David E. Kelly</i>					

City of Portland, Maine – Building or Use Permit Application 389 Congress Street, 04101, Tel: (207) 874-8703, FAX: 874-8716

Location of Construction: 609 Congress St- 6th flr		Owner: Congress Property Management		Phone: 775-1737	Permit No: 950362
Owner Address: 51A Oak St- Portland, ME 04101		Leasee/Buyer's Name:		Phone:	Business Name:
Contractor Name: owner		Address:		Phone:	
Past Use: office space	Proposed Use: office space w inter renvtns	COST OF WORK: \$ 20,000		PERMIT FEE: \$ 120	
		FIRE DEPT. <input type="checkbox"/> Approved <input type="checkbox"/> Denied		INSPECTION: Use Group: Type:	
Proposed Project Description: make interior renovations		Signature:		Signature:	
		PEDESTRIAN ACTIVITIES DISTRICT (P.U.D.) Action: Approved <input type="checkbox"/> Approved with Conditions: <input type="checkbox"/> Denied <input type="checkbox"/>			
Permit Taken By: L Chase		Date Applied For: 4/18/95			
<p>1. This permit application doesn't preclude the Applicant(s) from meeting applicable State and Federal rules.</p> <p>2. Building permits do not include plumbing, septic or electrical work.</p> <p>3. Building permits are void if work is not started within six (6) months of the date of issuance. False information may invalidate a building permit and stop all work.</p>					
<p align="center">CERTIFICATION</p> <p>I hereby certify that I am the owner of record of the named property, or that the proposed work is authorized by the owner of record and that I have been authorized by the owner to make this application as his authorized agent and I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in the application issued, I certify that the code official's authorized representative shall have the authority to enter all areas covered by such permit at any reasonable hour to enforce the provisions of the code(s) applicable to such permit</p>					
SIGNATURE OF APPLICANT: <i>[Signature]</i>		ADDRESS:		DATE: 4/18/95	PHONE:
RESPONSIBLE PERSON IN CHARGE OF WORK, TITLE				PHONE:	
<p align="center">White-Permit Desk Green-Assessor's Canary-D.P.W. Pink-Public File Ivory Card-Inspector</p>					

PERMIT ISSUED

Permit Issued:
APR 20 1995

CITY OF PORTLAND

Zone: B-3 CBL: 46D31

Zoning Approval: *[Signature]* 4/19/95

Special Zone or Reviews:

☐ Shoreland

☐ Wetland

☐ Flood Zone

☐ Subdivision

☐ Site Plan ☐ minor ☐ rm ☐

Zoning Appeal

☐ Variance

☐ Miscellaneous

☐ Conditional Use

☐ Interpretation

☐ Approval

☐ Denied

Historic Preservation

☐ Not in Historic or Landmark

☐ Does Not Require Review

☒ Requires Review

Action:

☐ Approved

☐ Approved with Conditions

☐ Denied

Date: 4/19/95

[Signature]

CEO DISTRICT **5**

m.w.g.

FROM: P. Samuel Hoffses, Chief of Inspection Services

DATE: May 17, 1995

SUBJECT: State Theater, 609 Congress Street
Plaster Falling from Ceiling 1st balcony

On May 17, 1995 at 8:02 P.M., I received a call at home from the Portland Fire Department Dispatcher requesting the presence of a building official at the State Theater on Congress Street to investigate a ceiling falling and causing injury to four people. Upon arriving at the theater at 8:31 P.M., I reported to Deputy Chief Thompson of the Portland Fire Department. He showed me the area of the ceiling in question.

The section of the ceiling that had fallen, was a section under the first balcony on the southerly side (facing the stage, left side) one quarter down the balcony. In this area, there is a structural beam which runs the width of the theater and extends down from the balcony ceiling by approximately 1 to 2 feet. The beam is enclosed with concrete and has plaster over the concrete. The thickness of the plaster is approx. 3/4" on the sides and 1" to 2" on the bottom. The section that fell was on the bottom section measuring about 2' in width and 5' in length. I made a visual inspection of the section and examined the fallen plaster. I did not see any signs of moisture on the plaster but thought I could see water marks on the concrete and plaster in the area of the damaged ceiling. I asked the fire department to use their plaster hook to remove any loose areas which they did. The plaster from the edge toward the building exterior wall was removed easily. This was about a 2' X 6' section. I also asked them to go to the other end of the damaged area and remove as much loose plaster as possible or until it becomes very difficult to remove. This was done and approximately a 2' X 3' section was removed. (Upon arrival, the fire department had sectioned off the area under the beam and four rows up and down.) I requested the fire department to probe along the beam for other voids. They found none. I then proceeded to the void between the balcony ceiling and floor. I investigated this area (visually and by touch) but found no signs of water or structural movement in the area of the beam. Next, I investigated the void between the building roof and the ceiling of the main theater. I was looking for any water damage or any item that might suggest a structural problem. I was accompanied by a firefighter and the building Manager, Bruce-----. I walked each truss running the length of the theater. Only one water spot was found. The next area I looked at was in the basement area, and no type of structural movement or failure was found.

I then met with the theater manager and told him I wanted a structural inspection to be made by either an architect or engineer. I stressed that a structural engineer would be a better choice and the manager agreed to have this done on the 18th but before the next performance. (the evening of the 18th) I left the theater at 9:40 P.M.

At 9:40 a.m., on May 18, 1995, I returned to the State Theater with LT. McDougall of the Portland Fire Department. We inspected the damage area once again with the management staff. The area in which I thought was water marked on the 17th was marked on the concrete. The area in question was again examined. We did not see stress marks or loose plaster. I requested the time that the architect would be there. I was told that Mr. Victor Sango, Architect, would be examining the damage area around noon. Mr. Sango was the architect during the 1993 renovations. LT. McDougall and I left the

site at 10:15.

At 11:30, received a call stating that Mr. Sango would be at the theater at 12:15 P.M. At 12:10, LT. McDougall and I returned to the theater and met with the theater staff and Mr. Sango. We all agreed the proper steps were taken and Mr. Sango suggested and it was agreed that a plaster contractor should look at this area. LT. McDougall and I left the site and I returned to City Hall. At 12:30 received a call from a staff member and he stated that Mr. Stango and the plaster contractor had checked the area and were satisfied with the conditions of the plaster. Once again, I suggested that a structural engineer look at the entire theater and the condition of the remaining plaster.

During my talks with the theater staff and owner, I stated that the plaster covering the concrete did not have to be left there for fire protection because now that the theater is fully sprinkled, the fire resistant rating on the truss could be reduced one hour. Therefore, the plaster around the beam could be removed if so desired.

On May 19, 1995, I sent a letter requesting structural analysis.

On May 22, 1995, I talked with owner of building. They will not be having any more events until the theater has been checked, but will keep me informed. Call 879-0949

On May 22, 1995, received call from Mr. Stango. He stated he had been removed from the job at the theater and had not finished his review. Then tried calling Lola Kampf, 879-0949.

On May 23, 1995, called Ms. Lola (Nick) Kampf, ref. engineer on job. Nick Kampf explained to me that Dave Tetreau, P.E. of S. & D. would be doing the structural analysis.

On May 23, 1995, Mr. Kampf called stating that the plaster would be removed.

On May 25, 1995, I talked with Mr. Kampf regarding the State Theater. All plaster is removed and skim coat is on. David Tetreau is still on job. Plaster checked again.

On June 5, 1995, I talked with D.T. of Structural Design and he stated he would send a copy of his work report to me. He also stated that a full inspection of all plaster had not been done at this time and was waiting to get the word from the owners.

CRITERIUM MOONEY ENGINEERS

MEMORANDUM

630 BRIGHTON AVENUE
PORTLAND ME 04102
TEL 207 775-1969
TOLL FREE : 800 922-1269
FAX 207 775-4405

TO: Sam Hoffses, City of Portland
Department of Inspections

FROM: Victor O. Stango, P.E. *Victor O. Stango*

DATE: May 24, 1995

RE: State Theater Ceilings

CC: Nick and Lola Kampf
Scott Simons Architects

As I discussed with you yesterday during our telephone call, Nick and Lola Kampf have terminated our engineering services related to the above project.

Based on our limited review of the theater, I recommend that the following be completed prior to any further use of the theater:


- 1) complete removal of all plaster along the bottom of the balcony truss (adjacent to spalled area);
- 2) similar removal of other plaster where not mechanically anchored or hung from supporting elements;
- 3) complete inspection of all ceilings within the theater for condition and adequacy, including lath, hangers, etc.;
- 4) removal of all debris on top of ceilings;
- 5) inspection of all stairs, railings, etc. for structural integrity and Code compliance.

We regret that we cannot complete our review of the project. If I can be of further service in this matter, please call.


VOS/bb

REGISTERED
PROFESSIONAL
ENGINEERS
BUILDING DIAGNOSTICS
INSPECTIONS
ANALYSIS
MAINTENANCE PLANNING
DESIGN

Call David Tethum of Sand D.



Sam
D.A.



SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4. Put your address in the "RETURN TO" space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional services requested, check the appropriate box(es) in the "Type of Service" section. For additional service(s) requested, check the appropriate box(es) in the "Type of Service" section. For additional service(s) requested, check the appropriate box(es) in the "Type of Service" section.

1. Show to whom delivered, date, and addressee's address. 2. Restricted Delivery (Extra charge)

3. Article Addressed to:
Congress Property Management
51 Oak Street
Portland, Maine 04101

4. Article Number:
P838-923-535

Type of Service:
☒ Registered ☐ Insured
☐ Certified ☐ COD
☐ Express Mail

5. Signature - Addressee:
X *[Signature]*

6. Signature - Agent:
X *[Signature]*

7. Date of Delivery:
6/13

8. Addressee's Address (ONLY if requested and fee paid)

PS Form 3811, Mar. 1987 U.S.G.P.O. 1987-178-288 DOMESTIC RETURN RECEIPT

Sam

5-19

1132

carb.

Michael Bowdler

799-2360-~~4~~

- D has idea

why plaster fell

d sound waves

lee

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

May 19, 1995

Congress Property Management
51A Oak Street
Portland, Maine 04101

RE: 609 Congress St.
(State Theater)

Dear Sir or Madam,

This is a follow-up on the verbal conversation we had on both May 17th and 18th on having a structural analysis done by a Registered Structural Engineer on the structure with special alterations on the plaster issue. I feel due to concerns of all parties, that this work should be done within the next few days, but no later than the end of the month. A copy of the report must be submitted to this office.

Thank you in advance for your assistance in this matter.

Sincerely,

P. Samuel Hoffses
Chief of Inspection Services

Inspection Services
P. Samuel Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

May 19, 1995

Congress Property Management
51A Oak Street
Portland, Maine 04101

RE: 609 Congress St.
(State Theater)

Dear Sir or Madam,

This is a follow-up on the verbal conversation we had on both May 17th and 18th on having a structural analysis done by a Registered Structural Engineer on the structure with special alterations on the plaster issue. I feel due to concerns of all parties, that this work should be done within the next few days, but no later than the end of the month. A copy of the report must be submitted to this office.

Thank you in advance for your assistance in this matter.

Sincerely,


P. Samuel Hoffses
Chief of Inspection Services



Congress Property Management

PO Box 4211
Portland, Maine 04101
(207) 879-0949

609 Congress St

July 26, 1995


Sam Hoffses
Inspection Services
389 Congress Street
Portland, Maine 04101


Dear Sam:

Thank you for your guidance during the plaster accident of May 17, 1995. Enclosed is David Tetreault's structural analysis in response to your letter of May 19, 1995, as well as a letter from Byron O'Shea, of O'Sheas plastering, detailing the repair. The subsequent roof leak that you noted and which damaged plaster has been repaired on 6/19/95 by Maine Roofing. The roofers then water tested the remaining roof as we discussed and noted no other leaks. I am still awaiting their report which I will forward to you. Byron O'Shea walked the suspended plaster ceiling on 6/17/95. Water as you know damages plaster, so but for the exception of avoiding more water damage to plaster he noted no immediate other actions to take. To prevent such plaster damage, as you know, a new rubber membrane was put on the theater on July 30, 1991.

I would like to at this time also reiterate the Congress Property leases the State Theater to Perfect Pitch whose principals are Kelly Grave, Steve Bailey, and Kim Magid. Whenever you have non structural concerns such as the suspended ceiling, they should be addressed to them with a copy to us. But of course, I am also available to you regarding any of my properties at any time. Their address is P.O. Box 4195, Portland, Maine 04101 and their phone number is 773-5540. If there are any areas you feel have not been adequately addressed please contact me at 775-5003.

Sincerely,


Nicholas Kampf
President
Congress Property Management



SHEA'S
Plastering
CO. INC.

Interior and exterior wall & ceiling specialists.

June 1, 1995

State Theater Repairs

State Theater
P.O. Box 40195
Portland, Maine 04101

To whom it may concern,

The following is a description of the damage and repairs for the above mentioned project.

Damage Description:

On the underside of the balcony ceiling a cement beam, coated with one coat of Gypsum plaster that was approximately 1"-2" thick. Looking at the beam from the stage, the plaster had been removed approximately 16' from the right to left side of the beam. The remaining plaster on the beam was cracked even with the bottom side of the cement, approximately the same distance.

REPAIR DESCRIPTION:


We removed the plaster from the underside of the beam, and recoated with a coat of SILPRO WELD-O-BOND with DIAMOND PLASTER finish approximately, 1/8"-1/4" thick.

Sincerely,

Byron Shea

Byron Shea
President
Shea's Plastering

BS:lg



RR 1 Box 559, Orr's Island, ME 04066 (207) 833-2918

FROM: P. Samuel Hoffses, Chief of Inspection Services

DATE: May 17, 1995

SUBJECT: State Theater, 609 Congress Street
Plaster Falling from Ceiling 1st balcony

On May 17, 1995 at 8:02 P.M., I received a call at home from the Portland Fire Department Dispatcher requesting the presence of a building official at the State Theater on Congress Street to investigate a ceiling falling and causing injury to four people. Upon arriving at the theater at 8:31 P.M., I reported to Deputy Chief Thompson of the Portland Fire Department. He showed me the area of the ceiling in question.

The section of the ceiling that had fallen, was a section under the first balcony on the southerly side (facing the stage, left side) one quarter down the balcony. In this area, there is a structural beam which runs the width of the theater and extends down from the balcony ceiling by approximately 1 to 2 feet. The beam is enclosed with concrete and has plaster over the concrete. The thickness of the plaster is approx. 3/4" on the sides and 1" to 2" on the bottom. The section that fell was on the bottom section measuring about 2' in width and 5' in length. I made a visual inspection of the section and examined the fallen plaster. I did not see any signs of moisture on the plaster but thought I could see water marks on the concrete and plaster in the area of the damaged ceiling. I asked the fire department to use their plaster hook to remove any loose areas which they did. The plaster from the edge toward the building exterior wall was removed easily. This was about a 2' X 6' section. I also asked them to go to the other end of the damaged area and remove as much loose plaster as possible or until it becomes very difficult to remove. This was done and approximately a 2' X 3' section was removed. (Upon arrival, the fire department had sectioned off the area under the beam and four rows up and down.) I requested the fire department to probe along the beam for other voids. They found none. I then proceeded to the void between the balcony ceiling and floor. I investigated this area (visually and by touch) but found no signs of water or structural movement in the area of the beam. Next, I investigated the void between the building roof and the ceiling of the main theater. I was looking for any water damage or any item that might suggest a structural problem. I was accompanied by a firefighter and the building Manager, Bruce-----. I walked each truss running the length of the theater. Only one water spot was found. The next area I looked at was in the basement area, and no type of structural movement or failure was found.

I then met with the theater manager and told him I wanted a structural inspection to be made by either an architect or engineer. I stressed that a structural engineer would be a better choice and the manager agreed to have this done on the 18th but before the next performance. (the evening of the 18th) I left the theater at 9:40 P.M.

At 9:40 a.m., on May 18, 1995, I returned to the State Theater with LT. McDougall of the Portland Fire Department. We inspected the damage area once again with the management staff. The area in which I thought was water marked on the 17th was marked on the concrete. The area in question was again examined. We did not see stress marks or loose plaster. I requested the time that the architect would be there. I was told that Mr. Victor Sango, Architect, would be examining the damage area around noon. Mr. Sango was the architect during the 1993 renovations. LT. McDougall and I left the

site at 10:15.

At 11:30, received a call stating that Mr. Sango would be at the theater at 12:15 P.M. At 12:10, LT. McDougall and I returned to the theater and met with the theater staff and Mr. Sango. We all agreed the proper steps were taken and Mr. Sango suggested and it was agreed that a plaster contractor should look at this area. LT. McDougall and I left the site and I returned to City Hall. At 12:30 received a call from a staff member and he stated that Mr. Sango and the plaster contractor had checked the area and were satisfied with the conditions of the plaster. Once again, I suggested that a structural engineer look at the entire theater and the condition of the remaining plaster.

During my talks with the theater staff and owner, I stated that the plaster covering the concrete did not have to be left there for fire protection because now that the theater is fully sprinkled, the fire resistant rating on the truss could be reduced one hour. Therefore, the plaster around the beam could be removed if so desired.

On May 19, 1995, I sent a letter requesting structural analysis.

On May 22, 1995, I talked with owner of building. They will not be having any more events until the theater has been checked, but will keep me informed. Call 879-0949


On May 22, 1995, received call from Mr. Sango. He stated he had been removed from the job at the theater and had not finished his review. Then tried calling Lola Kampf, 879-0949.

On May 23, 1995, called Ms. Lola (Nick) Kampf, ref. engineer on job. Nick Kampf explained to me that Dave Tetreau, P.E. of S. & D. would be doing the structural analysis.

On May 23, 1995, Mr. Kampf called stating that the plaster would be removed.

On May 25, 1995, I talked with Mr. Kampf regarding the State Theater. All plaster is removed and skim coat is on. David Tetreau is still on job. Plaster checked again.

On June 5, 1995, I talked with D.T. of Structural Design and he stated he would send a copy of his work report to me. He also stated that a full inspection of all plaster had not been done at this time and was waiting to get the word from the owners.



From: Portland Office Chief of Dept.

104

Date: 17 May 95

Subject: STATE Theater 609 Congress St.
Plaster Falling From Ceiling, 1st balcony

On 17 May 1995 @ 8:02 PM I received a call @ home from the Portland Fire Dept. Dispatcher requesting the presence of a building official at the State Theater on Congress St. to investigate a ceiling falling and causing injury to 4 people. Upon arriving at the theater 8:31 PM, reported to Deputy Chief Thompson of the PFD, and he showed me the area of the ceiling in question.

The section of the ceiling that had fallen was a section under the 1st balcony on the south side (facing the stage left side) approx. 10' x 12' down the balcony. In this area there is a structural beam which runs the width of the theater and extends from the balcony ceiling by approx. 1' to 2'. The beam is encased with concrete and has plaster over the concrete. The thickness of the plaster is approx. 3/4" on the sides and 1" to 2" on the bottom. The section that fell was on the bottom section measuring about 2' in width and 5 feet in length. I made a visual inspection of the section and examined the fallen plaster. I didn't see any signs of moisture on the plaster but thought I could see water marks on the concrete and plaster in the

20ff

area of the damaged ceiling. I asked the fire dept. to use their pike pole to remove any loose areas, which they did. The plaster from the edge toward the building exterior wall was removed easily. This was about a 2' x 6' section. I also asked them to go to the other end of the damage area and remove as much loose plaster as possible, or until it became very difficult to remove. This was done and approx 3' x 3' section was removed. Upon arrival the fire dept had sections off the area under the beam and gone raw up and down. I requested the fire dept. to probe along the beam for other leaks, they didn't find any. I then went to the void between the below ceiling and floor, I investigated this area (visual and touch) and found no signs of water or structural movement in the area of the beam. I then investigated the void between the building roof and the ceiling of the main theatre. I was looking for any water damage or any stain that might suggest a structural problem. It was accompanied by a firefighter and the building manager, since I walked each truss beam along the length of the theatre. Only one water spot was found. The next place I looked at was basement area, I didn't find any type of structural movement or failure. I then met with the Theater Manager.

and told them I want a structural inspection to be made by a either architect or engineer. I think a structural engineer would be better choice. The manager agreed. To have this done on the 18th but before the next performance. (The night of the 18th) I left the theater at 9:40 PM.

On 18th May, 95 I returned to the State Theater with Lt. McDougall P.D. @ 9:40 AM, we looked at the damage area once again with the management staff and Lt. Mc. The area in which I thought were route marks on the 17th were marks in the concrete. We all looked at the area in question. I couldn't see any stress marks or loose plaster. I requested to know the time when the architect would be there. (They stated Mr. Victor Sanyo ^(architect) would be looking at the damage area around noon. Mr. Sanyo was the Architect during the 93 renovation). Lt. Mc. and I left the site at 10:15.

At 11:30 I received a call stated Mr. Sanyo would be at the theater @ 12:15 PM. At 12:10 PM Lt. McDougall and I returned to the theater and met with the theater staff and Mr. Sanyo. we all agreed the proper steps were taken and Mr. Sanyo suggested that a plaster person should look at area, which was agreed upon. Lt. Mc. and I left the site and I returned to City Hall. At 2 PM I received a call from the Staff member and

VICTOR STORGO

775-1969

4-

he stated that Mr. Suroyo and the plaster contractor had checked the area and was satisfied with the condition of the plaster. I once again suggested that a structural engineer look at the whole theater on the condition of the remaining plaster.

During my talks with the theater staff I was told that the plaster covering the concrete didn't have to be left there for fire protection, because now that the theater is fully sprinklered the fire resistance rating on the truss could be reduced 1 hr. Therefore the plaster around the beam could be removed, if so desired.

19 MAY 95 SENT Letter requesting structural analysis.

22 MAY 95 TALKED with owner of building they will not have any more event until the theater has been checked - WILL keep me informed - call 879-0819

22 MAY 95 CALL FROM MR. V. STORGO, he STATED he had been removed from the job at the Theater and hadn't finished his review - Tried calling Lota Kampf, 879-0944 -

23 MAY 95 CALL MR. ^{NICK} Lota Kampf re: Eng. on job. NICK Kampf explained to me that Dave Detrou ^{PE} of S.E.J. would be doing the structural analysis.

13 MAY 95 MR. Kampf called plaster will be removed -

25/MAY/95 - Talked with Mr. Kempt on
STATE THEATRE - All plaster removal
Knee COAT ON - David Fiteall - still on
job - Plaster checked ~~again~~ again.

5/JUNE/95 Talked with D.T. of Structural Designer
he stated he would send a copy of his work report
to me - He also stated that in full inspection
of all plaster hadn't been done yet this time
he was waiting to get the word from the
owners -

City of Portland, Maine - Building or Use Permit Application 389 Congress Street, 04101, Tel: (207) 874-8703, FAX: 874-8716

Location of Construction: 389 Congress St - 6th flr		Owner: Congress Project Manager	Phone: 771-1737	Permit No: 950362
Owner Address: 389 Congress St - 6th flr	Lease/Buyer's Name:	Phone:	Business Name:	PERMIT ISSUED APR 20 1995 CITY OF PORTLAND
Contractor Name:	Address:	Phone:		
Past Use: office space	Proposed Use: office space & interior renovations	COST OF WORK: \$	PERMIT FEE: \$	
Proposed Project Description: site interior renovations		FIRE DEPT. <input type="checkbox"/> Approved <input type="checkbox"/> Denied Signature: [Signature]	INSPECTION: Use Group/Type: [Signature] Signature: [Signature]	Zoning: CBL: Zoning Approval: [Signature] Special Zone or Reviews: <input type="checkbox"/> Shoreland <input type="checkbox"/> Wetland <input type="checkbox"/> Flood Zone <input type="checkbox"/> Subdivision <input type="checkbox"/> Site Plan <input type="checkbox"/> minor <input type="checkbox"/> major
Permit Taken By: L Chase	Date Applied For: 3/1/95	PEDESTRIAN ACTIVITIES DISTRICT (P.A.D.) Action: <input checked="" type="checkbox"/> Approved <input type="checkbox"/> Denied <input type="checkbox"/> Approved with Conditions Signature: [Signature] Date: [Signature]		

1. This permit application doesn't preclude the Applicant(s) from meeting applicable State and Federal rules.
2. Building permits do not include plumbing, septic or electrical work.
3. Building permits are void if work is not started within six (6) months of the date of issuance. False information may invalidate a building permit and stop all work.

CERTIFICATION

I hereby certify that I am the owner of record of the named property, or that the proposed work is authorized by the owner of record and that I have been authorized by the owner to make this application as his authorized agent and I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in the application issued, I certify that the code official's authorized representative shall have the authority to enter all areas covered by such permit at any reasonable hour to enforce the provisions of the code(s) applicable to such permit.

SIGNATURE OF APPLICANT

ADDRESS:

DATE:

PHONE:

RESPONSIBLE PERSON IN CHARGE OF WORK, TITLE

PHONE:

White-Permit Desk Green-Assessor's Canary-D.P.W. Pink-Public File Ivon Card-Inspector

CEO DISTRICT

5

COMMENTS

4-26-95 WIP workers were
on beach. making

5-13-95 Fastened Lemo under way
on interior non-bearing walls

Inspection Record

Type	Date
Foundation: 5-16-95 checked Framing	
Framing: OK & Close-in	
Plumbing: 6/95/OK for Cdr	
Final: 6/95/OK for Cdr	
Other: 0cc.	



CITY OF PORTLAND, MAINE
Department of Building Inspection

Certificate of Occupancy

LOCATION 608 Congress St. 6th Floor

Issued to Congress Property Management

Date of Issue 7/1/95

This is to certify that the building, premises, or part thereof, at the above location, built — ~~as shown~~ — changed as to use under Building Permit No. 950362, has had final inspection, has been found to conform substantially to requirements of Zoning Ordinance and Building Code of the City, and is hereby approved for occupancy or use, limited or otherwise, as indicated below.

PORTION OF BUILDING OR PREMISES

office space
6th floor

APPROVED OCCUPANCY

entire

Limiting Conditions:

This certificate supersedes
certificate issued

Approved:

7/1/95

(Date)

Inspector

Notice: This certificate identifies lawful use of building or premises, and ought to be transferred from owner to owner when property changes hands. Copy will be furnished to owner or lessee for one dollar.

Inspection Services
Samuel P. Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

CITY OF PORTLAND

April 19, 1995

Congress Property Management
51A Oak Street
Portland, ME 04101

Re: 609 Congress St (6th fl)


Dear Sir,

Your application to make interior renovations has been reviewed and a permit is herewith issued subject to the following requirements: This permit does not excuse the applicant from meeting applicable State and Federal laws.

No Certificate of Occupancy will be issued until all requirements of this letter are met.

1. No exterior work shall be done.
2. All exit signs, lights, and means of egress lighting shall be done in accordance with chapter 10, section & subsections 1023 & 1024 of the city's building code (BOCA National Building Code/1993).
3. A portable fire extinguisher shall be located as per NFPA #10. They shall bear the label of an approved agency and be of an approved type.
4. Fire alarm system shall be maintained to NFPA #72 standards.
5. The fire protection system shall be maintained to NFPA #13.
6. An area of refuse shall be provided as per NFPA and the city's building code (BOCA National Building Code/1993).
7. The fire alarm system shall be maintained to NFPA #14 standards.

Sincerely,


F. Samuel Hoffses
Chief of Inspection Services

cc: LT Mc Dougall, Fire Prevention Bureau