

GENERAL PLAN NOTES:

- 01. AN ARCHITECTURAL SITE VISIT TO FIELD MEASURE AND VERIFY EXISTING CONDITIONS OF THE BUILDING WAS CONDUCTED ON AUGUST 1, 2014.
- 02. ALL EFFORTS HAVE BEEN MADE TO PROVIDE A COMPREHENSIVE DOCUMENTATION OF THE EXISTING BUILDING. SOME INTERIOR FINISHES AND ITEMS ARE CONCEALED AND HAVE BEEN A CHALLENGE TO DOCUMENT. IT IS POSSIBLE THAT DEFICIENCIES MAY EXIST WHICH ARE NOT IDENTIFIED IN THESE DRAWINGS.
- 03. IT IS POSSIBLE CONDITIONS MAY CHANGE DURING THE INTERIM PERIOD BETWEEN THE DATE OF THE INSPECTION AND COMPLETION OF THE PROJECT. 2A ARCHITECTS ASSUMES NO RESPONSIBILITY FOR ANY UNIDENTIFIED DEFICIENCIES OR CHANGES IN THE CONDITION OF THE BUILDING ANYTIME AFTER THE DATE OF THE INSPECTION.
- 04. CONTRACTOR TO VERIFY ALL EXISTING DIMENSIONS AND CONDITIONS AFTER REVIEWING PROPOSED REVISIONS. NOTIFY ARCHITECT OF ANY DISCREPANCIES.
- 05. ALL CHANGES ARE ANTICIPATED TO BE NON-STRUCTURAL. NOTIFY ARCHITECT/ENGINEER OF ALL STRUCTURAL CONDITIONS IDENTIFIED DURING DEMOLITION FOR DIRECTION / RESOLUTION.

SYMBOL LEGEND

ROOM-	ROOM NAME
C: 000 —	CEILING MATERIAL
F: 000——	FLOORING MATERIAL
(FP.00)	KEY PLAN REFERENCE NUMBER
€ +8'−5"	CEILING HEIGHT ABOVE FINISH FLOOR
$W^w \times H^h$	DOOR OR WINDOW SIZE
W X H	WIDTH X HEIGHT (IN FEET & INCHES)
EXST	EXISTING DOOR (NO CHANGES)
000	DOOR REFERENCE NUMBER FOR NEW DOOR
<u>^</u>	WALL TYPE REFERENCE NUMBER
EXST	EXISTING WINDOW (NO CHANGES)
EF	RECESSED EXHAUST FAN (VENT TO EXTERIOR)
RS	INDICATES ADA COMPLIANT ROOM SIGNAGE W/ BRAILLE CHARACTERS
	,

BACKUP & COMBINATION EMERGENCY LIGHTS. SEE FLOOR PLAN FOR LOCATIONS.

EXISTING EXIT SIGN W/ EMERGENCY LIGHTS

INDICATES EMERGENCY LIGHTING (NOT INTEGRAL TO COMBINATION EXIT LIGHTS) W/ BATTERY BACKUP

INDICATES (E) FIRE EXTINGUISHER IN SEMI RECESSED CABINET OR SURFACE MOUNTED. INSPECT/ TEST TO VERIFY IN WORKING ORDER.

(E) WALL OR CEILING MOUNTED SMOKE DETECTOR (VERIFY)

	(E) WALL CONSTRUCTION
	NEW WOOD FRAMED WALL CONSTRUCTION
	INDICATES RATED / SEPARATION WALL

- 5/8" TYPE 'X' DRYWALL (EA. SIDE), 2X4 WOOD STUDS @ 16" O.C. & INSTALL PER U.L. INSTRUCTIONS TO UNDERSIDE OF FRAMING ABOVE. NOTE: PROVIDE (2) LAYERS OF \$" TYPE 'X' DRYWALL ON ONE SIDE, IF OPPOSITE SIDE IS NOT ACCESSIBLE (I.E. NEW KNEE WALL UNDER (E) STAIR) (2x6 WALL STUDS AT "1A" LOCATIONS — GA 3660)
- WALL ASSEMBLY: PATCH/ REPAIR (E) 1/2" LATH & PLASTER (VERIFY) OR ADD \(\frac{8}{2} \) TYPE 'X' DRYWALL, (E) WOOD STUDS/ STRAPPING & INSULATION (UNKNOWN), (E) MASONRY LOAD

FLOOR PLAN KEYNOTES:

- (FP.02) REMOVE (E) PARTIAL WALL BELOW (E) STAIR FOR NEW CONNECTION HALL TO (E) LOBBY. NOTIFY ARCHITECT IF
- (FP.03) SLOPED THRESHOLD TO MAKE UP FLOOR HEIGHT DIFFERENCE
- (FP.04) REMOVE (E) TRIM & INFILL (E) OPENING TO MATCH ADJACENT MATERIALS / FINISHES.
- (E) LIGHTED EXIT SIGN TO REMAIN
- (FP.08) REMOVE (E) FINISHES AS REQUIRED FOR NEW DOOR OR RATED WALL INFILL. PATCH & REPAIR AS REQUIRED. ALL
- PER SCHEDULE. PATCH & REPAIR AS REQUIRED. REUSE OR REPLACE ALL TRIM & FINISHES TO MATCH ADJACENT WALL
- FP.10 REMOVE (E) EXIT SIGN AND REPLACE WITH NEW EMERGENCY LIGHT.
- HINGES. PROVIDE SIGN ON WALL TO READ "NOT AN EXIT" FP.12 (E) PLUMBING CHASE TO REMAIN (VERIFY)
- THAN 3" DIFFERENCE. NO HANDRAILS REQUIRED. (E) STORAGE W/ DRYWALL CEILING BELOW (E) STAIRS TO REMAIN
- REUSE / MATCH (E) TRIM
- AT 34" ABOVE NOSING OF TREADS. EXTENSIONS NOT / EMERGENCY LIGHT.
- (FP.19) AT CEILING, TO ACHIEVE FIRE-RATING, OPTION 1: PATCH ANY MISSING AREAS OF EXISTING PLASTER ON UNDERSIDE OF FLOOR JOISTS ABOVE LAY-IN CEILING. OPTION 2: LAY-IN CEILING SYSTEM TO COMPLY WITH DETAIL 4/A7.0.



architects, Ilc

724 Rockland Street (Office) P.O. Box 189 (Mailing) Rockport, Maine 04856

Tel: 207.236.6545 Web: www.2Aarch.com

©Copyright 2010, 2A architects II

Registration:

S

0

Consultant:

INDICATES HARDWIRED ILLUMINATED EXIT SIGN W/ BATTERY

INDICATES (E) EMERGENCY LIGHTING TO REMAIN

WALL SYMBOL LEGEND

	(E) WALL CONSTRUCTION
	NEW WOOD FRAMED WALL CONSTRUCTION
	INDICATES RATED / SEPARATION WALL

- NEW RATED WALL ASSEMBLY: GA NO. 3520
- WALL ASSEMBLY: (E) PLASTER & LATH EA. SIDE (VERIFY) ON (E) WOOD STUDS. (1-HOUR EQUIVALENT ASSEMBLY)
- BEARING EXTERIOR WALL.

- (E) SINK BASE & ASSOCIATED ITEMS TO BE REMOVED TO REWORK EGRESS HALL. VERIFY W/ TENANT RE: RELOCATION. LOAD-BEARING.
- (NOTIFY ARCHITECT OF HT DIFFERENCE).
- (FP.05) REMOVE (E) INSWING DOOR & ASSOCIATED ITEMS, PREP FOR
- FP.06 REMOVE (E) EXIT SIGN OR EMERGENCY LIGHT & ASSOCIATED ITEMS, PATCH & REPAIR AS REQ'D
- TRIM & FINISHES TO MATCH ADJACENT WALL SURFACES. (AT NEW DOOR, STRUCTURAL IMPRACTIBILITY PREVENTS FULL DOOR MANEUVERING CLEARANCE. ADA 6.402(B)(c) (FP.09) REMOVE (E) DOOR & ASSOCIATED ITEMS FOR RATED DOOR
- FP.11 ADD 42" HIGH STEEL FRAME GATE W/ SELF CLOSING
- INTERIOR ADA RAMP (MAX 1:8 SLOPE) TO MAKE UP (FP.13) DIFFERENCE IN FLOOR HEIGHT. NOTIFY ARCHITECT IF MORE
- (FP.15) ENLARGE (E) CASED OPENING TO BE 32" CLEAR OPENING, FP.16 ADD SLOPED STONE THRESHOLD TO FILL (E) GAP IN FLOOR
- (FP.17) EXISTING STEPS TO REMAIN. INSTALL HANDRAIL EACH SIDE REQUIRED PER IBC 3404.1(2). (GUARDRAIL NOT REQD. AT STAIRS LESS THAN 30" A.F.F. PER NFPA 7.1.8 / IBC 1013.1) (FP.18) REPLACE EXISTING EMERGENCY LIGHT WITH A COMBO EXIT

Pre-App. Meeting 11/3/14 12/15/14 **Client Record** 3/13/15 Prelim. Pricing 06/08/15 Permit Submittal Project Start Date: August 2014 Project Number: 14-119

> **FOURTH FLOOR PLAN**

06/10/2015 A3.2_767Congress_4thFlr.dw