



Mercy on the Fore Hardware Specification Notes:

General Notes:

All numbering needs to be revised as per on arch plans and schedule

- 1) Opening numbers that are duplicated on plans (Manually changed back, will have to do again for every update, still concerned this will cause confusion during construction).
G001B swing door is G001BA on Hardware
G001B overhead gate is G001BB on Hardware
G030C on door schedule is G030CA on Hardware
G030c on door schedule is G030CB on Hardware
G040a on door schedule is G040AA on Hardware
G040A on door schedule is G040AB on Hardware
1024a on door schedule is 1024AA on Hardware
1024A on door schedule is 1024AB on Hardware
1024B on door schedule is 1024BA on Hardware
1024b on door schedule is 1024BB on Hardware
1046a on door schedule is 1046AA on Hardware
1046A on door schedule is 1046AB on Hardware
1046b on door schedule is 1046BA on Hardware
1046B on door schedule is 1046BB on Hardware
1047a on door schedule is 1047AA on Hardware
1047A on door schedule is 1047AB on Hardware
1047b on door schedule is 1047BA on Hardware
1047B on door schedule is 1047BB Hardware
- 2) Opening ST01, listed as ST1 on plans. Used ST01 on Hardware Specification. Correct to use ST01
- 3) Why do some electrical rooms card access while others are not? No need for doors electric
- 4) Why would we have card access on only some of the employee lounges? Only at Lab and Pharmacy
- 5) Need to review toilet room hardware. Thought most of the toilets were changing to emergency egress out swing. Most of these openings still are shown as inswing only on plans. All should have emergency egress swing,
Unable to supply fire or smoke rating for opening 1033 if emergency egress hardware
Opening 1065A is to be lead lined, can't have emergency egress hardware and have lead lined.
Assumed toilet rooms inside patient rooms to remain as is, with no emergency egress hardware since they are shown as outswing doors. (HW-58).
Some of these toilets are in staff areas, but have changed to emergency egress hardware as requested.
- 6) Do openings 1061 and 1065 need to be fire rated? Not required. OK

Schlage
Von Duprin
LCN
Steelcraft
Glynn-Johnson
Recognition Systems
Locknetics
Falcon
Monarch
Dor-O-Matic
Ives

- 7) If openings 1061 and 1065 are fire rated why don't we have a fire rating on 1064? [Not required.](#) [OK](#)
- 8) Do we need a bathroom interlock at 1058AA and 1058AB? [Yes.](#) [New set HW-64](#)
- 9) On what wall is opening GE02A? Electrical and Arch. Show different. [Use Architectural numbering](#) [OK](#)
- 10) Thought security hardware at openings G040B and G040C was to be moved to GX050 and GX070C? [Correct](#) [OK](#)
- 11) Do we have an answer on special hardware at 1002 and 1003? [Do a classroom function](#)
- 12) Please verify that doors such as 1027B require no hardware other than that supplied by the laundry chute manufacturer. [Correct](#) [OK](#)
- 13) Need to review electrified hardware requirements with Electrical Engineer. See attached excel spreadsheets to see these issues. [Do it.](#)
- 14) Why have a card reader at 2011, but not at 2012 as well? [Card both](#) [OK](#)
- 15) Why card reader at 3X100, but not at 3X080? Both set HW-96 on Hardware. [OK](#)
- 16) Why "HUG" Infant abduction. Locking hardware required for doors going into third floor. Since these doors are double egress would the requirement only be for the egress door? [Clarify.](#) [Not privy to any security discussions re hug.](#)
- 17) Opening G042 why on access control system? Why electrify both doors? Hardware specified (HW-03) is not electrified, please clarify. [No access control required](#) [OK](#)
- 18) Suggest opening 3001A and 3001B swing toward conference 3051 instead of waiting 3001. [Please clarify.](#) [Swing already corrected on latest drawings](#)
- 19) Would suggest changing swing of GE01 to swing out of Emergency Elect. Room. [OK](#)
- 20) Are closets 1024C, or 4011 to be locked? [1024C—No](#) [OK, what about 4011?](#)
- 21) Do we have an opening 2054? It is on door schedules, but am unable to locate on any of the plans. [Deleted](#) [OK](#)
- 22) Opening 2080C as shown on plans renumbered to 2X080C to match door schedule. [OK](#)
- 23) Please verify use of door 3110 from roof. [Staff access only](#) [OK](#)
- 24) Unable to locate 4X100C on plans. [Anteroom between S4X100D and S4X100A pair of inswing double doors right on Column Line D](#)

[New set HW-65, need to review hardware requirements.](#)



John Gant, AHC, CCPR
Hardware Consultant