



85 MORNING ST
 CURRENTLY HAS TWO MEANS OF
 EGRESS INSIDE THE BUILDING
 AND DOES NOT REQUIRE EXTERIOR
 STAIRS