

Permitting and Inspections Department Michael A. Russell, MS, Director

November 15, 2017

BEDARD COLLEEN C PO BOX 4566 PORTLAND, ME 04112

CBL: 003 F009001

Located at: 20 MORNING ST

Certified Mail 70141820000140495136

Dear BEDARD COLLEEN C,

An evaluation of the above-referenced property on 11/15/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 12/20/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Kevin Hanscombe

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager BEDARD COLLEEN C		Inspector Kevin Hanscombe	Inspection Date 11/15/2017
20 MORNING ST	003 F009001	Violations Exist	Housing Safety Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 207

Violation: CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings:

Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on

walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes: Missing 1st 2nd and 3rd floor, Recommendation was made to replace existing hardwired smoke alarms

with combination alarms including basement.

2) 211

Violation: OTHER

Notes: Egress window 3rd floor living area.

3) 211

Violation: OTHER

Notes: junction box missing cover and various hanging wires need to be addressed.

Comments: