CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
STEPHENS CLARK B		Suzanne Hunt	11/21/2008
Locatation	CBL	Status	Inspection Type
31 OXFORD ST	013 B007001	Re-Inspect 10 Days	Complaint-Housing Inspection

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date	
1)	6-108.b	Interior	2	2	Bedroom		
,	Violation:	Interior floors, walls, ceilings and doors					
	Notes:	doors must be good repair. Repair broken	interior bed	room door			
2)	6-108.b	Interior	2	2			
	Violation:	Interior floors, walls, ceilings and doors					
	Notes:	missing and broken floor tiles must be repaired/replaced/					
3)	6-108.b	Interior	2	2	Bedroom		
	Violation:	Interior floors, walls, ceilings and doors					
	Notes:	ceiling cracks must be repaired					
4)	6-108.b	Interior	2	2			
٠,							
',	Violation:	Interior floors, walls, ceilings and doors					
	Violation: Notes:	Interior floors, walls, ceilings and doors 2nd egress door must be made structurally with caulking.	/ vermin pro	oof, air tight to	hallway. This	s door cannot be seale	
5)		2nd egress door must be made structurally	/ vermin pro	oof, air tight to	hallway. This	s door cannot be seale	
	Notes:	2nd egress door must be made structurally with caulking.			hallway. This	s door cannot be seale	
	Notes: 6-108.c	2nd egress door must be made structurally with caulking. Interior	2	2	hallway. This	s door cannot be seale	
	Notes: 6-108.c Violation:	2nd egress door must be made structurally with caulking. Interior Exterior windows, doors and skylights	2	2	o hallway. This		
5)	Notes: 6-108.c Violation: Notes:	2nd egress door must be made structurally with caulking. Interior Exterior windows, doors and skylights All exterior windows must be weather and	2 I water tight	2	,		
5)	Notes: 6-108.c Violation: Notes: 6-108.f	2nd egress door must be made structurally with caulking. Interior Exterior windows, doors and skylights All exterior windows must be weather and	2 I water tight 2	2	,		
5)	Notes: 6-108.c Violation: Notes: 6-108.f Violation:	2nd egress door must be made structurally with caulking. Interior Exterior windows, doors and skylights All exterior windows must be weather and Interior Required equipment and utilities	2 I water tight 2	2	,		
5)	Notes: 6-108.c Violation: Notes: 6-108.f Violation: Notes:	2nd egress door must be made structurally with caulking. Interior Exterior windows, doors and skylights All exterior windows must be weather and Interior Required equipment and utilities radiator covers must be working, attached	2 I water tight 2 , functionin	2 2 g safely.	Various loca		
5)	Notes: 6-108.c Violation: Notes: 6-108.f Violation: Notes: 6-108.b	2nd egress door must be made structurally with caulking. Interior Exterior windows, doors and skylights All exterior windows must be weather and Interior Required equipment and utilities radiator covers must be working, attached	2 I water tight 2 , functionin	2 2 ag safely.	Various loca	ations	
5)	Notes: 6-108.c Violation: Notes: 6-108.f Violation: Notes: 6-108.b Violation:	2nd egress door must be made structurally with caulking. Interior Exterior windows, doors and skylights All exterior windows must be weather and Interior Required equipment and utilities radiator covers must be working, attached Interior Interior floors, walls, ceilings and doors Walls in bathroom must be structurally soo	2 I water tight 2 , functionin	2 2 ag safely.	Various loca	ations	
5) 6) 7)	Notes: 6-108.c Violation: Notes: 6-108.f Violation: Notes: 6-108.b Violation: Notes:	2nd egress door must be made structurally with caulking. Interior Exterior windows, doors and skylights All exterior windows must be weather and Interior Required equipment and utilities radiator covers must be working, attached Interior Interior floors, walls, ceilings and doors Walls in bathroom must be structurally soon needs to fully enclosed (sheathed)	2 d water tight 2 , functionin 2 und. Air tigh	2 2 ag safely. 2 at, vermin pro	Various loca	ations	

Comments: