

Permitting and Inspections Department Michael A. Russell, MS, Director

March 12, 2018

MELNICK SPENCER J & 30 CHASE ST SOUTH PORTLAND, ME 04106

CBL: 013 D009001

Located at: 20 CLEEVES ST

Certified Mail 7015 0920 0001 0776 6430

Dear MELNICK SPENCER J &,

An evaluation of the above-referenced property on 02/16/2018 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 04/12/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Matt Sarapas

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager				Inspector		Inspection Date		
MELNICK SPENCER J &				Matt Sarapas		2/16/2018		
Location		CBL		Status		Inspection Type		
20 CLEEVES ST		013 D009001		Failed		Housing Inspection		
Code	In	t/Ext	Floor	Unit No.	Area	Compliance Date		
1) 55.005								
Violation:	NFPA 101- 31.2.1.1 ESCAPE WINDOWS - INSUFF. SIZE; It shall be an outside window or door operable from the inside without the use of tools, keys, or special effort and shall provide a clear opening of not less than 5.7 square feet. The width shall be not less than 20 inches, and the height shall be not less than 24 inches. The bottom of the opening shall not be more than 44 inches above the floor. See NFPA 101 24.2.2.3.3 for a continuation of this code.							
Notes:	Third floor bedrooms lack compliant egress/escape windows.							
2) 55.047								
Violation:	NFPA 101- 7.1.3.2.1 60-MIN FIRE DOOR ASSEMBLIES REQ; THE SEPARATION SHALL HAVE A MINIMUM 1-HOUR FIRE RESISTANCE RATING WHERE THE EXIT CONNECTS THREE OR FEWER STORIES.							
Notes:	All unit entry doors and basement door must be self closing 60 minute fire rated doors. On first floor, second door into unit may be removed and clsoed in with fire rated drywall on both sides.							
3) 55.05								
Violation:	appliances use	ed to init	iate or dire	ct action, eva	cuation or r	nance, location, and mounting of notification elocation of the occupants, or for providing quirements of Chapter 6.		
Notes:	Basement requires hardwired carbon monoxide alarm. Combination smoke/co alarm is acceptable provided that it is of the photoelectric type.							
4) 55.164								
Violation:	NFPA 72- 5.5.2.1 SMOKE DETECTORS ON ALL FLOOR LEVELS; If required and unless otherwise modified by 5.5.2.1.1 through 5.5.2.1.5, total coverage shall include all rooms, halls, storage areas, basements, attics, lofts, spaces above suspended ceilings, and other subdivisions and accessible spaces as well as the inside of all closets, elevator shafts, enclosed stairways, dumbwaiter shafts, and chutes.							
Notes:	Basement requires hardwired smoke alarm. Combination smoke/co alarm is acceptable provided that is of the photoelectric type.							
5) 55.088								
Violation:	NFPA 70 PLUG OPENINGS IN FUSE PANEL; REFER TO NFPA 70, NATIONAL ELECTRICAL CODE, REGARDING PLUGGING OPEN FUSES IN PANELS.							
Notes:	Panel #2 & #3 require blanks in open breaker openings.							
6) 55.083								
Violation:	NFPA 70 JUNCTION BOXES REQUIRE COVERS; REFER TO NFPA 70, NATIONAL ELECTRICAL							

CODE, ON STANDARDS REGARDING JUNCTION BOXES REQUIRING COVERS.

Notes:

Throughout basement

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
MELNICK SPENCER J	. &	Matt Sarapas	2/16/2018
Location	CBL	Status	Inspection Type
20 CLEEVES ST	013 D009001	Failed	Housing Inspection

7) 55.530

Violation:

CITY OF PORTLAND RULES AND REGS- CHAPTER 4.6 LABEL UNIT DOORS; 4.6 Commercial suites shall be designated as approved by the FD. In single floor buildings letter designations shall be acceptable.

4.6.1 Residential units shall be designated using numericals.

4.6.2 The first numerical of each residential unit shall be the floor designation.

4.6.3 In single floor buildings the floor designation shall be omitted.

Notes:

8) 3.011

Violation:

NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; THE AREAS DESCRIBED IN TABLE

31.3.2.1.1 SHALL BE PROTECTED AS INDICATED:

BOILER AND FUEL-FIRED HEATER ROOMS SERVING MORE THAN A SINGLE DWELLING UNIT

(MINIMUM SEPARATION/PROTECTION IS 1 HOUR OR SPRINKLERS)

Notes:

Sprinkler protection required over fuel fired appliances in basement

9) 55.040

Violation:

NFPA 101- 31.3.1.1 VERTICAL OPENING VIOLATIONS; VERTICAL OPENINGS SHALL COMPLY

WITH 31.3.1.1.1 THROUGH 31.3.1.2.

Notes: Ceiling and basement stairs requires repair to be 1 hour fire rated.

10) 55.300

Violation: NF

NFPA 101- 31.2.2.2.2.1 DOORS LOCKED AGAINST EGRESS; NO DOOR IN ANY MEANS OF

EGRESS SHALL BE LOCKED AGAINST EGRESS WHEN THE BUILDING IS OCCUPIED.

Notes:

11) 10.002

Violation: NFPA 10- 7.1.1 FIRE EXTINGUISHERS NEED ANNUAL SERVICE; THE OWNER OR DESIGNATED

AGENT OR OCCUPANT OF A PROPERTY IN WHICH FIRE EXTINGUISHERS ARE LOCATED

SHALL BE RESPONSIBLE FOR INSPECTION, MAINTENANCE, AND RECHARGING.

Notes:

12) 80.60

Violation: NFPA 101- 7.2.1.5.2 ILLEGAL LOCKS ON EXIT DOOR; LOCKS, IF PROVIDED, SHALL NOT

REQUIRE THE USE OF A KEY, A TOOL, OR SPECIAL KNOWLEDGE OR EFFORT FOR

OPERATION FROM THE EGRESS SIDE.

Notes: Locks that require two hands to operate are prohibited and must be removed and replaced with

compliant locks immediately.

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
MELNICK SPENCER J	&	Matt Sarapas	2/16/2018
Location	CBL	Status	Inspection Type
20 CLEEVES ST	013 D009001	Failed	Housing Inspection

13) 80.52

Violation:

NFPA 101- 7.2.8.6.2 FIRE ESCAPE REQUIRES REPAIR; THE AUTHORITY HAVING JURISDICTION

SHALL BE PERMITTED TO APPROVE ANY EXISTING FIRE ESCAPE STAIR THAT HAS BEEN

SHOWN BY LOAD TEST OR OTHER SATISFACTORY EVIDENCE TO HAVE ADEQUATE

STRENGTH.

Notes:

Licensed design professional must certify that existing metal fire escape stair is structurally sound -

drop down stair is presently secured with a cargo strap.

Comments: