



3RD

SISTEROOD FLOOR DIST DUE TO SPLITTING



2ND



1ST

ALL WORK WAS INSPECTED BY ANDREW JONES AT STRUCTURAL INTEGRITY + RECOMMENDED