CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

Location	CBL	Inspection Date	
62 MONUMENT ST	017 E001001	3/16/2016	
Inspector	Inspection Type	Status	
Alan Greene	FP Routine Inspection	Failed	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
N.F.P.A.101- CHAPTER 8.6.2 & 8.6.8 VERTICLE OPENINGS SHALL BE ENCLOSED OR PROTECTED; EVERY VERTICAL OPENING BETWEEN THE FLOORS OF A BUILDING SHALL BE SUITABLY ENCLOSED OR PROTECTED, AS NECESSARY, TO PROVIDE THE FOLLOWING: (1) REASONABLE SAFETY TO OCCUPANTS WHILE USING THE MEANS OF EGRESS BY PREVENTING THE SPREAD OF FIRE, SMOKE, OR FUMES THROUGH VERTICAL OPENINGS FROM FLOOR TO FLOOR TO ALLOW OCCUPANTS TO COMPLETE THEIR USE OF THE MEANS OF EGRESS; (2) LIMITATION OF DAMAGE TO THE BUILDINGS AND ITS CONTENTS. Rear hallway, 1st floor. No sheet ock on ceiling, multiple holes in wall with wires.	//
NFPA 80- ANNEX D.4 1-HOUR FIRE DOORS ASSEMBLIES REQ; Listings are provided for floor fire door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have been tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 square feet of floor or ceiling.	//
NFPA 72- 10.2.1.2.2 SMOKE DETECTOR NEEDS REPAIR; System defects and malfunctions shall be corrected. Multiple detector in basement. Battery operated must be maintained or removed, appears there is both hardwired and battery detectors.	//
NFPA 30 CLASS 1 LIQUID VIOLATION ; Refer to NFPA 30. Must meet NFPA 385 Standard for Tank Vehicles for Flammable and Combustible Liquids. Gas can in basement	//

Violation		Proposed Date of Completion
FINAL DATE OF COMPLETE	D VIOLATION(S)	· / / /
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	t to reject or modify any proposed plan of action, and may nical capacity to complete the proposed plan. Please contact TION	-
understand that I must conta	ons listed within the timeframes provided. If I require add act the Fire Prevention Bureau <u>prior to the deadline</u> to requ's discretion to grant or deny.	
v	is my responsibility to schedule a reinspection of my prope . My failure to schedule a reinspection shall be deemed an nedied.	•
	greement, I understand that I am liable for penalties pursurs $\{s, s, s, 1-15\}$ and 10-25, and 30-A M.R.S. $\{s, s, s$	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		

Fire Prevention Bureau

Date