Portland, Maine



Yes. Life's good here.

Danielle P. West-Chuhta Corporation Counsel

Anne M. Torregrossa Associate Counsel Michael I. Goldman Associate Counsel

July 15, 2016

NOTICE OF INTENT TO PROSECUTE

Katherine J. Palmer 70 Waterville Street Portland, Maine 04101

RE:

70 Waterville Street

CBL017 E004001

To Whom it May Concern,

Please see the attached Inspection Violations. The City of Portland Fire Department has referred this matter to me for prosecution. In order to avoid prosecution, you must submit to Fire Prevention Bureau a plan of action to remedy the violations no later than **July 29, 2016**.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION WITHIN THE TIMEFRAME PROVIDED WILL RESULT IN LEGAL ACTION AND THE IMPOSITION OF CIVIL PENALTIES.

Please feel free to contact Tori Ross of the Fire Prevention Bureau at (207)874-8400 with any questions. I look forward to your anticipated cooperation and appreciate your efforts to help keep the citizens of Portland safe.

Sincerely,


Anne M. Torregrossa

Associate Corporation Coursel

City of Portland

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101



Inspection Violations

Owner/Manager Palmer Katherine J				Inspector		Inspection Date
				Daniel Small		6/24/2016
Location CBL			Status		Inspection Type	
0070 WA	TERVILLE ST	017 E004001		Failed		Fire Company-FP Routine Inspec
Code	ln	t/Ext	Floor	Unit No.	Area	Compliance Date
1) 69.25						
Violation:	PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 RESIDENTIAL UNITS SHALL BE DESIGNATED USING NUMERALS.					
	4.6.2 THE FIR	ST NUM	MERAL OF	EACH RESI	DENTIAL UI	NIT SHALL BE THE FLOOR DESIGNATION.
Notes:						
2) 73.15						
Violation:	NFPA 101- 31 ENCLOSED O					RATED; VERTICAL OPENINGS SHALL BE SECTION 8.6.
Notes:	PLYWOOD W	ALLS, E	BREACHES	FRONT STA	AIRS, WOO	D DOOR IN WALL
3) 80.24						
Violation:	NFPA 101-7.2.1.4.5 (3) EXIT DOOR OPENING FORCE EXCEEDS 50 LBS.; THE OPENING FORCES FOR EXISTING DOOR LEAVES IN EXISTING BUILDINGS SHALL NOT EXCEED 50 LBS (222 N) APPLIED TO THE LATCH STILE.					
Notes:	REAR STAIRWAY EXIT DOOR REQUIRES EXCESSIVE FORCE TO OPEN					
4) 89.05						
Violation:	NFPA 1 EXCESSIVE/DISORDERLY STORAGE; REFERENCE NFPA 1 FOR EXCESSIVE FUEL-LOAD.					
Notes:	STORAGE IN	STAIRV	VAYS			
5) 3.011						
Violation:	NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; THE AREAS DESCRIBED IN TABLE 31.3.2.1.1 SHALL BE PROTECTED AS INDICATED: BOILER AND FUEL-FIRED HEATER ROOMS SERVING MORE THAN A SINGLE DWELLING UNIT (MINIMUM SEPARATION/PROTECTION IS 1 HOUR OR SPRINKLERS)					

Comments:

Notes: