

# INSPECTION REPORT

CUSTOMER: S.W. COLE			PAGE 1 OF 1
ADDRESS: 127 FORE ST PORTLAND MAINE			
ATTENTION: CARL			
COPIES:			
PROJECT:			
OWNER:			
CONTRACTOR:			
JOB No.: 06-0726.2	REPORT No.: QAL-08-0719	P. O. NUMBER: VERBAL	DATE INSPECTED: 04-17-08

**REMARKS**


AN ULTRASONIC INSPECTION WAS PERFORMED USING AWS D1.1

PILE # 204  
 PILE SIZE# 1057  
 JOB # 06-0726.2

NO INDICATIONS WERE NOTED AT TIME OF INSPECTION.

/// LAST ITEM ///

**FAA REPAIR STATION NUMBER RX5R187N**  
 METHOD(S),PROCESS(ES),PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED:				<input type="checkbox"/> SKETCHES	<input type="checkbox"/> SUPPLEMENTARY SHEET(S)	<input type="checkbox"/> NDI REPORTS	<input type="checkbox"/> VIDEO	
<b>SIGNATURES</b>				<b>CERTIFICATION</b>		<b>DATE</b>		
INSPECTOR	S. DYER			ASNT	II	04	17	08
SUPERVISOR								