



PHOTO
1002.1
1002 004.jpg

Carriage House Rear Wall: Subgrade preparation immediately after removing center pier from below timber girder.



PHOTO
1002.2
1002 010.jpg

Carriage House Rear Wall: Filter fabric and crushed stone in place, prior to crushed stone compaction.



PHOTO
1002.3
1002 005.jpg

Carriage House Rear Wall: Crushed stone bed, prior to compaction and placing concrete.



PHOTO
1002.4
1002 008.jpg

Carriage House Rear Wall: Photo showing 38 ½" depth from top of crushed stone to bottom of girder.