



PHOTO
1114.1
1114 001.jpg

Center-East Wall: Formwork and rebar cages in place on compacted fill just over clay subgrade. Note tower in upper left background. Bottom of footing 4'-0 below grade.



PHOTO
1114.2
1114 002.jpg

Center-East Wall: View looking north showing reinforcement and dowels.