



At Door 200.4, provide and install new 2 hour rated door, frame and sidelites equal to FireLite Plus as manufactured by Technical Glass Products to replace existing door pair. Door to swing out to garage

OTHER DOOR/ HARDWARE CHANGES

1. At existing door pair 200.4, provide H.C. operator to operate the right hand leaf only.
2. Door 140 was discussed in our hardware meeting on 11/2. The owner has decided NOT to add a card reader to this door so this door remains as scheduled w/ no change