CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
HUCKSTER'S ROW PROPERTIES LLC		Suzanne Hunt	9/8/2010
Locatation	CBL	Status	Inspection Type
316 CONGRESS ST	028 C002001	Re-Inspect 14 Days	Complaint-Inspection

1) 6-108.(d) Exterior
 Violation: Stairways, stairwells, stairs and porches.
 Notes: Stairways, stairwells, stairs and porches. Every inside and outside stairway, stairwell, stairs, and porch and any appurtenances thereto shall be structurally sound, in good repair, and safe to use. The Exterior stairs leading to third story are not structurally sound, have missing ballusters, and a split stringer running from level 3 to 2.

Floor

Unit No.

Area

Compliance Date

2) 6-116.(b)

Code

Violation: Egress

Notes: The excavation in back yard must be filled. This excavation covered with piece of plywood is creating

a hazard. The excavation areas does not provide a safe or open areas for emergency egress.

Excavation is a hazard to emergency egress.

3) 6-116.(b)

Violation: Egress

Notes: The exterior egress is not in good repair. The Exterior stairs leading to third story are not structurally

sound, have missing ballusters, and a split stringer running from level 3 to 2. The stairs shake when

walked on.

Int/Ext

Comments: The 4/10 excavation in back yard is not backfilled. There is a piece of plywood covering the "hole".

The back steps to store front have not been replaced. The exterior egress from floor 3 to 2 is deteriorating. The Stair Stringer is split; there are missing balusters, and the entire section from 2 to 3 shakes. The back steps to store front have not been replaced. Replacement of stairs requires a

permit. Litter and debris are accumulating under stairs and around perimeter of building.