



25 CUSTON HOUSE WHARF PORTLAND, MAINE 04101

EXISTING CONDITIONS SURVEY AND PROPOSED NEW CONSTRUCTION SEABAGS









DOOR SCHEDULE

Door	Location	Style	Door				Frame				Hardware	Key	Remarks
No.			Width	Height	Material	Elev.	Material	Head	Jamb	Elev.		Set	
E1	ENTRY DOOR	EXISTING-EXTERIOR	2'-8"	EXIST.			EXIST.						
2	CLOSET	EXISTING-WOOD BIFOLD	3'-0"	EXIST.			EXIST.						
E3	LANDING	EXISTING-PAIRED EXTERIOR WOOD	7'-6"	EXIST			EXIST.						
Ξ4	CLOSET	EXISTING-PRESSED METAL	2'-6"	EXIST.			EXIST.						
5	TOILET	EXISTING-PRESSED METAL	2'-6"	EXIST			EXIST.						
E 6	OFFICE	EXISTING	3'-0"	EXIST.			EXIST.						
E7	WORK SPACE	EXISTING-PAIRED EXTERIOR	5'-10"	EXIST.			EXIST.						
						_				-			
E10	ROOF DECK	EXISTING-PAIRED INSWING	5'-10"	EXIST.									
E11	OFFICE	EXISTING	2'-8"	EXIST.									
E12	OFFICE	EXIST.	EXIST	EXIST			EXIST.						
E13	TOILET	EXIST.					EXIST.						
E14	CLOSET	EXIST.	EXIST.	EXIST.	EXIST.		EXIST.						
E15	STORAGE	EXIST.	EXIST.	EXIST.	EXIST.		EXIST.						
E16	LOBBY	EXISTING-PRESSED METAL											
017	OFFICE	PROPOSED INSWING	3'-0"	7'-0"	SC WOOD		НМ		PROPOSED INSWING SOLID CORE WOOD VENER DOOR IN HOLLOW METAL FRAME				
018	OFFICE	PROPOSED INSWING	3'-0"	7'-0"	SC WOOD		НМ		PROPOSED INSWING SOLID CORE WOOD VENER DOOR IN HOLLOW METAL FRAME				
019	OFFICE	PROPOSED INSWING	3'-0"	7'-0"	SC WOOD		НМ		PROPOSED INSWING SOLID CORE WOOD VENER DOOR IN HOLLOW METAL FRAME				
018	SOUTH STAIR	PROPOSED PAIRED	6'-0"	7'-0"	SC WOOD		НМ		PROPOSED ONE HOUR RATED SOLID CORE WOOD VENER DOOR IN HOLLOW METAL FRAME				

