



PILE LAYOUT DATA

PILE	EXISTING	NORTHING
1	5008.6899	4996.1742
18	5001.8989	5196.7637
20	4988.0819	4999.9270
21	4986.7549	5025.5086
29	4988.6301	5139.2897
30	4986.1921	5141.8309
34	4987.0938	5195.9983

- NOTES:**
- ELEVATIONS ARE BASED ON MEAN LOW WATER DATUM. DATUM ESTABLISHED BY SURVEYING THE TIDE GATE AT THE MOUTH OF THE RIVER AND ADJUSTING FOR ONLY ELEVATION.
 - HISTORIC INFORMATION AND STONE SEAWALL DEPICTED WAS COMPILED FROM A DRAWING TITLED "PROPOSED REPAIRS TO THE SEAWALL AT UNION WHARF, PORTLAND, MAINE". PLAN SHOWN ARE IN APPROXIMATE LOCATION ONLY.



PROPRIETORS OF UNION WHARF
 PORTLAND, MAINE

UNION WHARF PILE REPAIR
 SITE LAYOUT

TEC ASSOCIATES
 CONSULTING ENGINEERS

SCALE: 1/8" = 1'
 DATE: 1/13/2017