CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

| Owner/Manager | | Inspector | Inspection Date |
|----------------|-------------|--------------|----------------------|
| BELLINO MARY R | | Tammy Munson | 6/22/2010 |
| Locatation | CBL | Status | Inspection Type |
| 10 MOTLEY ST | 177 F005001 | | Complaint-Inspection |

| | Code | Int/Ext | Floor | Unit No. | Area | Compliance Date |
|----|-----------------------------------|---|-------------|---------------|---------------------------|-------------------------|
| 1) | 6-108.(a) Violation: Notes: | Exterior Foundations cellars, exterior walls, roofs The ledger board is inadequately fastened. | | | Rear Deck | |
| 2) | 6-108.(a) Violation: Notes: | Exterior Foundations cellars, exterior walls, roofs Joists must be supported by joist hangers | | | Rear Deck | |
| 3) | 6-108.(a) Violation: Notes: | Exterior Foundations cellars, exterior walls, roofs Add 2 additional 2" x 8"-s to front board to house. | create a ca | ırrying beam. | Rear Deck This board is r | running parallel to the |
| 4) | 6-108.(a) Violation: Notes: | Exterior Foundations cellars, exterior walls, roofs Adequately fasten the splice joints of the su | upport post | S. | Rear Deck | |
| 5) | 6-108.(a) Violation: Notes: | Exterior Foundations cellars, exterior walls, roofs Discontinue the use of the decks until the v | vork is com | plete. | Rear Deck | |

Comments: