

June 1, 2018

Cecile Stadler
Lio Restaurant

Re: Lio Restaurant

Cecile,

We are writing this letter at your request to indicate that we have walked through your second floor restaurant space and that the space does have the two separated means of egress in accordance with our plans with exit devices and exit signage.

We understand that the City has inspected the sprinkler system for the space and the fire alarm for the tenant space and they are fully operational.

We understand that the ground level retail space is NOT seeking occupancy at this time and that improvements will need to be made to that space to fire separate it from the second floor restaurant space prior to occupying the ground floor.

Based on the above it is of our opinion that the second floor restaurant tenant space is in conformance with our drawings.

Sincerely,



Ryan Senatore, AIA LEED-AP

Principal

207-650-6414

senatorearchitecture.com

ryan@senatorearchitecture.com