CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

	wner/Manag ARKIN ROBE			Inspector Suzanne Hunt		Inspection Date 5/10/2010		
Locatation CBL			Status	Status		Inspection Type		
76 PORTLAND ST		ST	036 1022001	Re-Inspect 30 Days		Complaint-Inspection		
	Code	Int/Ext		Floor	Unit No.	Area	Compliance Date	
1)	22-3 (a) Violation: Notes:	Interior Rodent Hark remove all d	J			Basement		
2)	6-108.(d) Violation: Notes:	Interior Basement Stairways, stairwells, stairs and porches. Repair the stairs to the basement and add a handrail one side. All stairs must be structurally sound, in good repair and safe to use.						
3)	6-108.(c) Violation: Notes:	Exterior Basement Exterior windows, doors and skylights All windows including basement must be substantiallly weather tight, water tight, and vermin proof.						
4)	6-108.(a) Violation: Notes:	Interior Basement Foundations cellars, exterior walls, roofs The basement has standing water. A hole (approximatly 3 ft sq., 1.5 ft deep) is filled with standing water, this hole has several drainage pipes connected to it. The drainage system must be made adequate to drain all water from the basement. The drainage system must meet code requirements.						
5)	6-108.(a) Violation: Notes:	Exterior Various locations Foundations cellars, exterior walls, roofs Missing siding must be replaced. Areas around soffits must be weather and water tight.						
6)	6-108.(a) Violation: Notes:	Exterior Various locations Foundations cellars, exterior walls, roofs Soffits on right and left side must be repaired and made water/weather tight						
7)	6-108.(d) Violation: Notes:	All handrails		be structurally sound a	Entry Way porches. structurally sound and safe to use. The handrail at interior front be sufficiently secured.			
8)	110.26 (b) Violation: Notes:	Interior NEC 2005/N Secure all lig		nprotected junction box	Basement nction boxes, remove extension cords.			
9)	6-108.(b) Violation: Notes:	Interior Through Out Interior floors, walls, ceilings and doors Repair all holes in egress hallway ceilings, walls, and floors.					ut	

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date 5/10/2010	
LARKIN ROBERT		Suzanne Hunt		
Locatation	CBL	Status	Inspection Type	
76 PORTLAND ST	036 1022001	Re-Inspect 30 Days	Complaint-Inspection	

10) 6-108.(d) Interior

Violation: Stairways, stairwells, stairs and porches.

Notes: Exterior Front entrance stairs need to made safe and structurally sound

11) 6-108.(c) Exterior

Violation: Exterior windows, doors and skylights

Notes: Replace broken window (door side light) level one. Tempered required.

12) 110.26 (b) Interior Various locations

Violation: NEC 2005/NFPA 70

Notes: all electrical switches, outlets, junction boxes, are required to properly covered.

13) 110.26 (b) Interior Bedroom

Violation: NEC 2005/NFPA 70

Notes: Repair broken light fixtures in unit known as 76 Rear (second floor)

14)

Violation:

Notes: Legal use of property is retail, office and five (5) residential dwelling units per permit #90-2167.

Property must be brought into legal use.

Comments: 7 residential units and 2 commercials in use. Legal use of property is retail, office and five (5)

residential dwelling units per permit #90-2167 on microfiche. -Saw 8 electirc meters