## CITY OF PORTLAND FIRE PREVENTION BUREAU

DEGETVED SEP 29 2017

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

September 15, 2017

100 COMMERCIAL ST //	S DISCUSSED I AM HE NEW OWNER OTICE WAS SENT WRONG LOCATION	MQBM LLC PO BOX 1377 MRMOUTH, ME 04096
Location	CBL	Inspection Date
106 HIGH ST (108 High St Bus	039 A037001	8/17/2017
Inspector	Inspection Type	Status
John Brennan	FP Routine Inspection Commerci	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 9/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 1- 1.12.5.13 FIRE ALARM INSPECTION STICKER REQUIRED; Permits shall be issued by the AHJ and shall bear the name and signature of the AHJ or that of the AHJ's designated representative. In addition, the permit shall indicate the following: (1) Operation or activities for which the permit is issued (2) Address or location where the operation or activity is to be conducted (3) Name and address of the permittee (4) Permit number and date of issuance (5) Period of validity of the permit (6) Inspection requirements and other permit conditions	9/27/17 COMPLETED
Expired sticker on panel.	
NFPA 101- 31.3.1.1.1 VERTICAL OPENINGS NOT FIRE RATED; Vertical openings shall be enclosed or protected in accordance with Section 8.6.	9 27/17
Patch the hole in the ceiling in the "Cave" studio. Also, patch any opening that remains after your electrician repairs the smoke alarm and light ballast wiring situation.	9/27/17 COMPLETED
NFPA 10- 7.2.4.4 FIRE EXTINGUISHER INSPECTION TAG; Where manual inspections are conducted, records for manual inspections shall be kept on a tag or label attached to the fire extinguisher, on an inspection checklist maintained on file, or by an electronic method.  All extinguishers in the building are expired. No extinguishers can be on the floor; all must be	9/27/17 COMPLETED
hung and secured to the wall.	
NFPA 10- TABLE 6.2.1.1 FIRE EXTINGUISHERS REQ- ORDINARY HAZARD OCCUPANCY; Fire extinguisher size and placement for Class A hazards: Ordinary (Moderate) Hazard Occupancy Minimum rated single extinguisher: 2-A Maximum floor area per unit of A: 1,500ft2 Maximum floor area for extinguisher: 11,250ft Maximum travel distance to extinguisher: 75 ft	9/27/17 COMPLETED
Add 1 extinguisher to the far studio where all the electronics were (back of 2nd floor hallway).	

THERE ALREADY IS AN EXTINGUSHER IN THE ROOM NEXT DOOR Page 1 5 RET AWAY

Violation	$\nearrow$	N/A WE	CARD CO	N Brown	osed Date
Yloratton		Vibob	1/2/	_ ^	oseu Date ompletion
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRE through out with an existing, complete automatic sm be installed in accordance with 9.6.2.10, as modified area in the immediate vicinity of the bedrooms and obasements.  Replace the missing smoke alarm in the "Cave" study.	noke detection d by 31.3.4.5 on all levels o	on system, smoke a 5.2, outside every sloof the dwelling unit,	ılarms shall eeping	temporary required below indi temporary	TELY install  y alarms where  Your signature  estes that y alarms have een installed.
NFPA 70- ARTICLE 110.12 B EXPOSED WIRING electrical equipment, including busbars, wiring terminot be damaged or contaminated by foreign material abrasives, or corrosive residues. There shall be not safe operation or mechanical strength of the equipment; or deteriorated by corrosion, chemical reaction, The wiring for the light ballast and the smoke alarm not to code. Have a licensed electrician rectify the interest of the second strength of the light ballast and the smoke alarm not to code.	nals, insulated in the such as pudamaged partent such as or overheated in the "Cave	ors, and other surfa aint, plaster, cleane rts that may adverse parts that are broke ng.	ices, shall ers, ely affect en; bent;	9 Comi	PLETED
NFPA 70 MISSING COVER ON PANEL; Refer to N requirements of missing cover on electrical panel. The electrical plate caver is missing on the electrical			le, on	Con	127/17 APLETED
FINAL DATE OF COMPLETED VIOLATION(S)	amahamana anakamban kanayakakaka Gasara kata anakakara	ALTICOTE DE TITULE DE DESCONDE REVESTA POR DOMENTO COMPAÑO DO COMPAÑO DE PARTIE DE SENTE	(A discount Policies And Control Committee Control Control Control	9/	27/17
FIRE PREVENTION BUREAU RE-INSPECTION O	F COMPLE	TED VIOLATION(S)	)	/	//

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

## VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agreement, Portland Code of Ordinances §§ 1-15	I understand that I am liable for penalties pursuant to the City of and 10-25, and 30-A)M.R.S. § 4452 and may be subject to further legal
action. 9/27/17	Mi Wh
Date	Responsible Party
Date	Responsible Party
SEEN AND AGREED	
Date /0/02/2017	Fire Prevention Bureau

		·
		,