

Inspection and Testing Certificate

Presented To

Waterfront Maine

For

Merrill's Wharf

254 Commercial St.

Portland ME 04101

USA

This site has been inspected and tested in compliance with applicable standards.

Completed
Tuesday, July 23, 2019

Test Session: 06/12/19

ACCEPTED BY

Waterfront Maine

14 Maine St.
Brunswick ME 04011
USA

TESTED BY

Norris Inc.

Norris Inc

2257 Broadway
South Portland ME 4106
USA

Inspection Summary

Building Information

PROPERTY	Merrill's Wharf	CONTACT
ADDRESS	254 Commercial St.	PHONE
CITY/STATE/ZIP	Portland, ME 04101	MOBILE
COUNTRY	USA	EMAIL

Inspector Information

COMPANY	Norris Inc	CONTACT	Norris Inc.
ADDRESS	2257 Broadway	PHONE	(800) 370-3473
CITY/STATE/ZIP	South Portland, ME 4106	MOBILE	
COUNTRY	USA	EMAIL	tech1@norrisinc.com

NAME	INITIALS	QUALIFICATION AND PROFICIENCIES
Norris Inc.	NI	
Norris Inc.	NI	
Norris Inc.	NI	
Norris Inc.	NI	

Testing Summary

EQUIPMENT TYPE	TOTAL	TESTED	PASSED	FAILED
Fire Control Panel	1	1(100 %)	1(100 %)	0(0 %)
Power Supplies	5	5(100 %)	5(100 %)	0(0 %)
Public Emergency Alarm Reporting	1	1(100 %)	1(100 %)	0(0 %)
Initiating Device	171	168(98 %)	168(98 %)	0(0 %)
Alarm Notification Appliance	128	128(100 %)	128(100 %)	0(0 %)
Supervising Station Transmitting Equipment	1	1(100 %)	1(100 %)	0(0 %)
Emergency Control Equipment	3	3(100 %)	3(100 %)	0(0 %)

Certification

The equipment specified herein was inspected and tested according to the NFPA 72 standard for fire alarm and signaling systems, with the inspection completed on Tuesday, July 23, 2019

ACCEPTED BY
12/30/2019
Building Representative

TESTED BY
12/30/2019
Norris Inc.
Technician

System Details

Control Units

MANUFACTURER	GE EST	DESCRIPTION	GE EST backside of building
MODEL	EST	S/W VERSION	
SERIAL NUMBER		LAST UPDATE	
INSTALL DATE	6/1/2018	S/W LOCATION	

Secondary Power

TYPE	Battery - Sealed Lead-Acid	DESCRIPTION	4th floor, IS power extender
NOMINAL VOLTAGE	0	LOAD VOLTAGE	
AMP HOURS	0	STANDBY HOURS	0
ALARM MINUTES	0	CHARGER VOLTAGE	
BATTERY LOCATION			

TYPE	Battery - Sealed Lead-Acid	DESCRIPTION	1st floor electrical, IS power booster
NOMINAL VOLTAGE	0	LOAD VOLTAGE	
AMP HOURS	0	STANDBY HOURS	0
ALARM MINUTES	0	CHARGER VOLTAGE	
BATTERY LOCATION			

TYPE	Battery - Sealed Lead-Acid	DESCRIPTION	FACP BATTERIES
NOMINAL VOLTAGE		LOAD VOLTAGE	12
AMP HOURS	18	STANDBY HOURS	
ALARM MINUTES		CHARGER VOLTAGE	13
BATTERY LOCATION			

TYPE	Battery - Sealed Lead-Acid	DESCRIPTION	2nd floor, IS power extender
NOMINAL VOLTAGE	0	LOAD VOLTAGE	
AMP HOURS	0	STANDBY HOURS	0
ALARM MINUTES	0	CHARGER VOLTAGE	
BATTERY LOCATION			

TYPE	Battery - Sealed Lead-Acid	DESCRIPTION	IS Norris AES Box
NOMINAL VOLTAGE	0	LOAD VOLTAGE	12
AMP HOURS	12	STANDBY HOURS	0
ALARM MINUTES	0	CHARGER VOLTAGE	13
BATTERY LOCATION			

Monitoring Information

Norris AES Box

TYPE	Digital Alarm Communicator Transmitter	INSTALL DATE	6/1/2018
MANUFACTURER		TEST START	6/12/2019
MODEL		TEST COMPLETE	7/23/2019
SERIAL NUMBER		Time to Transmit to Supervising Station	
MONITORING ORGANIZATION		ALARM SIGNAL	

Norris Inc

MONITORING ORGANIZATION
PHONE

MONITORING ORGANIZATION
EMAIL

MONITORING ORGANIZATION
ACCOUNT NUMBER

MONITORING PHONE LINE 1

MONITORING PHONE LINE 2

MONITORING RETRANSMISSION
ENTITY

ALARM RESTORE

TROUBLE SIGNAL

TROUBLE RESTORE

SUPERVISORY SIGNAL

SUPERVISORY RESTORE

Resolved Corrective Action & Solution Summary

The following 1 corrective action(s) were resolved during the system inspection, testing or maintenance activities

EQUIPMENT TYPE	ADDRESS	DESCRIPTION
Heat Detector - Restorable Spot	L2D57	freight elevator machine room
	Created By:	Norris Inc.
	Creation Date:	6/12/2019
	Corrective Action:	did alarm FACP but did not shunt trip
	Resolution	Corrected with Elev company on 7/23/19
	Resolved By:	Norris Inc.
	Resolved On:	12/30/2019
	Manufacturer:	
	Model:	

Testing Details

Fire Control Panel

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Fire Alarm Panel		GE EST backside of building	Manual	6/12/2019 2:56 PM
	Comment:			



Manufacturer	GE EST
Model	EST
Serial Number	
Visual Inspection	True
Functional Inspection	True
Alarm Verification Timer (s)	30 seconds

Power Supplies

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Battery - Sealed Lead-acid		1st floor electrical, IS power booster	Manual	6/12/2019 2:53 PM
	Comment:	left: 6.28, right: 6.79ah PASSED		
		Visual Inspection		
		Functional Inspection		
		Nominal Voltage	0	
		Amp Hours	0	
		Stand By Hours	0	
		Alarm Minutes	0	
Battery - Sealed Lead-acid		2nd floor, IS power extender	Manual	6/12/2019 2:59 PM
	Comment:	left: 4.78ah, right: 4.88ah PASSED		
		Visual Inspection		
		Functional Inspection		
		Nominal Voltage	0	
		Amp Hours	0	
		Stand By Hours	0	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Battery - Sealed Lead-acid		Alarm Minutes	0	
		FACP BATTERIES	Manual	6/12/2019 3:04 PM
	Comment:	left 11.7ah right 11.7ah passed		
		Visual Inspection	True	
		Functional Inspection	True	
		Amp Hours	18	
		Charger Voltage	13	
		Load Voltage	12	
Battery - Sealed Lead-acid		4th floor, IS power extender	Manual	6/12/2019 3:05 PM
	Comment:	left: 6.48, right: 6.29ah PASSED		
		Visual Inspection		
		Functional Inspection		
		Nominal Voltage	0	
		Amp Hours	0	
		Stand By Hours	0	
		Alarm Minutes	0	
Battery - Sealed Lead-acid		IS Norris AES Box	Manual	6/12/2019 3:05 PM
	Comment:	12ah passed		
		Visual Inspection	True	
		Functional Inspection	True	
		Nominal Voltage	0	
		Amp Hours	12	
		Stand By Hours	0	
		Alarm Minutes	0	
		Charger Voltage	13	
		Load Voltage	12	

Public Emergency Alarm Reporting

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Master Box		Next to FACP	Manual	6/12/2019 3:06 PM
		Manufacturer	GE EST	
		Model	EST	
		Serial Number		
		Visual Inspection	True	
		Functional Inspection		
		Monitoring Organization	HSMC	
		Monitoring Organization Phone	1-800-933-4762	
		Monitoring Account Number	202 6093	

Initiating Device

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Manual Pull Station	L1M129	first floor electric room exit	Manual	6/12/2019 7:01 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D53	5th fl elev lobby	Manual	6/12/2019 7:15 AM
		Visual Inspection	True	

Norris Inc

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D31	5th fl elev lobby	Manual	6/12/2019 7:19 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D7	4th fl elev lobby	Manual	6/12/2019 7:22 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D4	4th fl elev lobby	Manual	6/12/2019 7:24 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D66	3rd fl elev lobby	Manual	6/12/2019 7:26 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D67	3rd fl elev lobby	Manual	6/12/2019 7:28 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D14	2nd fl elev lobby	Manual	6/12/2019 7:30 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D15	2nd fl elev lobby	Manual	6/12/2019 7:32 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D8	1st fl elev lobby	Manual	6/12/2019 7:33 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D7	1st fl elev lobby	Manual	6/12/2019 7:36 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D69	1st fl rear elev lobby	Manual	6/12/2019 7:41 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Alarm Verification Participation	False	
Smoke Detector - General	L1D1	elevator machine room	Manual	6/12/2019 7:42 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D10	1st fl freight elev lobby	Manual	6/12/2019 7:49 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D24	2nd fl freight elev lobby	Manual	6/12/2019 7:51 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D55	3rd fl freight elev lobby	Manual	6/12/2019 7:53 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D29	4th fl freight elev lobby	Manual	6/12/2019 7:56 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D65	5th fl freight elev lobby	Manual	6/12/2019 7:59 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D56	freight elevator machine room	Manual	6/12/2019 8:05 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
		Alarm Verification Participation	False	
Heat Detector - Restorable Spot	L1D2	elevator machine room	Manual	6/12/2019 8:27 AM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Pull Station	L1M142	first floor vestibule 112	Manual	6/12/2019 9:34 AM
		Visual Inspection	True	
		Functional Inspection	True	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D10	5th floor lobby 501	Manual	6/12/2019 10:00 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Manual Pull Station	L2M130	5th floor stair 523	Manual	6/12/2019 10:00 AM
		Visual Inspection		
		Functional Inspection		
		Alarm Verification Participation	False	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	L2D58	5th floor South stair Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:00 AM
Smoke Detector - General	L2D12	5th floor lobby 501 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:00 AM
Smoke Detector - General	L2D63	5nd floor hall by room 512 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:01 AM
Smoke Detector - General	L2D62	5nd floor hall by room 511 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:01 AM
Smoke Detector - General	L2D66	5nd floor hall by room 528 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:01 AM
Smoke Detector - General	L2D60	5nd floor hall by room 509 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:01 AM
Smoke Detector - General	L2D59	5nd floor by room 507 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:01 AM
Smoke Detector - General	L2D21	5th floor storage by 553 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:01 AM
Smoke Detector - General	L2D61	5nd floor hall by room 505 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:01 AM
Smoke Detector - General	L2D64	5nd floor hall by room 503 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:01 AM
Smoke Detector - General	L2D23	5th floor Corridor by room 538 Visual Inspection	Manual	6/12/2019 10:02 AM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D26	5th floor Corridor by cabinets	Manual	6/12/2019 10:02 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D39	5th floor by office 556	Manual	6/12/2019 10:02 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D9	5th floor OpenOffice 569	Manual	6/12/2019 10:02 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D8	5th floor Corridor 371	Manual	6/12/2019 10:02 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D16	5th floor room 560	Manual	6/12/2019 10:02 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D11	5th floor Corridor 371	Manual	6/12/2019 10:02 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D25	5th floor Corridor by room 542	Manual	6/12/2019 10:02 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D41	5th floor Corridor by stairs	Manual	6/12/2019 10:02 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Manual Pull Station	L2M133	5th floor stair 546	Manual	6/12/2019 10:03 AM
		Visual Inspection		
		Functional Inspection		
		Alarm Verification Participation	False	
Smoke Detector - General	L2D40	5th floor stair 546	Manual	6/12/2019 10:03 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Manual Pull Station	L1M162	1st fl unit 100 East exit Visual Inspection Functional Inspection Alarm Verification Participation	Manual False	6/12/2019 10:41 AM
Manual Pull Station	L1M164	first floor unit 100 South Visual Inspection Functional Inspection Alarm Verification Participation	Manual False	6/12/2019 10:41 AM
Manual Pull Station	L1M162	1st floor unit 100 Kitchen rear exit Visual Inspection Functional Inspection Alarm Verification Participation	Manual False	6/12/2019 10:41 AM
Manual Pull Station	L1M163	first floor 100 West exit Visual Inspection Functional Inspection Alarm Verification Participation	Manual False	6/12/2019 10:42 AM
Smoke Detector - General	L2D13	5th floor Corridor by 540 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:42 AM
Smoke Detector - General	L2D36	4th floor Lobby 401 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:42 AM
Smoke Detector - General	L2D19	4th floor Lobby 401 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:42 AM
Smoke Detector - General	L2D50	4th floor office by 403 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:42 AM
Smoke Detector - General	L2D27	4th floor Corridor by 401a Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:42 AM
Manual Pull Station	L2M131	4th floor stair 405 Visual Inspection Functional Inspection Alarm Verification Participation	Manual False	6/12/2019 10:42 AM
Smoke Detector - General	L2D30	4th floor pantry 407 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 10:42 AM
Smoke Detector - General	L2d67	4th files room 440 Visual Inspection	Manual	6/12/2019 10:44 AM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D18	4th floor OpenOffice 458	Manual	6/12/2019 10:44 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D5	4th floor room 408	Manual	6/12/2019 10:44 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D52	4th floor by office 447	Manual	6/12/2019 10:44 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D48	4th floor copy room 423	Manual	6/12/2019 10:44 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D22	4th floor office 443	Manual	6/12/2019 10:44 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D32	4th floor by paralegal 424	Manual	6/12/2019 10:44 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D35	4th floor file room 479	Manual	6/12/2019 10:44 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D37	4th floor by office 420	Manual	6/12/2019 10:45 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D24	4th floor office by 414	Manual	6/12/2019 10:45 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D33	4th floor by office 416	Manual	6/12/2019 10:45 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	L2D15	Alarm Verification Participation 4th floor open Office 476	False Manual	6/12/2019 10:45 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D28	Alarm Verification Participation 4th floor by office 412	False Manual	6/12/2019 10:45 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D3	Alarm Verification Participation 4th floor corridor 458	False Manual	6/12/2019 10:45 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D54	Alarm Verification Participation 4th floor Corridor by restrooms	False Manual	6/12/2019 10:45 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D6	Alarm Verification Participation 4th floor open Office 453	False Manual	6/12/2019 10:45 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D38	Alarm Verification Participation 4th floor by office 452	False Manual	6/12/2019 10:45 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D55	Alarm Verification Participation 4th floor electric room	False Manual	6/12/2019 10:45 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D20	Alarm Verification Participation 4th floor Corridor by office 461	False Manual	6/12/2019 10:46 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D1	Alarm Verification Participation 4th floor office 473	False Manual	6/12/2019 10:46 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D17	Alarm Verification Participation 4th floor OpenOffice 458	False Manual	6/12/2019 10:46 AM
		Visual Inspection Functional Inspection Drift Compensation	0	
Smoke Detector - General	L2D34	Alarm Verification Participation 4th floor by office 471	False Manual	6/12/2019 10:46 AM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D49	4th floor file room 459	Manual	6/12/2019 10:46 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D42	4th floor office 464	Manual	6/12/2019 10:46 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D14	4th floor open Office 369b	Manual	6/12/2019 10:46 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D43	4th floor office 469a	Manual	6/12/2019 10:46 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D47	4th floor office 465	Manual	6/12/2019 10:46 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D46	4th floor office 467	Manual	6/12/2019 10:46 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D44	4th floor office 466	Manual	6/12/2019 10:46 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D51	4th floor office 369b	Manual	6/12/2019 10:47 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D45	4th floor office 468	Manual	6/12/2019 10:47 AM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Manual Pull Station	L2M132	4th floor stair 456	Manual	6/12/2019 10:47 AM
		Visual Inspection		
		Functional Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Alarm Verification Participation	False	
Smoke Detector - General	L1D65	3rd fl corridor by office 307	Manual	6/12/2019 12:00 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D56	3rd fl Corridor by office 332	Manual	6/12/2019 12:00 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D68	3rd fl pantry 308	Manual	6/12/2019 12:00 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D74	3rd floor by room 382	Manual	6/12/2019 12:01 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Manual Pull Station	L1M149	3rd floor stair 305	Manual	6/12/2019 12:01 PM
		Visual Inspection		
		Functional Inspection		
		Alarm Verification Participation	False	
Smoke Detector - General	L1D64	3rd fl corridor by office 310	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D47	3rd fl office 342	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D63	3rd fl copy room 322	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D48	3rd fl office 342	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D62	3rd fl open Office 312	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D61	3rd fl open Office 314	Manual	6/12/2019 12:02 PM
		Visual Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D46	3rd fl Corridor by office 350	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D60	3rd fl open Office 318	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D59	3rd fl open Office 321	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D49	3rd fl file room 379	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D58	3rd fl Corridor by 328	Manual	6/12/2019 12:02 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D51	3rd fl office by 376	Manual	6/12/2019 12:03 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D57	3rd fl Corridor by conf room 329	Manual	6/12/2019 12:03 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D45	3rd fl Corridor by office 352	Manual	6/12/2019 12:03 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D44	3rd fl Corridor by office 358	Manual	6/12/2019 12:03 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D43	3rd fl Corridor by office 358	Manual	6/12/2019 12:03 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Manual Pull Station	L1M148	Alarm Verification Participation 3rd floor stair 355	False Manual	6/12/2019 12:03 PM
		Visual Inspection Functional Inspection		
Smoke Detector - General	L1D50	Alarm Verification Participation 3rd fl office376	False Manual	6/12/2019 12:03 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D54	Alarm Verification Participation 3rd fl by office 357	False Manual	6/12/2019 12:03 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D42	Alarm Verification Participation 3rd fl Corridor by office 360	False Manual	6/12/2019 12:03 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D41	Alarm Verification Participation 3rd fl office 363	False Manual	6/12/2019 12:03 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D52	Alarm Verification Participation 3rd fl office by 374	False Manual	6/12/2019 12:03 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D39	Alarm Verification Participation 3rd fl office 364	False Manual	6/12/2019 12:04 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D53	Alarm Verification Participation 3rd fl by office 373	False Manual	6/12/2019 12:04 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D38	Alarm Verification Participation 3rd fl office 365	False Manual	6/12/2019 12:04 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D40	Alarm Verification Participation 3rd fl office 363	False Manual	6/12/2019 12:04 PM
		Visual Inspection Functional Inspection		
		Drift Compensation	0	
Smoke Detector - General	L1D37	Alarm Verification Participation 3rd fl office 366	False Manual	6/12/2019 12:04 PM
		Visual Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D36	3rd fl office 368	Manual	6/12/2019 12:04 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D35	3rd fl office 367	Manual	6/12/2019 12:04 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D55	3rd fl Corridor by freight elevator	Manual	6/12/2019 12:04 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D13	2nd fl Lobby 201	Manual	6/12/2019 12:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Manual Pull Station	L1M144	2nd floor stair 247	Manual	6/12/2019 12:35 PM
		Visual Inspection		
		Functional Inspection		
		Alarm Verification Participation	False	
Smoke Detector - General	L1D25	2nd fl Corridor by office 212	Manual	6/12/2019 12:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D23	2nd fl room 250	Manual	6/12/2019 12:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D18	2nd fl Corridor by Room 207	Manual	6/12/2019 12:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D11	2nd fl corr by stair 242	Manual	6/12/2019 12:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D17	2nd fl Corridor by Bike Room 209	Manual	6/12/2019 12:35 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	L1D34	2nd fl Corridor by office 240 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:35 PM
Smoke Detector - General	L1D16	2nd fl Corridor by room 204 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D33	2nd fl copy room 232 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D70	2nd fl electric room Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D32	2nd fl Corridor by office 236 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D31	2nd fl Corridor by office 227 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D30	2nd fl open office 228 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D29	2nd fl Corridor by office 222 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D28	2nd fl Corridor by office 220 Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D21	2nd fl N corridor Visual Inspection Functional Inspection Drift Compensation Alarm Verification Participation	Manual 0 False	6/12/2019 12:36 PM
Smoke Detector - General	L1D20	2nd fl N Corridor Visual Inspection	Manual	6/12/2019 12:36 PM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D12	2nd fl Pantry 245	Manual	6/12/2019 12:36 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D26	2nd fl Corridor by office 216	Manual	6/12/2019 12:37 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	l1d78	2nd floor waiting 209	Manual	6/12/2019 12:37 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	l1d82	2nd floor open office 214	Manual	6/12/2019 12:37 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D79	2nd floor corridor by stairwell	Manual	6/12/2019 12:37 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D19	2nd fl N Corridor by stair	Manual	6/12/2019 12:38 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Manual Pull Station	L1M147	2nd floor North stair	Manual	6/12/2019 12:38 PM
		Visual Inspection		
		Functional Inspection		
		Alarm Verification Participation	False	
Smoke Detector - General	L1D77	2nd FL behind stairwell	Manual	6/12/2019 12:39 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D81	2nd floor by office 204	Manual	6/12/2019 12:39 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L1D80	2nd floor by office 205	Manual	6/12/2019 12:40 PM
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	L1D24	2nd fl Corridor by freight elevator Visual Inspection Functional Inspection Drift Compensation	Manual 0	6/12/2019 12:40 PM
Smoke Detector - General	L1D27	2nd fl Corridor by office 217 Visual Inspection Functional Inspection Drift Compensation	Manual 0	6/12/2019 1:08 PM
Smoke Detector - General	L1D76	first floor above booster Visual Inspection Functional Inspection Drift Compensation	Manual True True 0	6/12/2019 1:36 PM
Manual Pull Station	L1M177	1st floor south lobby Visual Inspection Functional Inspection Alarm Verification Participation	Manual True True False	6/12/2019 2:20 PM
Manual Pull Station	L1M169	1st floor stair C exit Visual Inspection Functional Inspection Alarm Verification Participation	Manual True True False	6/12/2019 2:21 PM
Smoke Detector - General	L1D75	first floor stair by fright Elevator Visual Inspection Functional Inspection Drift Compensation	Manual True True 0	6/12/2019 2:23 PM
Smoke Detector - General	L1D5	first-floor vestibule 112 Visual Inspection Functional Inspection Drift Compensation	Manual True True 0	6/12/2019 2:23 PM
Smoke Detector - General	L1D71	first floor South stair Visual Inspection Functional Inspection Drift Compensation	Manual True True 0	6/12/2019 2:23 PM
Smoke Detector - General	L1D6	first-floor vestibule 112 Visual Inspection Functional Inspection Drift Compensation	Manual True True 0	6/12/2019 2:24 PM
Smoke Detector - General	L1D9	first-floor Corridor 116 Visual Inspection Functional Inspection Drift Compensation	Manual True True 0	6/12/2019 2:24 PM
Smoke Detector - General	L1D4	basement above facp Visual Inspection Functional Inspection Drift Compensation	Manual True True 0	6/12/2019 2:24 PM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General	L1D3	Alarm Verification Participation bsmt by water heater	False Manual	6/12/2019 2:25 PM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
Manual Pull Station	L1M130	Alarm Verification Participation first floor basement exit	False Manual	6/12/2019 2:25 PM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Pull Station	L1M168	Alarm Verification Participation basement stair C	False Manual	6/12/2019 2:26 PM
		Visual Inspection	True	
		Functional Inspection	True	
Smoke Detector - General	L1D73	Alarm Verification Participation first floor North stairway	False Manual	6/12/2019 2:48 PM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
Smoke Detector - General	L1D72	Alarm Verification Participation first floor Hall by North stair	False Manual	6/12/2019 2:48 PM
		Visual Inspection	True	
		Functional Inspection	True	
		Drift Compensation	0	
Manual Pull Station	L1M167	Alarm Verification Participation first floor north stair	False Manual	6/12/2019 2:48 PM
		Visual Inspection	True	
		Functional Inspection	True	
Heat Detector - Restorable Spot	L2D57	Alarm Verification Participation freight elevator machine room	False Manual	12/30/2019 12:04 PM
		Visual Inspection	True	
		Functional Inspection	True	

Skipped

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - Duct		5th floor	Manual	6/1/2018 8:38 AM
	Comment:	could not locate		
		Visual Inspection		
		Functional Inspection		
Smoke Detector - General	L1D22	2nd fl N Corridor	Manual	6/1/2018 3:35 PM
	Comment:	could not locate		
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	
Smoke Detector - General	L2D31	1st FL OS offices	Manual	6/26/2018 1:23 PM
	Comment:	could not locate		
		Visual Inspection		
		Functional Inspection		
		Drift Compensation	0	
		Alarm Verification Participation	False	

Alarm Notification Appliance

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Audible And Visible		5th FL OS office 568	Manual	6/12/2019 1:44 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL OS office by det. 2-11	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL OS women's RM	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL OS office by det. 2-39	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL OS electrical RM	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL elev. lobby	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL OS conf. RM(Allen)	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL OS conf. RM(Pierce)	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL OS conf. RM(Casco bay2)	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th FL IS women's RM	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th fl kitchen area	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		5th fl IS stair B	Manual	6/12/2019 1:45 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Audible And Visible		5th fl OS stair B Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		5th fl by SD 2-13 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		5th fl McKusick Library Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		5th fl S corridor entrance Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		5th fl by reception desk Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		5th fl restroom vestibule Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		5th fl mens room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		5th fl womens room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		5th fl OS Casco Bay 1 meeting room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl by SD 2-51 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl by SD 2-14 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl by SD 2-43 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl by SD 2-49 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Audible And Visible		4th fl by SD 2-36 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl men's room vestibule Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl men's room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl by SD 2-52 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl by SD 2-29 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl by SD 2-36 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl men's room vestibule Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl women's room vestibule Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl men's room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl women's room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th FL OS office 470 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th FL OS office by det. 2-15 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th FL OS women's RM Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Audible And Visible		4th FL IS women's RM Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th FL OS office by kitchen Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th FL by sliding door, on brick wall Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th FL OS office 409 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th FL OS office by det. 2-24 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		4th fl by SD 2-33 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:45 PM
Audible And Visible		3rd fl by SD 1-59 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl womens room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl womens room vestibule Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl mens room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl by SD 1-57 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl by SD 1-55 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl mens room vestibule Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Audible And Visible		3rd fl mens room Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl mens room vestibule Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl by SD 1-46 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl by SD 1-44 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl by SD 1-41 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd fl by SD 1-40 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd FL OS office by det. 1-61 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd FL OS office by kitchen(near stair) Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd FL elev. lobby by det. 1-65 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd FL OS office by det. 1-47 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd FL by sliding door, on brick wall Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd FL OS women's RM Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd FL IS women's RM Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Audible And Visible		3rd FL OS office by det. 1-50 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		3rd FL OS office 372 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		2nd FL short hall. OS Berry Dunn by emergency door Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:46 PM
Audible And Visible		2nd FL OS Berry Dunn below exit sign Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		2nd FL men's RM OS Berry Dunn/Wells Fargo Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		2nd FL woman's men's RM OS Berry Dunn/Wells Fargo Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		2nd FL OS freight elevator Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		2nd FL elev. lobby Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		2nd FL OS office by det. 1-25 Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		2nd FL OS office by kitchen Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		2nd fl Selkirk Partners Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		2nd fl OS BerryDunn entrance Visual Inspection Functional Inspection Candela Rating	Manual 0	6/12/2019 1:47 PM
Audible And Visible		1st FL ORPC womens room Visual Inspection	Manual	6/12/2019 1:47 PM

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl by SD by mens room near selkirk	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL ORPC mens room	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl OS Wells Fargo	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL ORPC office 2	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl hallway past Wells Fargo	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL ORPC office 1	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl(ocean side) OS bathrooms	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL ORPC entrance	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FI Ricoh hallway	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl by SD 1-23	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl IS mens room	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl by SD 1-18	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FI by Stair B	Manual	6/12/2019 1:47 PM
		Visual Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl by SD 1-16	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl OS womens room	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl PP IS Yoga office	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl bathroom 2	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl bathroom 1	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl PP IS Federal Law office	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl OS Stair A	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl mens room vestibule	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl Stair C exit	Manual	6/12/2019 1:47 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl PP upper level	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl mens room	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl womens room vestibule	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl PP lower level	Manual	6/12/2019 1:48 PM
		Visual Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL OS office (Ricoh)	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL IS women's RM	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl womens room	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL IS office across from stair C exit	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL IS office by women's RM	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL OS custodial by EMR	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL elev lobby by Main doors	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st FL elev lobby bottom of stairs	Manual	6/12/2019 1:48 PM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl Wells Fargo 1	Manual	6/27/2019 6:44 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl Wells Fargo 2	Manual	6/27/2019 6:44 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl BerryDunn hallway	Manual	6/27/2019 6:44 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl BerryDunn main lobby	Manual	6/27/2019 6:44 AM
	Comment:	no access		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl NBT entrance	Manual	6/27/2019 6:44 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl by SD 1-34 NBT	Manual	6/27/2019 6:44 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl by SD 1-31 NBT	Manual	6/27/2019 6:44 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		2nd fl by SD 1-30 NBT	Manual	6/27/2019 6:44 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl Ricoh reception area	Manual	6/27/2019 6:45 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st Fl Ricoh	Manual	6/27/2019 6:45 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl IS restaurant OS bathrooms	Manual	6/27/2019 6:45 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl IS restaurant IS men's RM	Manual	6/27/2019 6:45 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st fl IS restaurant IS Women's RM	Manual	6/27/2019 6:45 AM
	Comment:	no access		
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		1st Fl Restaurant eating area	Manual	6/27/2019 6:45 AM
	Comment:	no access		
		Visual Inspection		

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		basement on post by storage(front)	Manual	6/27/2019 6:45 AM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		basement on post by storage(back)	Manual	6/27/2019 6:45 AM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	
Audible And Visible		basement by sprinkler area	Manual	6/27/2019 6:45 AM
		Visual Inspection		
		Functional Inspection		
		Candela Rating	0	

Supervising Station Transmitting Equipment

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Digital Alarm Communicator Transmitter		Norris AES Box	Manual	6/12/2019 3:13 PM
		Visual Inspection	True	
		Functional Inspection	True	

Emergency Control Equipment

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Elevator Recall	L1M126	Elev prim recall	Manual	6/12/2019 1:36 PM
		Visual Inspection	True	
		Functional Inspection	True	
Elevator Recall	L1M127	Elev alternate recall	Manual	6/12/2019 1:36 PM
		Visual Inspection	True	
		Functional Inspection	True	
Elevator Recall	L1M128	Elev hat light	Manual	6/12/2019 1:37 PM
		Visual Inspection	True	
		Functional Inspection	True	

Device/Equipment Details

Fire Control Panel

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Fire Alarm Panel					
	GE EST backside of building	GE EST	EST		6/1/2018

Power Supplies

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Battery - Sealed Lead-acid					
	4th floor, IS power extender				6/1/2018
	1st floor electrical, IS power booster				6/1/2018
	FACP BATTERIES				6/1/2018
	2nd floor, IS power extender				6/1/2018
	IS Norris AES Box				6/1/2018

Public Emergency Alarm Reporting

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Master Box					
	Next to FACP	GE EST	EST		6/1/2018

Initiating Device

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Heat Detector - Restorable Spot					
L2D57	freight elevator machine room				6/1/2018
L1D2	elevator machine room				6/1/2018
Manual Pull Station					
L1M149	3rd floor stair 305				6/1/2018
L2M131	4th floor stair 405				6/1/2018
L2M133	5th floor stair 546				6/1/2018
L1M177	1st floor south lobby				6/1/2018
L1M169	1st floor stair C exit				6/1/2018
L1M168	basement stair C				6/1/2018
L1M144	2nd floor stair 247				6/1/2018
L1M129	first floor electric room exit				6/1/2018
L1M130	first floor basement exit				6/1/2018
L1M148	3rd floor stair 355				6/1/2018
L1M167	first floor north stair				6/1/2018
L2M130	5th floor stair 523				6/1/2018
L1M147	2nd floor North stair				6/1/2018
L1M164	first floor unit 100 South				6/1/2018
L1M163	first floor 100 West exit				6/1/2018
L1M162	1st fl unit 100 East exit				6/1/2018
L1M162	1st floor unit 100 Kitchen rear exit				6/1/2018
L2M132	4th floor stair 456				6/1/2018
L1M142	first floor vestibule 112				6/1/2018
Smoke Detector - Duct					
	5th floor				6/1/2018

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Smoke Detector - General					
L1D6	first-floor vestibule 112				6/1/2018
L1D45	3rd fl Corridor by office 352				6/1/2018
L1D47	3rd fl office 342				6/1/2018
L1D54	3rd fl by office 357				6/1/2018
L2D3	4th floor corridor 458				6/1/2018
L2D12	5th floor lobby 501				6/1/2018
L2D28	4th floor by office 412				6/1/2018
L1D75	first floor stair by fright Elevator				6/1/2018
L1D1	elevator machine room				6/1/2018
L1D67	3rd fl elev lobby				6/1/2018
L1D10	1st fl freight elev lobby				6/1/2018
L1D16	2nd fl Corridor by room 204				6/1/2018
L1D33	2nd fl copy room 232				6/1/2018
L1D34	2nd fl Corridor by office 240				6/1/2018
L1D51	3rd fl office by 376				6/1/2018
L2D8	5th floor Corridor 371				6/1/2018
L2D25	5th floor Corridor by room 542				6/1/2018
L2D34	4th floor by office 471				6/1/2018
L2D38	4th floor by office 452				6/1/2018
L1D74	3rd floor by room 382				6/1/2018
L1D66	3rd fl elev lobby				6/1/2018
L1D31	2nd fl Corridor by office 227				6/1/2018
L1D36	3rd fl office 368				6/1/2018
L1D61	3rd fl open Office 314				6/1/2018
L1D73	first floor North stairway				6/1/2018
L2D19	4th floor Lobby 401				6/1/2018
L2D48	4th floor copy room 423				6/1/2018
L2D60	5nd floor hall by room 509				6/1/2018
L1D8	1st fl elev lobby				6/1/2018
L1D15	2nd fl elev lobby				6/1/2018
L1D29	2nd fl Corridor by office 222				6/1/2018
L1D38	3rd fl office 365				6/1/2018
L1D63	3rd fl copy room 322				6/1/2018
L2D21	5th floor storage by 553				6/1/2018
L2D50	4th floor office by 403				6/1/2018
L2D58	5th floor South stair				6/1/2018
L1D81	2nd floor by office 204				6/1/2018
L2D31	5th fl elev lobby				6/1/2018
L2D65	5th fl freight elev lobby				6/1/2018
L1D5	first-floor vestibule 112				6/1/2018
L1D23	2nd fl room 250				6/1/2018
L1D27	2nd fl Corridor by office 217				6/1/2018
L1D40	3rd fl office 363				6/1/2018
L1D57	3rd fl Corridor by conf room 329				6/1/2018
L2D15	4th floor open Office 476				6/1/2018
L2D44	4th floor office 466				6/1/2018
L2D64	5nd floor hall by room 503				6/1/2018
l1d78	2nd floor waiting 209				6/1/2018
L1D3	bsmt by water heater				6/1/2018
L1D25	2nd fl Corridor by office 212				6/1/2018
L1D42	3rd fl Corridor by office 360				6/1/2018

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
L1D59	3rd fl open Office 321				6/1/2018
L2D17	4th floor OpenOffice 458				6/1/2018
L2D27	4th floor Corridor by 401a				6/1/2018
L2D46	4th floor office 467				6/1/2018
L2D62	5nd floor hall by room 511				6/1/2018
L1D79	2nd floor corridor by stairwell				6/1/2018
L2D4	4th fl elev lobby				6/1/2018
L2D7	4th fl elev lobby				6/1/2018
L1D35	3rd fl office 367				6/1/2018
L1D49	3rd fl file room 379				6/1/2018
L1D50	3rd fl office376				6/1/2018
L2D9	5th floor OpenOffice 569				6/1/2018
L2D23	5th floor Corridor by room 538				6/1/2018
L2D24	4th floor office by 414				6/1/2018
L2D55	4th floor electric room				6/1/2018
L1D55	3rd fl freight elev lobby				6/1/2018
L2D29	4th fl freight elev lobby				6/1/2018
L1D17	2nd fl Corridor by Bike Room 209				6/1/2018
L1D18	2nd fl Corridor by Room 207				6/1/2018
L1D32	2nd fl Corridor by office 236				6/1/2018
L1D70	2nd fl electric room				6/1/2018
L1D71	first floor South stair				6/1/2018
L2D5	4th floor room 408				6/1/2018
L2D36	4th floor Lobby 401				6/1/2018
L2D37	4th floor by office 420				6/1/2018
L2D51	4th floor office 369b				6/1/2018
L1D4	basement above facp				6/1/2018
L1D24	2nd fl Corridor by freight elevator				6/1/2018
L1D26	2nd fl Corridor by office 216				6/1/2018
L1D60	3rd fl open Office 318				6/1/2018
L2D14	4th floor open Office 369b				6/1/2018
L2D26	5th floor Corridor by cabinets				6/1/2018
L2D43	4th floor office 469a				6/1/2018
L2D45	4th floor office 468				6/1/2018
I1d82	2nd floor open office 214				6/1/2018
L1D11	2nd fl corr by stair 242				6/1/2018
L1D20	2nd fl N Corridor				6/1/2018
L1D22	2nd fl N Corridor				6/1/2018
L1D56	3rd fl Corridor by office 332				6/1/2018
L2D1	4th floor office 473				6/1/2018
L2D10	5th floor lobby 501				6/1/2018
L2D32	4th floor by paralegal 424				6/1/2018
L2D39	5th floor by office 556				6/1/2018
L2D41	5th floor Corridor by stairs				6/1/2018
L1D19	2nd fl N Corridor by stair				6/1/2018
L1D44	3rd fl Corridor by office 358				6/1/2018
L1D62	3rd fl open Office 312				6/1/2018
L1D72	first floor Hall by North stair				6/1/2018
L2D11	5th floor Corridor 371				6/1/2018
L2D30	4th floor pantry 407				6/1/2018
L2D49	4th floor file room 459				6/1/2018
L2D59	5nd floor by room 507				6/1/2018

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
L1D69	1st fl rear elev lobby				6/1/2018
L2D56	freight elevator machine room				6/1/2018
L1D12	2nd fl Pantry 245				6/1/2018
L1D21	2nd fl N corridor				6/1/2018
L1D28	2nd fl Corridor by office 220				6/1/2018
L1D64	3rd fl corridor by office 310				6/1/2018
L1D76	first floor above booster				6/1/2018
L2D33	4th floor by office 416				6/1/2018
L2D40	5th floor stair 546				6/1/2018
L2D47	4th floor office 465				6/1/2018
L1D14	2nd fl elev lobby				6/1/2018
L1D7	1st fl elev lobby				6/1/2018
L1D39	3rd fl office 364				6/1/2018
L1D46	3rd fl Corridor by office 350				6/1/2018
L1D53	3rd fl by office 373				6/1/2018
L2D13	5th floor Corridor by 540				6/1/2018
L2D20	4th floor Corridor by office 461				6/1/2018
L2D61	5nd floor hall by room 505				6/1/2018
L1D24	2nd fl freight elev lobby				6/1/2018
L1D13	2nd fl Lobby 201				6/1/2018
L1D48	3rd fl office 342				6/1/2018
L1D52	3rd fl office by 374				6/1/2018
L1D65	3rd fl corridor by office 307				6/1/2018
L1D68	3rd fl pantry 308				6/1/2018
L2D6	4th floor open Office 453				6/1/2018
L2D35	4th floor file room 479				6/1/2018
L2D52	4th floor by office 447				6/1/2018
L2D54	4th floor Corridor by restrooms				6/1/2018
L2D53	5th fl elev lobby				6/1/2018
L1D9	first-floor Corridor 116				6/1/2018
L1D30	2nd fl open office 228				6/1/2018
L1D37	3rd fl office 366				6/1/2018
L1D55	3rd fl Corridor by freight elevator				6/1/2018
L2D18	4th floor OpenOffice 458				6/1/2018
L2D22	4th floor office 443				6/1/2018
L2D42	4th floor office 464				6/1/2018
L1D80	2nd floor by office 205				6/1/2018
L1D41	3rd fl office 363				6/1/2018
L1D43	3rd fl Corridor by office 358				6/1/2018
L1D58	3rd fl Corridor by 328				6/1/2018
L2D16	5th floor room 560				6/1/2018
L2D63	5nd floor hall by room 512				6/1/2018
L2D66	5nd floor hall by room 528				6/1/2018
L2D31	1st FL OS offices				6/26/2018
L1D77	2nd FL behind stairwell				6/12/2019
L2d67	4th files room 440				6/12/2019

Alarm Notification Appliance

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Audible And Visible					
	5th FL elev. lobby				6/26/2018

Norris Inc

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
	4th FL OS office by kitchen				6/26/2018
	4th FL OS office 409				6/26/2018
	3rd FL OS office by det. 1-47				6/26/2018
	2nd fl Wells Fargo 2				6/26/2018
	2nd fl hallway past Wells Fargo				6/26/2018
	1st FL OS office (Ricoh)				6/26/2018
	5th FL IS women's RM				6/26/2018
	3rd FL OS women's RM				6/26/2018
	3rd fl by SD 1-55				6/26/2018
	3rd fl by SD 1-57				6/26/2018
	3rd fl womens room vestibule				6/26/2018
	2nd fl BerryDunn hallway				6/26/2018
	4th fl by SD 2-43				6/26/2018
	4th fl women's room vestibule				6/26/2018
	3rd fl mens room				6/26/2018
	2nd FL short hall. OS Berry Dunn by emergency door				6/26/2018
	2nd fl womens room vestibule				6/26/2018
	1st FL ORPC entrance				6/26/2018
	5th FL OS office 568				6/26/2018
	4th fl by SD 2-36				6/26/2018
	4th fl by SD 2-36				6/26/2018
	3rd fl by SD 1-44				6/26/2018
	3rd fl womens room				6/26/2018
	2nd fl mens room vestibule				6/26/2018
	1st FL elev lobby by Main doors				6/26/2018
	5th FL OS women's RM				6/26/2018
	5th fl womens room				6/26/2018
	4th FL OS office by det. 2-15				6/26/2018
	3rd fl by SD 1-40				6/26/2018
	2nd FL OS freight elevator				6/26/2018
	2nd fl bathroom 1				6/26/2018
	1st FL IS women's RM				6/26/2018
	5th FL OS electrical RM				6/26/2018
	4th fl by SD 2-51				6/26/2018
	4th fl women's room				6/26/2018
	3rd FL OS office by kitchen(near stair)				6/26/2018
	2nd FL men's RM OS Berry Dunn/Wells Fargo				6/26/2018
	2nd fl by SD 1-16				6/26/2018
	1st FL IS office across from stair C exit				6/26/2018
	1st fl PP IS Yoga office				6/26/2018
	1st FL ORPC office 2				6/26/2018
	1st FL ORPC mens room				6/26/2018
	1st fl IS restaurant IS Women's RM				6/26/2018
	4th fl by SD 2-29				6/26/2018
	4th fl by SD 2-33				6/26/2018
	3rd FL OS office 372				6/26/2018
	2nd fl OS BerryDunn entrance				6/26/2018
	2nd fl NBT entrance				6/26/2018
	2nd fl by SD 1-34 NBT				6/26/2018
	1st FL ORPC womens room				6/26/2018
	5th fl IS stair B				6/26/2018

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
	5th fl OS stair B				6/26/2018
	4th fl men's room vestibule				6/26/2018
	3rd fl mens room vestibule				6/26/2018
	3rd fl mens room				6/26/2018
	2nd fl Selkirk Partners				6/26/2018
	1st fl OS womens room				6/26/2018
	1st fl IS mens room				6/26/2018
	1st FL ORPC office 1				6/26/2018
	5th FL OS office by det. 2-39				6/26/2018
	5th fl mens room				6/26/2018
	5th fl OS Casco Bay 1 meeting room				6/26/2018
	3rd fl by SD 1-41				6/26/2018
	2nd FL woman's men's RM OS Berry Dunn/Wells Fargo				6/26/2018
	2nd fl by SD 1-18				6/26/2018
	1st FL IS office by women's RM				6/26/2018
	1st fl IS restaurant IS men's RM				6/26/2018
	1st FI Restaurant eating area				6/26/2018
	5th FL OS conf. RM(Pierce)				6/26/2018
	5th fl McKusick Library				6/26/2018
	5th fl by reception desk				6/26/2018
	3rd FL elev. lobby by det. 1-65				6/26/2018
	2nd FL OS office by kitchen				6/26/2018
	2nd fl by SD by mens room near selkirk				6/26/2018
	1st fl PP upper level				6/26/2018
	1st fl PP IS Federal Law office				6/26/2018
	1st FI by Stair B				6/26/2018
	1st FI Ricoh				6/26/2018
	5th FL OS conf. RM(Allen)				6/26/2018
	4th fl by SD 2-49				6/26/2018
	4th fl men's room vestibule				6/26/2018
	3rd FL by sliding door, on brick wall				6/26/2018
	2nd fl Wells Fargo 1				6/26/2018
	2nd fl womens room				6/26/2018
	1st fl IS restaurant OS bathrooms				6/26/2018
	5th FL OS conf. RM(Casco bay2)				6/26/2018
	5th fl S corridor entrance				6/26/2018
	4th fl by SD 2-14				6/26/2018
	3rd fl by SD 1-46				6/26/2018
	3rd fl by SD 1-59				6/26/2018
	2nd FL OS office by det. 1-25				6/26/2018
	1st fl Stair C exit				6/26/2018
	1st FI Ricoh hallway				6/26/2018
	1st fl(ocean side) OS bathrooms				6/26/2018
	4th fl men's room				6/26/2018
	4th FL by sliding door, on brick wall				6/26/2018
	3rd FL IS women's RM				6/26/2018
	2nd fl by SD 1-23				6/26/2018
	2nd fl mens room				6/26/2018
	1st FL elev lobby bottom of stairs				6/26/2018
	5th fl kitchen area				6/26/2018
	4th fl men's room				6/26/2018

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
	4th fl by SD 2-52				6/26/2018
	3rd FL OS office by det. 1-50				6/26/2018
	2nd fl BerryDunn main lobby				6/26/2018
	2nd fl by SD 1-31 NBT				6/26/2018
	2nd fl by SD 1-30 NBT				6/26/2018
	1st fl Ricoh reception area				6/26/2018
	5th fl by SD 2-13				6/26/2018
	5th fl restroom vestibule				6/26/2018
	4th FL IS women's RM				6/26/2018
	4th FL OS office by det. 2-24				6/26/2018
	3rd fl mens room vestibule				6/26/2018
	2nd FL OS Berry Dunn below exit sign				6/26/2018
	2nd fl OS Wells Fargo				6/26/2018
	1st fl PP lower level				6/26/2018
	5th FL OS office by det. 2-11				6/26/2018
	4th FL OS office 470				6/26/2018
	4th FL OS women's RM				6/26/2018
	3rd FL OS office by det. 1-61				6/26/2018
	2nd FL elev. lobby				6/26/2018
	2nd fl bathroom 2				6/26/2018
	2nd fl OS Stair A				6/26/2018
	1st FL OS custodial by EMR				6/26/2018
	basement on post by storage(back)				6/12/2019
	basement on post by storage(front)				6/12/2019
	basement by sprinkler area				6/12/2019

Supervising Station Transmitting Equipment

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
	Digital Alarm Communicator Transmitter				
	Norris AES Box				6/1/2018

Emergency Control Equipment

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
	Elevator Recall				
L1M126	Elev prim recall				6/1/2018
L1M128	Elev hat light				6/1/2018
L1M127	Elev alternate recall				6/1/2018