



DETAIL CROSS SECTION UNDER KITCHEN AND THROUGH SECOND FLOOR



WOODEN BEAM

