

1	EXISTING EXTERIOR VENT CONDITIONS
SK-1	SCALE: N/A

NOTES:

- 1 EXISTING SIDE-WALL VENT TO BE REMOVED 2 MASONRY OPENING TO BE REPAIRED

- 3 NEW VENT COMPONENTS TO BE PAINTED PER HPB RECOMMENDATIONS 4 EXISTING SIDE-WALL VENT UNIT IS LIKELY TO BE REUSED ON THE ROOF. SEE CUT SHEET.
- 5 SEE SK-1a FOR SCALABLE EXTERIOR ELEVATION





PROPOSED VENT LOCATION



RENDERING SHOWING PROPOSED ROOF-TOP VENT SK-1 SCALE: N/A

FOR HISTORICAL PRESERVATION REVIEW



THE DANFORTH INN DANFORTH STREET PORTLAND, MAINE TEMPO DULU, LLC OWNER: 163 DATE: NOV. 19, 2014 DRAWN BY: ECD CHECKED BY: TES PROPOSED ROOF-TOP VENT **SK-1**