



SOUTH WALL EXTENDING FROM WINDOW SILL TO CEILING, INCLUDING WINDOW PERIMETER 175 SF



NORTH WALL WINDOW SOFFIT 30 SF





SOUTH WALL EXTENDING FROM BALCONY TO WINDOW SILL 100 SF



NORTHWEST CEILING/WALL CORNER 50 SF


NOTE: THE INTERIOR FINISH REPAIRS IS ADD. ALTERNATE #4. PROVIDE SEPARATE PRICING FOR THIS WORK ON BID FORM.



NORTH DOOR 50 SF



NORTH WALL ADJACENT TO DOOR 45 SF



EAST WALL WINDOW PERIMETER 125 SF AND CRACK IN NORTHEAST CORNER 20 LF

INTERIOR FINISH GENERAL NOTES

- A. REFERENCE SPECIFICATIONS FOR EXECUTION AND DESCRIPTION OF WORK AND MATERIALS.
- B. REMOVE DETERIORATED SECTIONS TO SOUND PLASTER AREAS.
- C. NOTIFY CHURCH REPRESENTATIVE IF REPAIR QUANTITES EXCEED 10% MORE THAN INDICATED ABOVE BEFORE PROCEEDING FURTHER.
- D. PAINTING OF THE INTERIOR IS ONLY REQUIRED AT THE AREAS OF REPAIR. MATCH PAINT TO THE EXISTING.
- E. CONTRACTOR IS REQUIRED TO PROVIDE ALL NESSECARY LIFTS AND SCAFFOLDING TO ACCESS AREAS OF REPAIR.
- F. EXECUTE TWO SAMPLE PANELS (1 CEILING AND 1 WALL PANEL) OF REPLACEMENT PLASTERS TO BE USED AS STANDARDS FOR THE WORKMANSHIP AND PATCHING MATERIAL.
- G. TOTAL FINISH REPAIR QUANTITIES: 680 SF AND 20 LF (CRACK REPAIR).



THIS DRAWING IS AN INSTRUMENT OF SERVICE AND SHALL REMAIN THE PROPERTY OF BECKER STRUCTURAL ENGINEERS INC. IT SHALL NOT BE REPRODUCED, COPIED, LENT OR DISPOSED OF DIRECTLY OR INDIRECTLY NOR USED FOR ANY PURPOSE OTHER THAN FOR WHICH IT IS SPECIFICALLY FURNISHED AND MUST BE RETURNED TO BECKER STRUCTURAL ENGINEERS INC. ON COMPLETION OF WORK, IF REQUESTED.

MSK 09/25/2014

Checked Becker Job Number EAR 3230.01