




South Face of Residence
Closeup of Dormer Joint to be Repaired



South Face of Residence
Closeup of Repairs and Flashing Work to be Done



South Face of Residence
Closeup of Porch Roof Joint Area to be Repaired



East Face (Front) of Residence
Closeup of Bay Window Trim to be Repaired