



West (Rear) Face of Building
Window Sills to be Replaced



Roof
Transition Area to be Repaired