CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

| Owner/Manag | Inspector | | Inspection Date 3/14/2007 Inspection Type | | | | |
|---------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|-------------------------------------------|-----------------------------|----------------------------|------------------|----------------------------------------------------|
| TRUSSELL PROPERTIES LLC | | | | | Suzanne Hunt | | |
| LocatationCBL84 PARK AVE048 B005001 | | Status | | | | | |
| | | 048 B005001 | Re-Inspect 10 Days | | Housing-Inspection | | |
| Code | Int/Ext | | | Floor | Unit No. | Area | Compliance Date |
| 1) 6-108.1 | Exterior | | | 3 | 3 | roof/ | |
| Violation: Notes: | Foundations cellars, exterior walls, roofs | | | | | | |
| | There is a hole approximtely 4 inches square above the ceiling tiles on a vertical wall. This opening to the exterior environment must be repaired. Sheathing and or proper covering required inside and out. | | | | | | |
| 2) 6-108.1 | 6-108.1 Interior | | | 3 | 3 | Bathroom | |
| Violation: Notes: | Foundations cellars, exterior walls, roofs | | | | | | |
| | The pipe located above the ceiling tiles may be leaking, All leaks into the bathroom must be repaired. | | | | | | |
| 3) 6-108.1 | Exterior | | | 3 | 3 | Bathroom | |
| Violation: | Foundations cellars, exterior walls, roofs | | | | | | |
| Notes: | The leak resulting in dripping water into the bathroom must be repaired | | | | | | |
| 4) 6-108.3 | Interior | | 3 3 | 3 | Bedroom | | |
| Violation: | Exterior windows, doors and skylights | | | | | | |
| Notes: | The window in the front window, (in the front room toward Park Ave.) must be repaired. Window weight springs are missing or broken. | | | | | | |
| | | ilissing of brokeri. | | | | | |
| 5) 110.26 (B) | Interior | ilissing of broken. | | 1 | 4 | | |
| 5) 110.26 (B) Violation: | Interior NEC 2005/N | | | 1 | 4 | | |
| , , , | NEC 2005/N No hard wire | FPA 70 smoke detectors in | | Building co | de requires | | letector in each bedroon with battery back- up. |
| Violation: | NEC 2005/N No hard wire | FPA 70 smoke detectors in | | Building co | de requires | | |
| Violation: Notes: | NEC 2005/N No hard wire and 1 in the | FPA 70 smoke detectors in vicinity of the bedroo | | Building co | de requires connected w | ithin the unit | |
| Violation: Notes: 6) 110.26 (B) | NEC 2005/N No hard wire and 1 in the Interior NEC 2005/N | FPA 70 smoke detectors in vicinity of the bedroo | oms in each | Building co unit, interd | de requires connected w | ithin the unit | |
| Violation: Notes: 6) 110.26 (B) Violation: | NEC 2005/N No hard wire and 1 in the Interior NEC 2005/N | FPA 70 smoke detectors in vicinity of the bedroo | oms in each | Building co unit, interd | de requires connected w | ithin the unit | |
| Violation: Notes: 6) 110.26 (B) Violation: Notes: | NEC 2005/N No hard wire and 1 in the Interior NEC 2005/N smoke detect | FPA 70 smoke detectors in vicinity of the bedroo | oms in each | Building con unit, interd | de requires connected w | ithin the unit v | |

Comments:

Each of 7 violations specified will be considered as a new violation. The reinspection on 3/28/07 will be done at no cost to property owner. . Any reinspections there after will be charged at \$75.00 per inspeciton.