CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

0	wner/Manag	er		Inspecto	or		Inspection	Date		
TF	RUSSELL PR	OPERTIES LL	.C	Suzanne Hunt			4/3/2007			
Locatation CBL				Status			Inspection Type			
84 PARK AVE 048 B005001			Re-Inspect 10 Days			Complaint-Inspection				
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date		
1)	110.26 (B) Violation: Notes:	Interior NEC 2005/N no hard wire		Hardwired	3 interconnec	3 cted smoke d	etectors per (City of Portland code		
		required, installed by licensed electrician. Electric Permit required.								
2)	110.26 (B) Violation:	Interior NEC 2005/N	FPA 70		1	4				
	Notes:	no hard wired smoke detector. Hardwired interconnected smoke detectors per Portland code. Permit and licensed electrician required. This violation was first cited on 3/14/2007								
3)	110.26 (B) Violation:	Interior NEC 2005/N	FPA 70		2	2				
	Notes:	no hard wired smoke detector. Hardwired interconnected smoke detectors per Portland Code required. Permit and licensed electrician required.								
4)	110.26 (B) Violation:	Interior NEC 2005/N	FPA 70		2	5				
	Notes:	no hard wired smoke detector, Hardwired interconnected smoke detectors per Portland Code required. Permit and electrician required.								
5)	6-108.4	Interior					Various loc	ations		
	Violation: Notes:	Stairways, stairwells, stairs, porches. All inside railings in egress hallways and stairs must be secure and structurally sound. (This was first cited on 2/23/07.)								
6)	6-108.1	Exterior			3	3	roof			
	Violation: Notes:	Foundations cellars, exterior walls, roofs The roof is leaking water continuously into the structure. The roof must be repaired. (This violation vinitially cited on 2/23/07, it was considered fixed on 2/23/07 after owner sent inspection department receipt for \$500. Repair on roof.) The roof covering remains in serious disrepair and is required to be weather and watertight.								
7)	6-108.1	Exterior					roof			
	Violation: Notes:	The roof drai	cellars, exterior wa n is not functioning oof drain must be br	. The roof						
8)	6-108.2	Interior			3	3	Bathroom			
	Violation:	Interior floors	s, walls, ceilings and	d doors						
	Notes:	There is a constant drip of water coming into bathroom via ceiling/roof. (this was first cited on 2/23/07)								

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Ow	vner/Manag	er		Inspecto	r		Inspection Date				
TR	USSELL PR	OPERTIES LL	С	Suzanne	Hunt		4/3/2007				
Lo	catation		CBL	Status			Inspection Type				
84 PARK AVE 048 B005001			Re-Inspe	ct 10 Days	;	Complaint-Inspection					
9)	6-108.2	Interior			3	3	Bathroom				
	Violation:	Interior floors	, walls, ceilings an	nd doors							
	Notes:	stained and missing ceiling tiles must be replaced and painted.									
10)	6-108.2	Interior			3	3	Bathroom				
	Violation:	Interior floors	, walls, ceilings an	nd doors	doors						
	Notes:	hole in bathroom wall all the way through to exterior surface must be repaired. Exterior surface of hole must be properly finished.									
11)	6-108.2	Interior			3	3	Hallway				
	Violation:	Interior floors	, walls, ceilings an	nd doors							
	Notes:	back hall has peeling paint and water stain on ceiling. This must be properly repaired and painted.									
12)	6-114.2	Interior			2	2	Living Room				
	Violation:	Heating facili	ties required.								
	Notes:	60 degrees in living room, 3 ft above floor. Code required 68 degrees.									
13)	6-114.2	Interior			1	4	Living Room				
	Violation:	Heating facili	ties required.								
	Notes:	60 degrees in living room, 3 feet above floor. Code required 68 degrees. (this violations was also cited on 2/5/07 LR at 60 degrees)) A mimimum temperature of 68 degrees is required 3 feet from floor in common room.									
14)	6-113.3	Interior			3		Hallway				
	Violation:	Passageway	s and common sta	airway.							
	Notes:	hallway light third floor, (outside unit 3) does not work. (this was first cited on 2/23/07 was working on 3/14/2007, was not working on 4/03/07))									
15)	6-108.2	Interior			3	6	Bedroom				
	Violation:	Interior floors	, walls, ceilings an	d doors							
	Notes:	Ceiling is water stained and paint is chipping									
16)	6-111.1	Interior			3	6	Kitchen				
	Violation:	Plumbing sta	Indards/Basic facil	lities.							
	Notes:	pipe under kitchen sink leaking.									
17)	6-108.2	Interior			3	6	Bathroom				
	Violation:	Interior floors	, walls, ceilings an	d doors							
	Notes:	water stains on ceiling and walls possibly from roof drainage system. Walls must be repaired and painted.									

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Owner/Man	-		Inspector		Inspection Date
TRUSSELL I	PROPERTIES LL	C	Suzanne Hunt		4/3/2007
Locatation CBL			Status		Inspection Type
84 PARK A\	/E	048 B005001	Re-Inspect 10 Day	S	Complaint-Inspection
18) 6-108.2 Violatior Notes:		s, walls, ceilings an stained ceiling tiles		6	Bathroom
19) 6-108.2 Violatior Notes:	Heat pipe ex	s, walls, ceilings an tending through flo allows for safe egr	or on landing 2nd floo	r outside ui	Stairways nit 2 must be removed or covered in a
20) 6-108.2 Violatior Notes:	Heat pipe ex	s, walls, ceilings an tending through flo allows for safe egr	or on landing 2nd floo	r outside u	Stairways nit 5 must be removed or covered in a
21) 6-108.2 Violation Notes:		s, walls, ceilings an ng tiles must be pri	2 nd doors med and painted and	2 in osund c	Bathroom
22) 6-113.1 Violatior Notes:	0 0	dards/Habitable ro does not work.	1 poms	1	Hallway
23) 6-108.2 Violatior Notes:		s, walls, ceilings an om ceiling is not sc	1 nd doors bund. The ceiling need	1 Is to stuctu	Bedroom
24) 6-108.2 Violatior Notes:		s, walls, ceilings an are stained and da	1 nd doors maged. Must be in so	1 ound condit	Bathroom tion and painted.
25) 6-108.3 Violatior Notes:	The exterior	lows, doors and sl	ack of house) is not st	ructurally s	Basement ound. The Bulkhead door must be
26) 6-108.3 Violatior Notes:	The cellar do	lows, doors and sl oor leading to bulkh casing is decayed	head is not structuraly	sound or v	Basement rermin proof. The door is off it's hinges

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Owner/Manag	ger		Inspector		Inspection Date		
TRUSSELL PF	OPERTIES LL	.C	Suzanne Hunt		4/3/2007		
Locatation CBL			Status		Inspection Type		
84 PARK AVE 048 B005001			Re-Inspect 10 Da	iys	Complaint-Inspection		
27) 6-113.5 Violation: Notes:		of lighting fixtures	, and non coated wi	re from the ce	Cellar ellar. Licensed electrician required.		
28) 6-113.5 Violation: Notes:		of lighting fixtures de open junction b	oxes and exposed v	Cellar kes and exposed wires. Licensed electrician required.			
29) 6-113.5 Violation: Notes:		of lighting fixtures bund the Electric M	eter Box to Water M	eter per Portla	Cellar and Code.		
30) 6-111.1 Interior Violation: Plumbing standards/Basic facilit Notes: Floor drain in cellar is not proper				or drain must	Cellar be secure.		
31) 6-108.6 Violation: Notes:	Required equipment and utilities Door bells do not work. All supplies utilities must function.						
32) 6-108.2 Violation: Notes:		s, walls, ceilings an /ay wall completel	1 d doors y through to exterior	4 surface of air	Hallway shaft. Repair		
33) 6-108.2 Violation: Notes:		s, walls, ceilings an bedroom is buckled	1 d doors d up near radiator, re	4 epair.	Bedroom		
34) 6-108.2 Violation: Notes:		s, walls, ceilings an and sub floor are lo	1 d doors bose and need struct	4 ural repair	Hallway		
35) 6-108.2 Violation: Notes:		s, walls, ceilings an stained ceiling tile		4	Various locations		
36) 6-108.3 Violation: Notes:		lows, doors and sl m window does no	1 kylights ot close properly. (th	4 iis was first cit	Bedroom ted on 2/05/07)		

CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Owner/Mana	ger		Inspector	Inspection Date		
TRUSSELL PI	ROPERTIES LL	С	Suzanne Hunt	4/3/2007		
Locatation CBL			Status	Inspection Type		
84 PARK AVE 048 B005001		Re-Inspect 10 Days	Complaint-Inspection			
 37) 6-108.2 Interior Violation: Interior floors, walls, ceilings and doors Notes: light fixture in back bedroom must be structurally sound and in working condition. (this was first or source) 						
	2/05/07)					
Comments: This inspection was conducted by Arthur Rowe, Jon Rioux, and Suzanne Hunt. We spoke to tenants from Unit 6, 4, 3, and 2. Trussell Property maintanance person Mike Smith showed us all 6 units and the basement. Sally Trussell initially met us at site but was unable stay for complete inspection.						