

Permitting and Inspections Department Michael A. Russell, MS, Director

December 13, 2017

56 SHERMAN STREET LLC 90 CARROLL ST PORTLAND, ME 04102

CBL: 048 F009001

Located at: 56 SHERMAN ST

Certified Mail 7013 2250 0001 6995 1915

Dear 56 SHERMAN STREET LLC,

An evaluation of the above-referenced property on 12/13/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 01/12/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Jason Duval

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager				Inspector		Inspection Date
56 SHERMAN STREET LLC			Jason Duval		12/13/2017	
Location		CBL		Status		Inspection Type
56 SHERMAN ST		048 F009001		Violations Exist		Inspection
Code	<u>In</u>	t/Ext	Floor	Unit No.	Area	Compliance Date
1) 55.083						
Violation:	NFPA 70 JUNCTION BOXES REQUIRE COVERS; REFER TO NFPA 70, NATIONAL ELECTRICAL CODE, ON STANDARDS REGARDING JUNCTION BOXES REQUIRING COVERS.					
Notes:	Address the junction boxes in the basement that do not have covers.					
2) 55.030						
Violation:	NFPA 101- 7.2.2.4.2 HANDRAILS ARE NOT CONTINOUS; REQUIRED GUARDS AND HARDRAILS SHALL CONTINUE FOR THE FULL LENGTH OF EACH FLIGHT OF STAIRS. AT TURNS OF NEW STAIRS, INSIDE HANDRAILS SHALL BE CONTINUOUS BETWEEN FLIGHTS AT LANDINGS.					
Notes:	R311.7.7.2 Continuity. Handrails for stairways shall be continuous for the full length of the flight, from a point directly above the top riser of the flight to a point directly above the lowest riser of the flight. Handrail ends shall be returned or shall terminate in newel posts or safety terminals.					
3) 55.082						
Violation:	NFPA 70 LABEL ALL ELECTRICAL PANELS; REFER TO NFPA 70 FOR REQUIREMENTS REGARDING LABELING OF ALL ELECTRICAL PANELS.					
Notes:	Label inside the electrical panels.					

Electrical panels need to be labeled inside. Junction boxes need to be covered in basement. Railing

endings throughout the inside of the building need to return to the wall.

Comments: