

Information from 1924 tax records for 19, 23, 25 and 31 Bramhall Street

19 Bramhall

- * tax form indicates roof was originally wood shingle
- * note balcony at 2nd floor
- * note shutters
- * note balustrade above bay window
- * note square stair posts with turned ball finials
- * porch railing includes open baluster sections and solid clapboard sections

23 Bramhall

- * tax form confirms roof was slate
- * dark, single color for trim—close in value to brick exterior
- * small balcony in front of roof dorm has turned ball finials
- * will need to zoom in on scanned photo to determine baluster design

25 Bramhall

- * photo confirms original side entrance—details difficult to discern—will need to zoom in on scanned photo.
- * photo suggests that salvaged door inside was likely original front door
- * window sash appear dark with lighter color trim
- * roof was originally wood shingle
- * note shutters
- * only center gable on side elevation appears to have had finial top
- * need to zoom in on scanned photo to determine treatment of center panel between windows on third floor
- * note what appears to be massive flagpole!
- * note original garage doors

31 Bramhall

- * original roof was asbestos
- * note railing above porch; need to zoom in to determine railing design.
- * shutters appear on some windows only

Year	Unit	Coefficient	Land Value
19	40	5573	90000



63-4-4

Surveyed by

[Handwritten signature]

(Remarks on other Side)

[Handwritten notes]

1032
1724

Area	Multiplier	Coefficient	
4653	78	45517	
Year	Unit	Coefficient	Land Value
19	119	20820	42500



Brown

19 .

\$ 2417 50



63-A-2


25-
Bram

Surveyed by

[Handwritten signature]

(Remarks on other Side)

123 - 1118/172 - 5 11500+ 199



725-
Bram

63-4-2

Surveyed by

W. H. K. K. K.

(Remarks on other Side)

20/2

Surveyed by

W. C. ...

63-A-1

(Remarks on other Side)

1051/273-1925 - St - good condition



31
Bram