CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

	wner/Manag	Inspector Peter Merrow			Inspection Date 03/29/2006				
	GUO LIANGPING & Locatation CBL			Status			Inspection Type		
	760 CONGRESS ST 054 F013001			Otatus	Status			Complaint-Inspection	
	Code	Int/Ext		F	loor	Unit No.	Area	Compliance Date	
1)	6-109.5 Violation: Notes:		vermin control. k yard must be rem	oved.			BackYard		
2)	6-108.1 Violation: Notes:	Exterior Various locations Foundations cellars, exterior walls, roofs Peeling paint on trim							
3)	6-113.5 Violation: Notes:	Interior Basement Maintenance of lighting fixtures Missing junction box covers/exposed wiring							
4)	6-110.6 Violation: Notes:	Interior Basement Basement dwelling units. Evidence of people living in basement. Bed, clothing, ect. Must be secured/removed							
5)	6-113.5 Violation: Notes:		of lighting fixtures ighting. Must be rep	paired.			Stairways		
6)	6-114.3 Violation: Notes:	Interior 2 2 Living Room Maintenance of equipment. Furnas is in-operatable. MUST BE REPAIRED/REPLACED WITH IN 5 DAYS.							
7)	6-108.3 Violation: Notes:	Interior 2 Exterior windows, doors and skylights Rear door is broken in.				3	Living Room		
8)	6-108.2 Violation: Notes:	Interior 2 3 Bathroom Interior floors, walls, ceilings and doors Exposed pipes in bathroom, leading into ceiling. Must be capped and filled							
9)	6-116.5 Violation: Notes:	Interior Fire Protection Missing smo	on ke detector. (Repla	2 aced by tenant		3	Hall		
10)	6-113.5 Violation:	Interior Maintenance	of lighting fixtures	3		4	Dining Room		

Notes:

ceiling fan/ light fixtur is broken.

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
GUO LIANGPING &		Peter Merrow	03/29/2006
Locatation	CBL	Status	Inspection Type
760 CONGRESS ST	054 F013001		Complaint-Inspection

11) 6-108.2 Interior 2 4 Stairways

Violation: Interior floors, walls, ceilings and doorsNotes: Hole in drywall, behind door, on landing.

Comments: All Repairs must be made with in 30 days, Heat In Unit 2, Must be repaired with in 5 days.