

Permitting and Inspections Department Michael A. Russell, MS, Director

October 30, 2017

KODI BOULIS K & 230 BRACKETT ST PORTLAND, ME 04102

CBL: 055 B050001

Certified Mail 7014 1820 0001 4049 6997

Located at: 230 BRACKETT ST

Dear KODI BOULIS K &,

An evaluation of the above-referenced property on 10/30/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 10 days of the date of this notice. A re-inspection of the premises will occur on 11/9/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to schedule a re-inspection earlier or if you have any questions. 207-874-8706

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Jason Duval

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

| Owner/Manager KODI BOULIS K & | | Inspector Jason Duval | Inspection Date 10/30/2017 |
|----------------------------------|---------------|--------------------------|-------------------------------|
| | | | |
| 230 BRACKETT ST | 055 B050001 | Violations Exist | Housing Safety Inspection |
| Code | Int/Ext Floor | Unit No. Area | Compliance Date |

1) 206

Violation:

SMOKE ALARMS / BEDROOMS; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: in all sleeping rooms.

NFPA 101 (2009) 24.3.4.1(1), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

Smoke detector required in first floor bedroom in owner apartment.

2) 207

Violation:

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

CO Alarms required for both floors in owner apartment.

Comments:

Unable to get into 2 bedrooms in front apartment. Back apartment (owner's) missing smoke detector in first floor bedroom. CO alarms needed for both floors in owner unit. Need to schedule re-inspection to check bedrooms that were locked and to check violations.