

168 Clark street
Original layout of
second floor

before water
damage.
Demolition was
done by Servpro
on exterior walls
approximately 3
feet from floor.
Plaster and lads.
Kitchen, bathroom
and bedroom. All
flooring in this
diagram was
removed to
subfloor. Removed
interior bathroom
walls and walls
around the pantry.
These walls are
not load bearing
walls.



N
↑
2nd Level