

Permitting and Inspections Department Michael A. Russell, MS, Director

RIEDER MORGAN A & 71 CARLETON ST PORTLAND, ME 04102

CBL: 056 G018001

Located at: 58 SPRUCE ST

Mail

Dear RIEDER MORGAN A &,

An evaluation of the above-referenced property on 11/08/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises needs to be scheduled within 30 days at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Matthew Sarapas

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager RIEDER MORGAN A &		•	Inspection Date	Date
			11/8/2017	
Location	CBL	Status	Inspection Type	
58 SPRUCE ST	056 G018001	Violations Exist	Inspection	

Code Int/Ext Floor Unit No. Area Compliance Date

1) 210

Violation: ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a

free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with

an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes: Third floor rear bedroom window not egress compliant, undersized, exits onto roof.

2) 211

Violation: OTHER

Notes: Front bedroom third floor needs window guard, window is less than 18" from floor

Comments: