The second secon

(FORM Q703 REV 0)

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES
BO PLEASANT AVENUE - SOUTH PORTLAND, MAINE 04106 • TEL: (207) 799-8911 • FAX: (207) 799-7251

		INS	PECH	IN REPORT					
CUSTOMER:	S. W. COLE E	ENG.				PAGE	1	OF	1
ADDRESS:	GRAY ME.			····					
ATTENTION:	ROGER DOM	INGO							
COPIES:									
PROJECT:	MERCY AT I	ORE RIVER							
ONNER:	MERCY HOSE	PITAL							
CONTRACTOR:	GILBANE								
JOB No.: 06-10	069.1 REPORT	No.: QAL-08-0919	P. O. NUMBER:		DATES INSPECTED	05-14	-08		
			REM	ARKS					
>>> SITE VISIT TO PERFORM VISUAL INSPECTION OF COLUMN ENHANCEMENTS AT GRID H-2 ALL LEVELS. > REF. AMERICAN STEEL DRAWING SK-502A FOR W 12 COLUMN STIFFNER ADDED PLATES. VISUAL INSPECTION REVEALS THE FOLLOWING: A) SUB-STANDARD WELDING AND WORKMANSHIP, B) NUMEROUS WELDS REJECTED FOR SLAG, UNDERCUT, UNDERFILL OF BEVELED PLATE PREPS, UNEQUAL FILLET LEG LENGTHS, POOR BASE METAL PREP PRIOR TO WELDING AND NOT COMPLYING WITH AWS D1.1 SEC 5.30 FINAL WELD CLEANING REQUIREMENTS. END ITEMS ##									
ADDITIONAL INFOR	ME MATION-SET ATTACH	ETHOD(S),PROCE	SS(ES),PR	NUMBER RX5R1 OCEDURE(S) MEI		ORTS [TIDEO M	DATE D Y
INSPECTOR M	ICHAEL DREV	V CWI # 9905021		ich I	7 1		.i.Ŧ.		14 08
SUPERVISOR			<u>-</u> [/1//						1