

INSPECTION REPORT

CUSTOMER: S.W. COLE ENG. PAGE 1 OF 1

ADDRESS: GRAY, ME.

ATTENTION: ROGER DOMINGO

COPIES:

PROJECT: MERCY AT FORE RIVER

OWNER: MERCY

CONTRACTOR: GILBANE

JOB No.: 06-1069.1 REPORT No.: QAL-07-1168 P.O. NUMBER: DATES INSPECTED: 06-26-07

REMARKS

REF. PREVIOUS FIELD REPORT DATED 06-15-07 FOR INCOMPLETE ITEMS. RE-INSPECTION SHOWS ALL ITEMS LISTED AS INCOMPLETE NOW COMPLETE AND ACCEPTABLE: IE:

- A) LEVEL (5) DIAGONAL WIND BRACE CONNECTION COMPLETE.
- B) LEVEL (4) KICKER BRACES AT LINE 45, E-F NOW COMPLETE.
- C) ROOF DECKING ATTACHMENTS COMPLETE. TO INCLUDE PENTHOUSES.
- D) LINTEL CONNECTIONS STILL IN-PROGRESS.
- E) CHAPEL AREA TO BE INSPECTED FROM MAN LIFT WHEN AVAILABLE.


COMPLETED ITEMS COMPLY WITH SITE DOCUMENTS AND AWS D1.1, D1.3 REQUIREMENTS FOR VISUAL ACCEPTANCE.

END ITEMS ///

FAA REPAIR STATION NUMBER RX5R187N
METHOD(S),PROCESS(ES),PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED: SKETCH(ES) SUPPLEMENTARY SHEET(S) NDT REPORTS VIDEO

SIGNATURES

INSPECTOR MICHAEL DREW CWI# 99050211 

SUPERVISOR

CERTIFICATION LEVEL	DATE		
	M	D	Y
	06	27	07