

6-13-01: Met Contractor @ site

110' Pin Found for reference to side
line. Permission Not granted
to place any concrete @ this time

6/15/01 Deck Reduced To 14', Owner
IDENTIFIED PROPERTY LINES. Ok To
Commerce Based On THEIR INFORMATION.
See EMAIL Dated 6/15/01 *All Comp* (16)

8/23/01 Final Deck inspection. Need intermediate
handrails. Inconsistent Rise on stairs ending with 2
granite steps - $7\frac{1}{2} \rightarrow 8\frac{1}{2} \rightarrow 7\frac{1}{4}$ JB

8/23/01 Spoke to contractors confe about issues - he will
call Monday JB

8/28/01 Reviewed for A commentary on Monumental Stairs.
w/s.t. The path of travel is indicated according to
door location. Therefore the handrails on either end suffice
as the path of travel. Harry Bennett will call regarding
granite steps. JB

9/5/01 The stairs built as per the plans on this permit are
in compliance with the code. The granite steps are (2)
installed per the owner/landscape contractor. JB