


Comments	Contact Info	Property Management	Inspection Outcome	Letters	Fees	CBL Inspections
----------	--------------	---------------------	--------------------	---------	------	-----------------

 <input type="button" value="Add Outcome"/>		<input type="button" value="New Inspection"/> <input type="button" value="Violation This Inspection"/> <input type="button" value="Violations All Inspections"/> <input type="button" value="Fire Violations Naviline"/> <input type="button" value="Inspection Check List"/>				
Score:	<input type="text" value="0"/>		Status:	<input type="text" value="Follow up Required"/>	Next Insp Due By	<input type="text" value="2/16/2018"/>
Notes:	Third floor living spaces lack compliant second means of egress/escape. Ionization smoke alarms in place in multiple locations. Multiple electrical violations noted including extension cords used as permanent wiring, open junction boxes, etc. Exterior wooden fire escape does not appear to meet code, should be evaluated. Follow up conversation with life safety plan reviewer needed..					
Created By:	<input type="text" value="msarapas"/>		Mod By:	<input type="text" value="msarapas"/>		
Create Date:	<input type="text" value="01/20/2018"/>	Mod Date:	<input type="text" value="01/20/2018"/>			
Record: <input type="button" value="1 of 1"/> <input type="button" value="No Filter"/> <input type="button" value="Search"/>						