CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

| Owner/Manager | | Inspector | Inspection Date |
|---------------------|-------------|--------------------|------------------------------|
| DONALDSON HERBERT L | | Suzanne Hunt | 10/30/2009 |
| Locatation | CBL | Status | Inspection Type |
| 169 GLENWOOD AVE | 131 K001001 | Re-Inspect 30 Days | Complaint-Housing Inspection |

| | Code | Int/Ext | Floor | Unit No. | Area | Compliance Date | | | |
|---|--|---|-------|----------|-------------|-------------------|--|--|--|
| 1) | 110.26 (b) | Interior | 2 | 2 | Various loc | Various locations | | | |
| | Violation: | NEC 2005/NFPA 70 | | | | | | | |
| | Notes: | all electric outlets must be covered and secure. Outlets include light fixtures, receptacles, dir switches. | | | | | | | |
| 2) | 110.26 (b) | Interior | 2 | 2 | | | | | |
| | Violation: | on: NEC 2005/NFPA 70 | | | | | | | |
| | Notes: | Smoke detector was not secure to wall. Hard wired /battery back up Smoke detector and Carbon Monoxide detectors required. | | | | | | | |
| 3) | 6-108.(a) | Exterior | 2 | 2 | Deck | | | | |
| Violation: Foundations cellars, exterior walls, roofs | | | | | | | | | |
| | Notes: | Railing on 2nd floor deck is not secure. Screen door to deck needs repair. | | | | | | | |
| 4) | 6-108.(f) | Interior | 1 | | Entry Way | | | | |
| | Violation: Required equipment and utilities | | | | | | | | |
| | Notes: | Notes: radiator in front hall entrance floor one is not secure to floor. | | | | | | | |
| | Commenter inspection conducted with tagent on 10/20/00 | | | | | | | | |

Comments: inspection conducted with tenant on 10/30/09