


11/24/15



— Existing 2nd Floor Framing

116 Gleckler Rd. Erin Van Horne Residence
Contractor: Paul Davis Restoration
Scale: $\frac{1}{4}'' = 1 \text{ ft.}$

FIVE STAR. ★★★★★

FIVE STAR. ★★★★★

FIVE STAR. ★★★★★

FIVE STAR. ★★★★★