


Field Report

The Park Danforth **Project No:** 13-059-00
Portland ME **Field Report No:** 21

To: Mark Donovan **Time of Visit:** 8:00 AM
 PC Construction **Date of Visit:** 10/18/2016
 131 Presumpscot Street **Weather:** Drizzle, Cool (55 Deg)
 Portland ME


Submitted by: Scott Timmons **Copies:**
Present: Andrew Pires PC Construction
 Kemp Carey PC Construction

Item	Description	Status:
21.1	<p>Apartment 1105</p> <ul style="list-style-type: none"> - Door swing is on wrong side of the w/d closet - Bathroom light fixture missing the "basket" over the light fixtures - The kitchen island Plam appears damaged. 	Correct Work
21.2	<p>Level 2 Trash Chutes</p> <p>The recycling door to the level 2 trash chute is incorrectly labeled "Rubbish"</p>	Correct Work
21.3	<p>Connector Canopy Expansion Joint (Courtyard Side)</p> <p>The expansion joint for the connector canopy is missing (Reference attached Photo) Construct in accordance with Sketches issued SI 009</p>	Observation
21.4	<p>Resident Apartment Windows</p> <p>Some windows appear to be missing the inside vertical stop. Reference attached photo</p>	Correct Work
21.5	<p>Water Infiltration Admin Suite</p> <p>Water appears to be working its way down to the Admin suite via the level 2 balconies above. Work in place shall be protected from water damage. Any areas exhibiting water damage shall be replaced (See attached photo)</p> <p>Spray fireproofing is missing on the underside of these level 2 balconies.</p>	Correct Work



Living room windows in Apartment 1209. Other apartments similar (Reference Item 21.4)

A




Ceiling in CEO 1009F. Other rooms below L2 balconies similar. Reference Item 21.5

B



Canopy Expansion Joint - Reference Item 21.3

A



Sketch SK-SI-9.2 from SI 009 Issued 3/15/2016

B