

FIELD OBSERVATION – Third FLOOR CEILING REPORT

07-22-2016

Report Date: 07/22/2016

Observation Date/Time: 07/22/2016 7:00AM to 8:30 PM

AEI Project Number and Name: 14018 – The Park Danforth

Report by: Susan Hathaway

Contractor: PC Construction

N:\Projects\2014\14018 – Park Danforth\40 Construction\Field Reports\2016-06-13 ELECTRICAL FIELD REPORT.doc

Observations:

1. Install pipe hangers within 12” of horizontal elbows.



2. Repair?



3. Provide fire caulking at sprinkler piping penetration.



4. Repair damaged supply duct insulation.



5. Complete exhaust duct installation.



6. Provide protection for showers during construction. Complete shower installation from floor above. (Some showers were covered, thank you!!)



7. Tape seam of supply duct insulation.




8. Verify fire caulking does not interfere with operation of volume damper.



9. Cover washing machine standpipe during construction, some were covered, some not.





10. Label piping throughout.

11. General Comment, Corridor: Complete pipe and duct routing and insulation.

If any information in this field observation report is incorrect or there are any questions, please let us know.

END OF FIELD OBERVATION