

FIELD OBSERVATION –REPORT

Report Date: 08/02/2016

Observation Date/Time: 08/02/2016 8:00AM to 9:30 PM

AEI Project Number and Name: 14018 – The Park Danforth

Report by: Ian MacDonald

Contractor: PC Construction

N:\Projects\2014\14018 - Park Danforth\40 Construction\Field Reports\2016-08-02 4th floor ceiling-wall mech FIELD REPORT.docx

Observations: 4th FLOOR Walk-through

1. Label piping throughout.
2. The Portland plumbing inspector has inspected the piping according to Titan.
3. General Comment, Corridor: Complete pipe and duct routing and insulation.



4. Complete piping, sample below:



5. Valve box drains still not protected. Coordinate installation of washer, dryer, and AC drains.



6. Fireproofing missing for fire pump exhaust.



7. When ceiling tiles are installed, make sure that shutoff valve locations are labeled in the ceiling grid with a labeling machine, 1/4" high black letters. This applies to fire dampers, control valves, valves, and any other item requiring service.



8. Fire proofing labeling is not consistent, many labels are missing.



If any information in this field observation report is incorrect or there are any questions, please let us know.

END OF FIELD OBERVATION