





**Photo # 1 – North elevation**



**Photo #2 – Southwest corner**



**Photo # 3 – West elevation**



**Photo #4 – Basement window near north end of west endwall**



**Photo # 5 – Basement window at middle of west endwall**



**Photo #6– Existing 1<sup>st</sup> floor joist bearing on foundation sill**