Portland, Maine



Yes. Life's good here.

August 17, 2015

MACWILLIAMS JAMES D

PO BOX 6807

PORTLAND, ME 04101

CBL: 181 F006001

Located at 91 COLUMBIA RD

NOTICE OF INTENT TO PROSECUTE

Dear Owner/Manager/Occupant,

An inspection of the property located at the address referenced above revealed that the structure and premises fail to comply with NFPA 2009 Fire Code and/or NFPA Life Safety Codes. Attached is a list of those violations.

The above-referenced property is in violation of the Chapter 10, Fire Prevention and Protection, Article 1 of the Portland City Code (the "Code") and National Fire Protection Association (NFPA) 101 Life Safety Code. Please note that the Code is available online at www.portlandmaine.gov.

This is a notice of intent to prosecute. As such, the matter is being referred to the City of Portland Corporation Council for legal action and possible civil penalties as provided for in Chapter 10, Fire Prevention and Protection, 10-25 of the Code and in Title 30- A.M.R.S.A. 4452.

Please be advised that you will need to contact the Fire Prevention Bureau at 207-874-8400 before the court date on the attached Reference to Court letter to either schedule a re-inspection or to submit a plan of action to correct these violations.

Sincerely,

Portland Fire Department

A/C With fautien

Fire Prevention Bureau

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager			Inspector Christopher Goodall			Inspection Date 8/14/2015			
MACWILLIAMS JAMES D					}				
Location		CBL		Status		Inspection Ty	•		
91 COLUMBIA RD		181 F006001)		Fire Company-FP Routine Inspec			
Code	In	t/Ext	Floor	Unit No.	Area		Compliance Date		
1) 9.002									
Violation:	door assembli tested in acco assembly and be permitted to provided without provides limitation openings permited to the state of the st	es that a rdance v the hou o be use out adve ations on nitted fo	are installed with the met rly rating (3 ed so that ac rsely affection the maximar each 100 s	in fire-rated thods described hours, 2 hous to the ng the fire reum size of a square feet of	floor-ceiling or reped in NFPA 288 urs, 1.5 hours, 1 space above the esistance rating on individual door of floor or ceiling.	REQ; Listings are pro pof-ceiling assemblies . The listing indicates hour, .75 hours) for w ceiling or to the floor f the entire assembly opening and the total	s that have been the fire-rated thich the door can above can be . The listing		
Notes:	DOOR REQU	IKED FI	KOM BASE	MENT TO C	OMMON REAR	STAIRS			
2) 2.125				4					
Violation:	N.F.P.A. 101 CHP. 31.3.3.2 HOLE IN CEILING NEEDS REPAIR; InteriorWall and Ceiling Finish Interior walls and ceiling finish materials complying with 10.2 shall be permitted as follows: 1) Exit encloures Class A or class B								
	2) Lobbies and	d corrido	orsClass A	or Class B					
	3) other space	es Class	s A, orClass	B, or Class	С				
Notes:	#93 REAR ST	AIRWE	LŁ						
3) 1.120									
Violation:	NFPA 101- 7.5.1.1 AND 7.5.1.1.1 OBSTRUCTED EGRESS; Exits shall be located and exit access shall be arranged so that exits are readily accesible at all times (7.5.1.1).								
	Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4 (7.5.1.1.1).								
Notes:	STORAGE OF	TITEMS	IN REAR S	STAIRWELL	OF #93				
4) 2.141									
Violation:	NFPA 101- 8.2.3 FIRE RATING NOT MAINTAINED; The fire resistance of structural elements and building assemblies shall be determined in accordance with test procedures set forth in NFPA 251, ASTM E 119, ANSI/ UL 263, or other approved test methods, or analytical methods approved by the authority having jurisdiction. Materials used to construct fire resistance-rated elements and assemblies shall be limited to those permitted in this code.								

ENTIRE REAR STAIRWELLS BOTH SIDES ARE WOOD BOARD PANELING, NO WALL COVERING

ABOVE BASEMENT STAIRS, OPEN STUD BAYS ABOVE BASEMENT STAIRS

Notes:

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date 8/14/2015	
MACWILLIAMS JAMES	D	Christopher Goodall		
Location	CBL	Status	Inspection Type	
91 COLUMBIA RD	181 F006001		Fire Company-FP Routine Inspec	

5) 55.05

Violation:

NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification

appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing

information to occupants or staff, shall comply with the requirements of Chapter 6.

Notes:

TENANT STATED APARTMENT DID NOT HAVE CO DETECTORS

Comments:

DISTRICT COURT Location: Portland Docket No.

CITY OF PORTLAND and body politic and Corporate, located in the County of Cumberland and State of Maine,

Plantiff,

FIRE PREVENTION AND PROTECTION CODE VIOLATION

(M.R. CIV. P. 80H AND 80k)

v.

James Macwilliams
Defendant

SUMMONS NUMBER:

354882

This matter has been referred to the Corporation Counsel's Office for immediate legal action with respect to the code violations detailed in the attached letter. It has been assigned the above summons number and will be filed with the Portland District Court and will be assigned for an initial appearance at the Portland District Court 205 Newbury Street Portland, Maine 04101 at 8:30 A.M. on 09/14/2015. I strongly urge you to contact Victoria Meserve at Fire Prevention at (207)-874-8400 or via e-mail at meserve@portlandmaine.gov to set up an inperson meeting to resolve these issues or make alternative arrangements to relieve you of the requirement to appear in Court on 09/14/2015.

Dated: 8/19/15

Adam R. Lee, Esq. Bar No. 4143 Associate Corporation Council City of Portland 389 Congress St Portland, ME 04101 207-874-8480