

## Permitting and Inspections Department Michael A. Russell, MS, Director

November 2, 2017

ENDICOTT CHRISTINE M 38 SHEFFIELD ST PORTLAND, ME 04102

CBL: 186 B009001

Located at: 85 FRANCES ST

Certified Mail 70141820000140495112

Dear ENDICOTT CHRISTINE M,

An evaluation of the above-referenced property on 11/02/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 12/07/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Kevin Hanscombe

Code Enforcement Officer

## CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager ENDICOTT CHRISTINE M		Inspector Kevin Hanscombe	Inspection Date
			11/2/2017
Location	CBL	Status	Inspection Type
85 FRANCES ST	186 B009001	Violations Exist	Housing Safety Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

1) 210

Violation:

ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes:

2nd floor bedrooms do have suitable secondary (emergency) escape. Plan of action to address

provided with in 30 days

2) 206

Violation:

SMOKE ALARMS / BEDROOMS; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: in all sleeping rooms.

NFPA 101 (2009) 24.3.4.1(1), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

one smoke alarm missing. 30 days to correct

3) 211

Violation:

OTHER

Notes:

one junction box missing cover. 30 days to coreect

Comments: