Legalization Inspection Form

| Date: _ | 11/6/2017 |
|-----------------------|---|
| Addre | ss:183 Whitney Avenue |
| Legal (| Jse:Two Family |
| Propos | sed Use: _Three Family |
| Comm | on Areas Exposure of ceiling on second floor landing hallway will need to be fixed. |
| Entry \ | way to apartments will need to be numbered on both interior and exterior doors. |
| Basem | rent |
| 0 | Fire Door: |
| 0 | Detection:_a hard wired photo electric combo smoke/carbon detector needs to be installed. |
| 0 | Sprinkler Head: |
| N (- x | All electrical boxes will need to have a cover, 2 were noted as missing during the inspection |
| Unit _: | 1 |
| | |
| 0 | Fire Door: Detection:_See below which applies to each unit |
| 0 | Egress: |
| wired | A hard wired photo electric smoke detector will need to be installed in each bedroom. A hard obtained electric combination smoke/carbon monoxide detector will need to be installed in each unit rea outside of the bedrooms. |
| Unit _: | 2 |
| 0 | Fire Door: Fire door will need to be adjusted to self-close. |
| 0 | Detection: See notes in Unit 1. |
| 0 | Egress: |
| Notes: | · |
| | ` |
| | |

| Unit | 3 |
|------|---|
| | |

- o Fire Door: Fire door will need to be adjusted to self-close.
- o Detection: See notes in Unit 1.
- o Egress: An egress window will need to be installed in the entry way of the rear means of egress. Additionally, the rear fire escape is most likely at the end of its life span and does not meet code. We are requiring that a design professional be consulted on the state and structural safety of the structure.

| Notes: | | |
|------------------|--------------------------|--|
| Unit_ | | |
| o | Fire Door: | |
| 0 | Detection: | |
| 0 | Egress: | |
| Notes: | | , |
| Overal Inspec | tor:_Chuck Fagone Wolf M | Follow up RequiredX |
| Fire Pr | evention: John Brennan | ************************************** |