COMMENTS

105/01- work has been angle tes & appears to meet LG1 ×15~ Glo

Inspection Record		
Туре		Date
Foundation:	_	
Framing:	_	
Plumbing:	_	
Final:	_	
Other:	_	